GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

Fax: 23412593, E-mail: <u>cfohq.dlfire@nic.in</u>, <u>Tel:-</u> 011-23414333

No. F.6/DFS/MS/GH/2015/ \$2 / 1678

Dated: 14 09/15

FIRE SAFETY CERTIFICATE

Certified that M/s. Bloom Rooms Hotels (A unit of Imperativ Hospitality Pvt. Ltd.) located at 7, Link Road, Jangpura, New Delhi comprised of basement, ground and two upper floors was granted Fire Safety Certificate by this department vide letter No. F6/DFS/MS/GH/2012/2717 dated 25.07.2012. The premises was re-inspected by the officer concerned of Delhi Fire Service on 24.08.2015 in presence of Mr. Ajay Chabra, manager of the guest house and observed that the management have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/premises is fit for occupancy class residential (Guest house) with effect from Ly for a period of 03 years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 1409115 at New Delhi by

(Dr. G.C. Misra) Chief Fire Officer

Copy to: -

- 1. The Manager, M/s. Bloom Rooms Hotels (A unit of Imperativ Hospitality Pvt. Ltd.), 7, Link Road, Jangpura, New Delhi.
- 2. The Joint C.P (Lic.), Police Station. Defence Colony. 1st floor, New Delhi.

Conditions for the validity of fire safety certificate

- a. All the fire safety and means of escape facilities shall be maintained in good working conditions at all time. Any lapse rendering fire safety or means of evacuation facilities rendering non-functional shall be the responsibility of the management.
- b. Building Sanctioning authority may verify any deviation with regard to the construction / occupancy in the building. In case of any deviation, the fire safety certificate stands null and void.
- c. The staffs shall be trained for operating fire fighting system and mock evacuation drills be conducted at regular intervals and record be maintained.
- d. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on website www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building: M/s. Bloom Rooms Hotels (A unit of Imperativ Hospitality

Pvt. Ltd.), 7, Link Road, Jangpura, New Delhi.

2. Type of Occupancy

: Lodging House

3. Type of Case

: Renewal

4. Details of previous NOC

: F6/DFS/MS/GH/2012/2717 dated 25.07.2012

5. Fire Safety directives letter No: Nil

6. Date of inspection

: 24.08.2015

7. Name of the Inspecting Officers: M.K.Chattopadhyay, ADO(M. Road)

8. Name and designation of officers

from the building side

: Mr. Ajay Chabra, Manager

9. Year of Construction

: 2007

10. Applicant's letter No.

: nil dated 04.07.2015

M/s. Bloom Rooms Hotels is comprised of basement, ground and two upper floors.

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	BBL Requirement	Provided at site	Remarks MR/NMR	
1	Access to building				
	Road width	06 mts	Provided	MR	
	Gate width	Required	03 mts provided	MR	
	 Width of internal road 	N/A	N/A	N/A	
2	Number, Width, Type & Arrangement of Exits				
	a. Number of staircases	-	-	-	
	• Upper Floors	02	02	MR	
	• Basements	02	02	MR	
	b. Width of staircases	-	-	-	
	• Upper Floors	0.90 mts	1.44 mts, 1.06 mt	MR being old case	
	• Basements	0.90 mts	0.95 mts, 0.65 mts	MR being old case	
	c. Protection of exits	_	-	-	
	Fire check door	N/A	N/A	N/A	
	 Pressurization 	N/A	N/A	N/A	
To the second se	e. No. of continuous staircases to terrace	01	01	MR	
	g. Width of Corridor	1.0 mt	Provided	MR	
	h. Door Size	1.0 mt	Provided	MR	
3	Compartmentation.				
	Fire check door	N/A	N/A	N/A	

		1	I	The state of		
	Sealing of electrical shafts	Required	Provided	MR		
	Fire Rating of shaft door	N/A	N/A	N/A		
	Water Curtain	N/A	N/A	N/A		
	Fire Dampers	N/A	N/A	N/A		
4	Smoke Management System.					
	Basements	30 a/c per hour	Exhaust Fan Provided	MR		
	• Upper floors	12 a/c per hour	N/A	N/A		
5	Fire Extinguishers					
	Total numbers	25 Nos.	Provided	MR		
	• Types	ABC, CO_2	Provided	MR		
	IS marking	ISI marked	Provided	MR		
6	First-Aid Hose Reels.					
	Total numbers on each floor	01	Provided	MR		
	• Length of hose reel hose	30 m	Provided	MR		
	Nozzle diameter	5 mm	Provided	MR		
7	Automatic fire detection and alarming system.					
	Type of detectors	N/A	Provided(battery			
			operated)			
	Location of Main Panel	N/A	N/A	N/A		
	Location of Repeater Panel	N/A	N/A	N/A		
	Alternate source of power	N/A	N/A	N/A		
	Hooters' Location			1N/ A		
		N/A	N/A	N/A		
8	MOEFA	Required	Provided	MR		
9	Public Address System.	Required	Provided	MR		
10	Automatic Sprinkler System.					
	 Basement 	Required	Provided	MR		
	• Upper Floor	N/A	N/A	N/A		
	Sprinkler above false ceiling	N/A	N/A	N/A		
11	Internal Hydrants					
	Size of riser/down-comer	100 mm	Provided	MR		
	• Number of hydrants per floor	01 No.	Provided	MR		
2	• Hose Box	01 No.	Provided	MR		

(

1	Yard Hydrants.				
	Total number of hydrants	N/A	N/A	N/A	
	• Hose Box	N/A	N/A	N/A	
3	Pumping Arrangements.				
	Ground Level				
	Discharge of main Pump	N/A	N/A	N/A	
	Head of Main pump	N/A	N/A	N/A	
	Number of main pumps	N/A	N/A	N/A	
	> Jockey Pump out put	N/A	N/A	N/A	
	> Jockey pump head	N/A	N/A	N/A	
	Standby Pump out put	N/A	N/A	N/A	
	Standby Pump Head	N/A	N/A	N/A	
	Auto Starting/ Manual stopping	N/A	N/A	N/A	
	Pump House Access	N/A	N/A	N/A	
	Terrace level				
	Discharge of pump	900 LPM	Provided	MR	
	> Head of the pump	35 mts	Provided	MR	
	Power Supply	Required	Provided	MR	
	Auto Starting of pump	Required	Provided	MR	
14	Captive Water Storage for fire fighting.				
	Underground tank capacity	N/A	N/A	N/A	
	Draw-off connection	N/A	N/A	N/A	
	Fire service inlet	N/A	N/A	N/A	
	Access to tank	N/A	N/A	N/A	
	Overhead Tank capacity	15,000 lts	Provided	MR	
15	Exit Signage.	Required	Provided	MR	
16	Provision of Lifts.				
	Pressurization of Lift Shaft	N/A	N/A	N/A	
	Pressurization of Lift lobby	N/A	N/A	N/A	
	Communication In lift Car	Required	Provided	MR	
	Fireman's Grounding Switch	Required	Provided	MR	

	Lift Signage	Required	Provided	MR	
17	Standby power supply	Required	Provided	MR	
18	Refuge Area.				
	> Total Area	N/A	N/A	N/A	
***************************************	> Location	N/A	N/A	N/A	
19	Fire Control Room				
	Detector System Panel	N/A	N/A	N/A	
	• Flow Switch Panel	N/A	N/A	N/A	
	PA System Panel	N/A	N/A	N/A	
	Batter backup	N/A	N/A	N/A	
T 2000.000	Building Floor Plans	N/A	N/A	N/A	
20	Special Fire Protection Systems for Protection of special Risks, if any:	Required	02 ABC type fire extinguisher found provided near elect. panel	MR	

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the NOC issued vide letter No. F6/DFS/MS/GH/2012/2717 dated 25.07.2012, renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

DFA is put up for approval & signature please.

DO(SX) - Letowe
DCFO(SX) OF OILS

Signature of the Inspecting Officer Name M.K.CHATTOPADHYAY Designation: - Asstt. Div. Officer (M.Rd)