GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/64/2015/ ND2/1722

Dated: 18/09/15

FIRE SAFETY CERTIFICATE

Certified that the Silver Shine Guest House located at 1323-1328, Sangtrashan Chowk, Pahar Ganj, New Delhi comprised of Ground + 05 Upper floors, Ground floor (02 guest room + reception + office), 1st floor to 3rd floor (11 guest rooms at each floor), 4th floor (07 staff rooms/store rooms) and 5th floor (sealed with bricks), total 35 guest rooms (includes 75 was granted FSC beds) by this department No.F6/DFS/MS/GH/2012/3368 dated 14/09/12. The premises was re-inspected by the officer concerned of this department on 03/08/15 in the presence of Sh. Virender (Manager) and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 as above 35 guest rooms (include 75 beds) only with effect from ----- for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued ----- 18 9-1-5-- at New Delhi by.

(Dr. G.C.Misra) Chief Fire Officer Ph-011-23414333

Copy to:-

- of c M 1. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi Ref. letter No. 850-54/Joint C.P./Lic.(H) dated 08/07/2015.
- 2. Sh. Virender (Manger), Silver Shine Guest House, 1323-1328, Sangtrashan Chowk, Pahar Ganj, New Delhi Condition for the validity of fire safety certificate
 - 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
 - 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
 - 3. The trained fire fighting staff should be available round the clock.
 - 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
 - 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
 - 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
 - 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

INSPECT	IKON	DEDC	DT
INSPECT	UN	KEP	IVI

1. Name & address of the building:-

Silver Shine Guest House located at 1323-1328, Sangtrashan Chowk, Pahar

Ganj, New Delhi

2. Type of occupancy:-

Residential, Sub Division-A-1

Gr. + 05 Upper floors (total 35 Guest rooms &

75 beds)

3. Type of case:-

4. Details of previous FSC:-

Renewal No. F6/DFS/MS/GH/2012/3368 dated

14/09/12.

5. Fire safety directives No.-

N/A 03/08/15

6. Date of inspection:-

Sh. Manoj Kumar Sharma (ADO/CC)

7. Name of the inspecting officer:-8. Name & designation of officer

From the building side:-

Sh. Virender (Manger)

9. Year of construction:-10. Applicant's letter No:-

No. 850-54/Joint C.P./Lic.(H)

dated 23/06/2015.

10.		dated 23/06/2015.		Old Case	
	G I I an Ema	Requirement	Provided at site	Remarks	
S.No.	William Startage	Existing	PSS	MR/NMR	
	Prevention and me salety	LXISHIIB			
	U/R 33				
1.	Access to Building	N/A	06 mtr.	MR	
	1) Road width	N/A	N/A	N/A	
	2) Gate width		N/A	N/A	
	3)Width of internal road	N/A		2 17 2 2	
2.	Number, Width Type & Arra	angement of E	XILS		
	A. Number of staircases		01 Nos.	MR	
	1. Upper floors	01 Nos.	N/A	N/A	
	2. Basements	N/A	IN/A		
	B. Width of staircase	0.00	1.25 mtr.	MR	
	1. Upper floors	0.80 mtr.	1.23 1110.		
		N/A	N/A	N/A	
	2. Basements	14/71			
	C. Protection of exits	N/A	N/A	N/A	
	1. Fire check door	N/A	N/A	N/A	
	2. Pressurization	01	01	MR	
	D. No. of continuous	O1			
	staircase to terrace	N/A	N/A	N/A	
	E. Width of corridor	1 mtr.	1 mtr.	MR	
	F. Door size	1 11111.			
3.	Compartmentation	N/A	N/A	N/A	
	1) Fire check door		N/A	N/A	
	2) Sealing of electrical shafts	N/A N/A	N/A	N/A	
	3) Fire rating of shaft door	N/A N/A	N/A	N/A	
	4) Water curtain	N/A	N/A	N/A	
	5) Fire Dampers		1 11 2	200	
4.	Smoke Management System	30 ACPH	N/A	N/A	
	1) Basements	JU ACI II	2.07.2	•	

	100

	2) Upper floors	12 a/c per hour	Natural Ventilation	MR
5.	Fire Extinguishers			
	1) Total numbers	12 Nos.	12 Nos.	MR
	2) Types	ABC & CO2	ABC & CO2	MR
	3) ISI marking	Required	Provided	MR
6.	First-Aid Hose Reel			
	1) Total number of eachfloor	01	01	MR
	2) Length of hose reel hose	30 m	30 m	MR
	3) Nozzle diameter	05 mm	05 mm	MR
7.	Automatic Fire Detection &	Alarming Syste		
F .	1) Type of detectors	N/A	N/A	N/A
	2) Location of main panel	N/A	N/A	N/A
	3) Location of repeater panel	N/A	N/A	N/A
	4) Alternate source of power	N/A	N/A	N/A
	5) Hooter's Location	N/A	N/A	N/A
8.	MOEFA	Required	Provided	MR
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System	1		
	1) Basement	N/A	N/A	N/A
	2) Upper floors	N/A	N/A	N/A
	3) Sprinkler above false	N/A	N/A	N/A
	ceiling			
11.	Internal Hydrants			
	1) Size of riser/down-comer	N/A	N/A	N/A
	2) Number of hydrants per	N/A	N/A	N/A
	floor	2		
	3) Hose box	N/A	N/A	N/A
12.	Yard Hydrants			
	1) Total number of hydrants	N/A	N/A	N/A
	2) Hose box	N/A	N/A	N/A
3.	Pumping Arrangement			
	1) Ground level	N/A	N/A	N/A
	a) Discharge of main	N/A	N/A	N/A
	pump			
	b) Head of main pump	N/A	N/A	N/A
	c) Number of main pump	N/A	N/A	N/A
	d) Jockey pump out put	N/A	N/A	N/A
	e) Jockey pump head	N/A	N/A	N/A
	f) Stand by pump output	N/A	N/A	N/A
	1) Starta by partip output	T 11 T T		
	g) Stand by pump head	N/A	N/A	N/A
				N/A N/A
	g) Stand by pump head h) Auto starting/Manual	N/A	N/A	
	g) Stand by pump head	N/A	N/A	
	g) Stand by pump head h) Auto starting/Manual stopping 2) Terrace level	N/A N/A	N/A N/A	N/A
	g) Stand by pump head h) Auto starting/Manual stopping 2) Terrace level a) Discharge of pump	N/A	N/A N/A 225 LPM	N/A MR
	g) Stand by pump head h) Auto starting/Manual stopping 2) Terrace level a) Discharge of pump	N/A N/A	N/A N/A	N/A

14.	Captive Water Storage for	Fire Fighting		
The second	1) Under ground tank capacity	N/A	N/A	N/A
	a) Draw-off connection	N/A	N/A	N/A
	b) Fire service inlet	N/A	N/A	N/A
	c) Access to tank	N/A	N/A	N/A
	d) Over head tank capacity	2500 ltr.	2500 ltr.	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.		V .	17111
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	Required	Provided	MR
	d) Fireman's switch	Required	Provided	MR
	e) Lift signage	Required	Provided	MR
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection Syste Risk, if any:	m for Protection	on of special	NA

The fire protection systems provided in the guest house building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/2012/3368 dated 14/09/2012 renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended.

Signature of the Inspecting Officer

Name: - M.K. Sharma Designation: - ADO (CC)

Da cento