

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE**  
**NEW DELHI- 110 001**

No. F6/DFS/MS/Hospital/2015/1402/1752

Dated: 29/09/15

**FIRE SAFETY CERTIFICATE**

Certified that the Amar Jyoti Charitable Trust, Vikas, Marg, Karkardooma,, Delhi-92, comprised of one basement ground plus three upper floors was granted NOC by this department vide letter No. F6/DFS/MS/2005/2396/Hospital Dated 23.11.2005. The Hospital was re-inspected by the officer concerned of this department on 18.09.2015 in the presence of Shri Kamal Pandey, and found that the hospital have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rule, 2010 and found that the building is fit for occupancy class C -1 "Hospital (Institutional Building)" with effect from 29/09/15 renewed for a period of **three** years, in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010, subject to conditions printed overleaf.

Issued on..... 29/09/15 ..... at New Delhi by



(Dr. G.C. Misra)

Chief Fire Officer

Ph -011- 23414333

C/o Sks

To,

Dr. Uma Tuli,

Amar Jyoti Charitable Trust, Vikas, Marg, Karkardooma, , Delhi-92,

## CONDITIONS:

1. All the means of escape shall be kept free of all the type of obstruction all the time.
2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
4. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
5. This Fire Safety Certificate can not be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on [www.dfs.delhigovt.nic.in](http://www.dfs.delhigovt.nic.in)
7. Basement shall be used as per BBL.
8. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.

### INSPECTION REPORT

1. Name & address of the building : Amar Jyoti Charitable Trust, Karkardooma, Vikas Marg, Delhi-92
2. Building is comprised of : B+G+3
3. Type of Occupancy : Institutional Building
4. Type of Case : Renewal
5. Details of Previous NOC : F6/DFS/MS/2005/2396/Hospital Dated 23.11.2005
6. Fire Safety direction letter No : F6/MS/DFS/BP/Hospital/2003/2041 dated 03.09.2003
7. Date of Inspection : 18.09.2015
8. Name of the Inspecting Officers: : Suresh Singh (ADO)
9. Name of the designation of Officer from the building side : Shri Kamal Pandey
10. Year of Construction : 2003
11. Applicant's letter No : Dated 02.09.2015

S.No	Minimum Standards on fire prevention and fire safety U/R33	Requirement /NBC	Provided at Site	Remarks MR/NMR
1	Access to building			
	Road width	6 m	20 m	MR
	Gate width	4.5 m	5 m	MR
	Width of internal road	N.A.	N.A.	N.A.
2	Number, Width, Type and Arrangement of Exits			
	a. Number of Staircases			
	Upper Floor	1 no	1 no +01 ramp	MR
	Basement	1 no + 1 ramp	1 no + 1 ramp	MR
	B. Width of Staircases			
	Upper Floor	2 m	1.1 m (2 m Ramp)	MR †
	Basement	1.1 m	1.1 m	MR
	c. Protection of exits			
	Fire check door	Required	Provided	MR
	Pressurization	N.A.	N.A.	N.A.
	e. No. of continuous staircases to terrace	1 no.	1 no.	MR
	g. Width of Corridor	2 m	2 m	MR
h. Door Size	1 m	1m, 2m	MR	
3	Compartmentation.			
	Fire check door	Required	Provided	MR
	Sealing of electrical shafts	Required	Provided	MR
	Fire rating of shaft door	Required	Provided	MR
	Water curtain	N.A.	N.A.	N.A.
	Fire Dampers	N.A.	N.A.	N.A.
4	Smoke Management System.			
	Basement	NA	Ventilated	MR
	Upper floor	NA	Ventilated	MR

† Previous noc was given on 1.1 meter wide Stair Case.

5.	Fire Extinguisher			
	Total numbers	35 no.	35 no.	MR
	types	Co2 & ABC	Co2 & ABC	MR
	ISI marking	ISI marked	ISI marked	MR
6	First-aid-Hose Reels.			
	Total numbers of each floor	01 no.	01 no.	MR
	Length of hose reel hose	30 m	30 m	MR
	Nozzle diameter	5 mm	5 mm	MR
7	Automatic fire detection and alarming system.			
	Type of detectors	NA	NA	NA
	Location of main panel	NA	NA	NA
	Location of repeater panel	NA	NA	NA
	Alternate source of power	NA	NA	NA
	Hooters's location	NA	NA	NA
8	MOEFA	Required	Provided	MR
9	Public address System.	NA	NA	NA
10	Automatic Sprinkler System.			
	basement	Required	Provided	MR
	upper floor	N.A.	N.A.	N.A.
	sprinkler above false ceiling	N.A.	N.A.	N.A.
11	Internal Hydrants			
	size of riser/down-comer	100 mm	100 mm	MR
	Number of hydrants per floor	1 no.	1 no.	MR
	Hose Box per floor	1 no.	1 no.	MR
12	Yard Hydrants.			
	Total number of hydrants	N.A.	NA	NA
	Hose Box	N.A.	NA	NA
13	Pumping Arrangements.			
	<ul style="list-style-type: none"> <li>• Ground Level</li> <li>➤ Discharge of main Pump</li> <li>➤ Head of Main Pump</li> <li>➤ Number of main pumps</li> <li>➤ Jockey pump out put</li> <li>➤ Jockey pump head</li> <li>➤ Standby pump out put</li> <li>➤ Standby pump Head</li> <li>➤ Auto Starting /Manual stopping</li> <li>➤ Pump House Access</li> <li>• Terrace Level</li> <li>➤ Discharge of pump</li> <li>➤ Head of the Pump</li> <li>➤ Power supply</li> <li>➤ Auto Starting of pump</li> </ul>			
		1620 LPM	1620 LPM	MR
		60 m	60 m	MR
		01 no.	01 no	MR
		180 LPM	180LPM	MR
		60 m	60 m	MR
		1620 LPM	1620 LPM	MR
		60 m	60 m	MR
		Required	Provided	MR
		Required	Provided	MR
		N.A.	N.A.	N.A.
		N.A.	N.A.	N.A.
		N.A.	N.A.	N.A.
		N.A.	N.A.	N.A.
		N.A.	N.A.	N.A.

14	Captive Water Storage for Fire Fighting.			
	Underground tank capacity	50,000 Liters	50,000 Liters	MR
	Draw-off connection	Required	Provided	MR
	Fire service inlet	Required	Provided	MR
	Access to tank	Yes	Provided	MR
	Overhead Tank capacity	30,000 Liters	30,000 Liters	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			
	Pressurization of Lift Shaft	NA	NA	NA
	Pressurization of Lift lobby	N.A.	N.A.	N.A.
	Communication in lift car	NA	NA	NA
	Firemen's grounding switch	NA	NA	NA
	Lift Signage	NA	NA	NA
17	Standby power supply	NA	Provided	MR
18	Refuge Area.			
	Total area	N.A.	N.A.	N.A.
	Location	N.A.	N.A.	N.A.
19	Fire Control Room			
	Detector system panel	N.A.	N.A.	N.A.
	Flow switch panel	N.A.	N.A.	N.A.
	PA system panel	N.A.	N.A.	N.A.
	Batter backup	N.A.	N.A.	N.A.
	Building Floor Plans	N.A.	N.A.	N.A.
20	Special Fire Protection systems for protection of special Risks, if any:			

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the Rules the NOC issued letter no. F6/DFS/MS/2005/2396/Hospital Dated 23.11.2005 renewal under Rule 35 of the Delhi Fire Service Rules 2010 is recommended.

*Suresh Singh*  
21.9.15

Signature of the Inspecting Officer

Name Suresh Singh

Designation ADO (Shah)

DO (EAST)

*Submitted for approval please.*

*Vingh*