## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F 6/DFS/MS/2015/school/w2/1786

Dated: 07 /10 /2015

## FIRE SAFETY CERTIFICATE

Certified that the M.C.D Pratibha School located at C-block, Mangol Puri, Delhi-83 comprised of Ground and first floor was granted FSC by this department vide letter No F 6 / DFS / MS / 2011/797 dated 22.02.2013. The premises was re-inspected by the officer concerned of this department on 10.09.2015 in the presence of Sh. B.L.Sharma, Principal and observed that all the fire prevention and fire safety arrangements as provided in the premises found in good working condition. The premises have deemed complied with requirements of circular issued by Director of Education letter no 3298-3398 dated 01.03.2011 and verified by the officer concerned of Fire Service and the building/ premise is fit for occupancy Group B Educational with effect from ...67. / 1.0./. (.5...... for a period of three years, subject to compliance of the conditions mentioned below:

## Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.

The trained fire fighting staff should be available round the clock.

4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.

This certificate cannot be treated in any case for regularizations of unauthorized construction.

- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
- The owner / occupier shall submit a declaration every year in form "K" provided in the schedule of Delhi Fire Service Rules 2010. The form is available on <u>WWW.dfs.Delhigovt.nic.in</u>

Issued on ...... at New Delhi

Chief Fire Officer Ph:-011-23414250 Offelle

Copy to: -

1. 2. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi - 54.

3. The Principal, MCD Pratibha School, C Block, Mangol Puri, Delhi – 110083.

## **INSPECTION REPORT**

Name & address of the building:

M.C.D Pratibha School, "C" Block Mangol Puri, Delhi

Type of Occupancy 2.

:Educational

3. Type of Case

:Renewal

4. Details of previous NOC

:F.6/DFS/MS/2011/797 dated 22/02/2013

Fire Safety directives letter No

: Director of Education Circular dated 01.03.2011

Date of inspection

: 10/09/2015

Name of the Inspecting Officers

: ADO (RN)

8. Name and designation of officers

from the building side

: B.L.Sharma, Principal

9. Year of Construction

: 1978

10. Applicant's letter No.

:NPV/2015/45 dated 20/07/2015

Plot Area-5433 sqm

Covered Area: 1711 sq.m,

class rooms -18 No. of Student 581

-	Minimum Standards on fire prevention and fire safety U/R 33	Circular of Director of Education	Provided at site	Remarks MR/NMI	
1	Access to building				
	Road width	6m	6m	MR	
	Gate width	Accessible	3.6m	MR	
	Width of internal road	Accessible	Open Ground	MR	-
	Number, Width, Type & Arrangement of Exits				
	a. Number of staircases				
	• Upper Floors	02	02	MR	
	Basements	NA	NA NA	NA	
	b. Width of staircases				
	• Upper Floors	1.50m	2m & 1.36m	MR	
	Basements	NA	NA	NA	
	STATE STATES OF THE STATES OF		я		
	c. Protection of exits	NA	NA	NA	
	Fire check door				
	Pressurization	NA	NA	NA	
	d. No. of continuous staircases to terrace	NA	01	NA	
	e. Width of Corridor	R	2.1m	MR	
	f. Door Size		10,000 1000	IVIIX	
		1 m	1.05 m	MR	

	Fire check door	NA	NA	NA	
	Sealing of electrical shafts	NA	NA	NA	
	• Fire Rating of shaft door	NA	NA	NA	
	• Water Curtain	NA	NA	NA	
	• Fire Dampers	NA	NA	NA	
4	Smoka Managamant Saut			IVA	
	Smoke Management System.				
	• Basements	NA	NA	NA	
	Upper floors	NA	NA	NA	
5	Fire Extinguishers			NA	
	Total numbers	06 nos	10 nos 🗸	MR	
	• Types	ABC/Co2	ABC—10	MR	
	ISI marking	ISI Marked	Yes	MR -	
6	First-Aid Hose Reels.			-	
	Total numbers on each floor	NA	NA	NA	
	• □ ngth of hose reel hose	NA	NA	NA	
	Nozzle diameter	NA	NA	NA	
7	Automatic fire detection and alarming system.				
	Type of detectors	NA	NA	NA	
	Location of Main Panel	NA	NA	NA	
	Location of Repeater Panel	NA	NA	NA	
	Alternate source of power	NA	NA	NA	
	Hooters' Location	NA	NA	NA	
3	MOEFA	NA	NA	NA	
)	Public Address System.	NA	NA	NA	
		TVA .	INA	NA	
10	Automatic Sprinkler System.				
	Basement	NA	NA	NA	
	Upper Floor	NA	NA	NA	
	Sprinkler above false ceiling	NA	NA	NA	
1	Internal Hydrants				
	Size of riser/down-comer	NA	NA	NA	
	Size of restrict with control	- 111	1,77	14/1	

1 1 -

	Number of hydrants per floor	NA	NA	NA		
	Hose Box	NA	NA	NA		
2	Yard Hydrants.					
	Total number of hydrants	NA	NA	NA		
	Hose Box	NA	NA	NA		
13	Pumping Arrangements.					
	Ground Level					
	➤ Discharge of main Pump	N/A	N/A	N/A		
	Head of Main pump	N/A	N/A	N/A		
	Number of main pumps	N/A	N/A			
	> Jockey Pump out put			N/A		
	> Jockey pump head	N/A	N/A	N/A		
	➤ Standby Pump out put	N/A	N/A	N/A		
	Standby Pump Head	N/A	N/A	N/A		
	<ul><li>Auto Starting/ Manual stopping</li><li>Pump House Access</li></ul>	N/A	N/A	N/A		
	Terrace level	N/A	N/A	N/A		
	Discharge of pump					
	Head of the pump	NA	N/A	NA		
	<ul><li>Power Supply</li><li>Auto Starting of pump</li></ul>	NA	N/A	NA		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
4	Captive Water Storage for fire fighting.					
	Underground tank capacity	NA	NA	NA		
	> Draw-off connection	NA	NA	NA		
	➤ Fire service inlet	NA	NA	NA		
	> Access to tank	NA	NA	NA		
	Overhead Tank capacity	NA	N/A	NA		
15	Exit Signage.	N/A	P	N/A		
16	Provision of Lifts.					
	Pressurization of Lift Shaft	N/A	N/A	N/A		
	Pressurization of Lift lobby	N/A	N/A	N/A		

	Communication In lift Car	N/A	N/A	N/A
• Firen	Fireman's Grounding Switch	N/A	21/4	
	• Lift Signage	IN/A	N/A	N/A
		N/A	N/A	N/A
7	Standby power supply	N/A	N/A	N/A
18	Refuge Area.			
	> Total Area	N/A	N/A	N/A
	Location	N/A	N/A	N/A
19	Fire Control Room			
	Detector System Panel	N/A	N/A	N/A
	Flow Switch Panel	N/A	N/A	N/A
	<ul><li>PA System Panel</li><li>Batter backup</li></ul>	N/A	N/A	N/A
	Building Floor Plans	N/A	N/A	N/A
	· ·	N/A	N/A	N/A
0	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested/ checked randomly and found in working condition at the time of inspection.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in director of education Circular dated 01.03.2011, it is recommended to renewal of fire safety certificate issued vide this department letter of even no. 1809 dated 18.05.2012.

DO/NOSO 216/9/15

Signature of the Inspecting Officer
Name: - Rajesh Kumar
Designation: - ADO/RN