

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE

NEW DELHI- 110 001


No. FC/DFS/MS/School/2015/S2/1893

Dated: 21/10/15

PART FIRE SAFETY CERTIFICATE EXCEPT AUDITORIUM

Certified that Veer Chander Singh Garhwali Govt. Sarvodaya Bal Vidyalaya, J-Block, Saket, New Delhi-110017, comprised of ground plus two upper floors (one block) and ground plus one upper floor (one block) except auditorium, owned/occupied by Directorate of Education, Govt. of NCT of Delhi have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules,2010 and verified by the officer concerned of this department on dated 08.10.15 in the presence of Mr. A.S.Bharangar, Principal of the school and found that the school building (Only two blocks except auditorium) is fit for occupancy class B 'Educational Building' with effect from 21/10/2015 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of Delhi Fire Service Rules,2010.

Issued on.....21/10/2015 at New Delhi by



(Dr.G.C.Misra)

Chief Fire Officer

T.No.011-23414333

olch

To,

1. The Principal, Veer Chander Singh Garhwali Govt. Sarvodaya Bal Vidyalaya, J-Block, Saket, N.D-17,
2. The Director of Education, Old Secretariat, Civil Lines, Delhi-52.
3. Executive Engineer, PWD EMD.M-453,MSO Building, 11th floor, New Delhi-02.

Conditions for the validity of fire safety certificate are as under :-

1. All the means of escape shall be kept free of all type of obstruction all the time.
2. The employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
3. All fire fighting equipments shall be maintained in perfect working condition all time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.
5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.
7. The owner/occupier shall apply for renewal of this Fire Safety Certificate in form J, six month prior to its expiry.

2. Building is comprised of : J-Block, Saket, New Delhi-110017.
 : G+2(one block), G+1(one block) and Ground floor only(Auditorium).
 FSC only for G+2 &G+1(one block). Total two blocks except Audi.
3. Type of Occupancy : Education
4. Type of Case : New.
5. Details of Previous NOC : Nil.
6. Fire Safety direction letter No : Nil
7. Date of Inspection : 08.10.15.
8. Name of the Inspecting Officers: : Vedpal (ADO)
9. Name and designation of Officer from the building side : Sh. A.S.Bharangar (Principal).
10. Year of Construction : 1976.
11. Applicant's letter No : DB(2-A)/PWDES DM-453/2015-16/1886, dated 11.09.15.

S.No	Minimum Standards on fire prevention and fire safety as per Rules.	Requirement	Provided at Site	Remarks MR/NMR
1	Access to building			
	Road width	6 m	9 m	MR
	Gate width	N.A.	N.A.	N.A.
	Width of internal road	N.A.	N.A.	N.A.
2	Number, Width, Type and Arrangement of Exits.			
	a. Number of Staircases			
	Upper Floor	2nos.in G+2, 2nos.in G+1 block.	2nos.in G+2, 2nos.in G+1 block.	MR
	Basement	N.A.	N.A.	N.A.
	B. Width of Staircases			
	Upper Floor	1.5 m (each)	1.25m(each) in G+2, 1.40m(each) in G+1block.	MR
	Basement	N.A.	N.A.	N.A.
	c. Protection of exits			
	Fire check door	N.A.	N.A.	N.A.
	Pressurization	N.A.	N.A.	N.A.
	e. No. of continuous staircases to terrace	N.A.	N.A.	N.A.
	g. Width of Corridor			
	h. Door Size	1.5 m	1.5 m	MR
		1 m	1m	MR
3	Compartmentation			
	Fire check door	N.A.	N.A.	N.A.
	Sealing of electrical shafts	N.A.	N.A.	N.A.
	Fire rating of shaft door	N.A.	N.A.	N.A.
	Water curtain	N.A.	N.A.	N.A.
	Fire Dampers	N.A.	N.A.	N.A.
4	Smoke Management System.			
	Basement	30a/c per hour	N.A.	N.A.
	Upper floor	12 a/c per hour	N.A.	N.A.

4

M/S

Veer Chander Singh Garhwali Govt. Sarvodaya Bal Vidyalaya, J-Block, Saket, New Delhi-110017.

14	Captive Water Storage for Fire Fighting.			
	Underground tank capacity	N.A.	N.A.	N.A.
	Draw-off connection	N.A.	N.A.	N.A.
	Fire service inlet	N.A.	N.A.	N.A.
	Access to tank	N.A.	N.A.	N.A.
	Overhead Tank capacity	15000 liters	15000liters	MR.
15	Exit Signage.	Required	Provided	MR.
16	Provision of Lifts.			
	Pressurization of Lift Shaft	N.A.	N.A.	N.A.
	Pressurization of Lift lobby	N.A.	N.A.	N.A.
	Communication in lift car	N.A.	N.A.	N.A.
	Firemen's grounding switch	N.A.	N.A.	N.A.
	Lift Signage	N.A.	N.A.	N.A.
17	Standby power supply in auditorium	Required	Not Provided	NMR
18	Refuge Area.			
	Total area	N.A.	N.A.	N.A.
	Location	N.A.	N.A.	N.A.
19	Fire Control Room			
	Detector system panel	N.A.	N.A.	N.A.
	Flow switch panel	N.A.	N.A.	N.A.
	PA system panel	N.A.	N.A.	N.A.
	Batter backup	N.A.	N.A.	N.A.
	Building Floor Plans	N.A.	N.A.	N.A.
20	Special Fire Protection systems for protection of special Risks, if any:	N.A.	N.A.	N.A.

Keeping in view the substantial non compliance of the minimum standards on fire prevention and fire safety required under rules, it is recommended to issue shortcomings as noted at serial numbers 2,5,6,8,10,11,&17. Reply letter on same lines is put up for kind consideration please


Signature of the Inspecting Officer

Name Vedpal

Designation ADO