GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110 001

No. F6/DFS/ms/2015/52/1962

Dated: 3/11/15

FIRE SAFETY CERTIFICATE

Certified that the M/S Hotel City Center Inn Guest House building at 751, Main Mathura Road, Jungpura, New Delhi-110014, comprised of basement (storage only), ground floor (reception+1hall), 1st floor (07 Rooms), 2rd floor (07 Rooms) & 3rd floor (1G Room+2 Staff Rooms), total 15 guest rooms, was granted FSC by this department vide letter No. F6/MS/DFS/GH/2012/4178, dated 07-11-2012. The premises was re-inspected by the officer concerned of this department on 17-10-2015 in the presence of Sh. Persanna (Manager) and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential (Guest House 15 guest rooms only) with effect from 2015 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

(Dr.G.C.Misra)

Chief Fire Officer

T.No.011-23414333

Copy to:- 1. Joint Commissioner of Police, Licensing Branch, 1st floor, P.S. Defence Colony, O/L. New Delhi.

- 2. M/S Hotel City Center Inn at 751, Main Mathura Road, Jungpura, New Delhi-110014.

 Conditions for the validity of fire safety certificate are under:-
- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.
- 5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate on form J, six month prior to its expiry.

3		5
- 1		

1	Name & address of the building	M/S Hotel City Cente	r Inn Guest House buildin	g at 751,	
2	Type of Occupancy	Main Mathura Road, Jungpura, New Delhi-110014.			
3	Type of Occupancy Building Comprised of	Residential & Lodging House "A"			
3	Danding Comprised Of	Basement=Storage, GF=Reception +1Hall, 1st			
		Floor=7Rooms, 2nd Floor=7 rooms & 3rd Floor=1Rooms& 2staff rooms. Total=15 Guest Rooms.			
4	Type of case	Renewal			
5	Details of previous NOC	No.F6/MS/DFS/GH/20	12/4178, Dated 07.11.20	12.	
6	Fire safety directives letter No	Nil.			
7	Date of inspection	17.10.2015			
8	Name of the inspecting Officers	: ADO(S.J.) Vedpal			
9	Name and designation of officers				
	from the building side	- Mr.Persanna, Manage	r		
	The same state of the same sta	orodinia, wanage	1.		
10	Year of construction	2007			
	2. 2. 2				
11	Applicant's letter No.	2038/ Joint. C.P/Lic(H)			
S. NO.	Minimum Standards on fire	NBC/ BBL 1983	Provided at site	Remarks	
	prevention and fire safety U/R	Requirement		MR / NMF	
1	Access to building				
•	1) Road width	Accessible	15m Provided	MR	
	2) Gate width	N/A	N/A	N/A	
	3) Width of internal road	N/A	N/A	N/A	
2	Number, width Type & arrangem		1	113/11	
	a. Number of staircases			8	
	1. Upper floors	01no.	01no. Provided	MR	
	2. basements	Two	Two Provided	MR	
	b. Width of staircase				
	1. Upper floors	1.25 Mtr	1.14m (old case)	MR	
	2. basements	1.25 Mtr	1.14 & 1.9 Mtr Provided		
	c. Protection of exits				
	1. Fire check door	N/A	N/A	N/A	
	2. Pressurization	N/A	N/A	N/A	
	d. No. of continuous staircase to terrace	Requied	1 No. Stairs Provided	MR	
	to terrace e. Width of corridor	N/A	N/A	N/A	
	f. Door size	1 Mtr	Provided	MR	
3	Compartmentation.		. Tovidou	IVIIX	
	1. Fire check door	N/A	N/A	N/A	
	2. Sealing of electrical shafts	Required	Provided	MR	
	3. Fire Rating of shaft door	N/A	N/A	N/A	
	4. water curtain	N/A	N/A	N/A	
	5. Fire dampers	N/A	N/A	N/A	
4	Smoke Management system.	20 a/a nan hair			
	Basement	30 a/c per hour 12 a/c per hour	Exhaust fans provided	MR	
	Upper floors	12 are per flour	Natural Ventilation	MR	
5	Fire Extinguishers		Inatural Ventilation	INIIX	
	Total numbers		08 Nos	MR	
			ABC, Co2,	MR	
	Types		IABC. COZ	IIVIC	



ut	9
	'

6	First-Aid Hose Reels.				
	Total numbers on each floor	One	01no. Provided in part of 750.(Both G/H connected at each floo level)	MR (old case)	
	Length of Hose reel hose	30 m	Provided	MR	
	Nozzle Diameter	5 mm	Provided	MR	
7	Automatic fire detection and a	arming system	1. 1011000	INITY	
	Type of detectors	N/A	N/A	N/A	
	Location of Main Panel	N/A	N/A		
	Location of Repeater panel	N/A	N/A	N/A N/A	
	Alternate source of power	Required	Battary Backup	MR	
	hooter's location	N/A	N/A	N/A	
8	MOEFA	Required	Provided	MR	
9	Public Address System.	Required	Provided	MR	
10	Automatic Sprinkler System.			1011	
	Basement	Required	Provided	MR	
	Upper floors	N/A	N/A	N/A	
	Sprinkler above false ceiling	N/A	N/A	N/A	
11	Internal Hydrants		[IVI	TIN/A	
	Size of riser/down-corner	N/A	N/A	N/A	
	Number of Hydrants per floor	N/A	N/A	N/A	
40	hose Box	N/A	N/A	N/A	
12	Yard Hydrants.				
	total number of hydrants	N/A	N/A	N/A	
40	hose box	N/A	N/A	N/A	
13	Pumping arrangements	Fire fighting s	ystem common for both G/H at	750 & 751.	
	1. Ground level	1 V V2			
	a. Discharge of main Pump	N/A	N/A	N/A	
	b.Head of main pump	N/A	N/A	N/A	
	c.Number of main pumps	N/A	N/A	N/A	
	d.jockey pump out put	N/A	N/A	N/A	
	e.jockey pump head	N/N	N/A	N/A	
	f. Standby Pump output	N/A	N/A	N/A	
	g.Stanby Pump head	N/A	N/A	N/A	
	h.Auto Starting/Manual stopping	N/A	N/A	N/A	
	pump house access 2.Terrace level	N/A	N/A	N/A	
	a. Discharge of pump	900LPM	900+180LPM	MR	
	b. head of the pump	40m	40m	MR	
	c. Power supply	Required	Provided	MR	
	d. Auto starting of pump	Required	Provided	MR	
14	Captive water storage for fire fighting	Fire fighting system common for both G/H at 750 & 751.			
	1. Underground tank capacity	N/A	N/A	N/A	
	a. Draw-off connection	N/A	N/A	N/A	
	b. fire service inlet	N/A	N/A	N/A	
	c.Access to tank	N/A	N/A	N/A	
	Over head tank Capacity	10,000 ltr	10,000 ltrs. Provided	MR	
15	Exit Signage.	Required	Provided	MR	
16	Provision of lifts.				
	a. Pressurization of lift shaft	N/A	N/A	N/A	
	b. pressurization of lift lobby	N/A	N/A	N/A	
	c. communication in lift car	N/A	N/A	N/A	
	d. Fireman's grounding switch	N/A		N/A	
	e. Lift signage	N/A	N/A		

ok

H110

17	Standby power supply	Required	Provided	MR
18	Refuge Area.		Not Required	
	total area			
	location			
19	Fire control room			
	a. Detector system Panel	N/A	N/A	N/A
	b. Flow switch Panel	N/A	N/A	N/A
	c. PA system Panel	N/A	N/A	N/A
	d. Batter backup	Required	Provided	MR
	e. Building floor plans	N/A	N/A	N/A
20	Special Fire Protection syste	ems for protection of	special risks, if any:	

The fire protection systems provided in the building were test checked randomly and found functional at the time of inspection. In view of the deemed compliance of the minimum standards on fire prevention and fire safety required under the rules the FSC issued vide letter No.F.6/DFS/MS/GH/2012/4178, dated 07.11.12 renewal under rule 35 of the Delhi Fire Service Rule 2010 is recommended.

Accordingly DFA is put up for your approval and signature please.

Signature of the inspecting officer

Name Vedpal

Designation : Assistant Divisional Officer (\$

cer (\$.