

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI-110001.

E-mail:- cfohq.dlfire@nic.in

No. F.6/DFS/MS/EH/2015/ 52/2016

Fax: - 011-23412593

Dated: 09/11/15

FIRE SAFETY CERTIFICATE

Certified that the building of **Burger King India Pvt. Ltd.**, Unit no-GF-05, Orchard Road, Janakpuri West Metro Station, New Delhi-110058, is comprised of two basements, ground plus eight upper floors and terrace floor. But restaurant is running at ground floor only. The above restaurant owned/ occupied by Burger King India Pvt. Ltd. The Restaurant building was inspected by the officer concerned of this department on 02.11.2015 in the presence of Sh. Anil (Supervisor) and found that the owner have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises (**Restaurant Only**) is fit for occupancy class Group "D" Assembly building w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed overleaf.

Issued on 09/11/15 at New Delhi.



(DR. G.C. MISRA)
CHIEF FIRE OFFICER
DELHI FIRE SERVICE

o/c

Copy to:-

1. The Manager,
Burger King India Pvt. Ltd., Unit no-GF-05, Orchard Road,
Janakpuri West Metro Station, New Delhi-110058.

Following fire safety directives must be adhered to:-

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
3. The trained staff should be available round the clock.
4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
6. Basement shall be used as per the building bye laws.
7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

N/1

Building is comprised of two basements, ground plus eight upper floors and terrace but restaurant is at ground floor.
(Burger King Unit no-GF-05, Orchard Road, Janakpuri West Metro Station, New Delhi-110058)

INSPECTION REPORT

1. Name & address of the building: Burger King India Pvt. Ltd., Unit no-GF-05, Orchard Road, Janakpuri West Metro Station, New Delhi-110058.
2. Type of Occupancy : Group D (Assembly)
3. Type of Case : New
4. Details of Previous NOC : N/A (F.6/DFS/MS/2015/SZ/1900 dated 23.10.2015)for whole bldg.
5. Fire Safety directives letter No : N/A (F.6/DFS/MS/BP/2014/207 dated 28.07.2014) for whole bldg.
6. Date of inspection : 02.11.2015
7. Name of Inspecting Officer : A.D.O. Sandeep Duggal
8. Name and designation of officers
From the building side : Sh. Anil (Supervisor)
9. Year of Construction : 2015
10. Applicant's letter No. : Nil dated 26.10.2015

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	NBC/ BBL Requirement	Provided at site	Remarks MR/NMR
1.	Access to building			
	<ul style="list-style-type: none"> • Road width • Gate width • Width of internal road 	09 mtrs 06 mtrs 06 mtrs	14 mtrs 06 mtrs 06 mtrs	M/R M/R M/R
2.	Number, Width, Type & Arrangement of Exits			(Restaurant is at GF only)
	a. Number of staircases			
	<ul style="list-style-type: none"> • Upper Floors • Basements 	03 No.'s 03 No.'s	03 No.'s 03 No.'s	M/R M/R
	b. Width of staircases			
	<ul style="list-style-type: none"> • Upper Floor • Basements 	1.5 mtrs 1.5 mtrs	1.5 mtrs 1.5 mtrs	M/R M/R
	c. Protection of exits			
	<ul style="list-style-type: none"> • Fire check door • Pressurization 	Required Required	Provided Provided	M/R M/R
	d. No. of continuous staircases to terrace	01 No.	03 No.'s	M/R
	e. Width of Corridor	1.5 mtrs	Opening in hall	M/R
	f. Door Size	02 mtrs	02 mtrs	M/R
3.	Compartmentation			(Restaurant is at GF only)
	<ul style="list-style-type: none"> • Fire check door • Sealing of electrical shafts • Fire Rating of shaft door • Water Curtain • Fire Dampers 	Required Required N/A N/A Required	Provided Sealed N/A Provided Provided	M/R M/R N/A N/A M/R
4.	Smoke Management System			(Restaurant is at GF only)
	<ul style="list-style-type: none"> • Basements 	30 Air change PH	Provided	M/R

San

Building is comprised of two basements, ground plus eight upper floors and terrace but restaurant is at ground floor.
(Burger King Unit no-GF-05, Orchard Road, Janakpuri West Metro Station, New Delhi-110058)

	<ul style="list-style-type: none"> Upper floors 	12 Air change PH	Natural Ventilation	M/R
5.	Fire Extinguishers			
	<ul style="list-style-type: none"> Total numbers Types IS marking 	05 No.'s ABC/CO2 ISI marked	09 no.'s Provided Co2, Water Co2 ISI marked	M/R M/R M/R
6.	First-Aid Hose Reels (common with Parking cum Commercial Building)			
	<ul style="list-style-type: none"> Total numbers on ground floor Length of hose reel hose Nozzle diameter 	One 30 mtrs 5 mm	Provided Provided Provided	M/R M/R M/R
7.	Automatic fire detection and alarming system			
	<ul style="list-style-type: none"> Type of detectors Location of Main Panel Location of Repeater Panel Alternate source of power Hooters' Location 	N/A N/A N/A N/A N/A	Smoke/heat/gas detectors Provided Provided at GF N/A Provided Provided Near exit	Sens N/A N/A N/A N/A N/A
8.	MOEFA	Required	Provided	M/R
9.	Public Address System	Required	Provided	M/R
10.	Automatic Sprinkler System (Restaurant is at GF only)			
	<ul style="list-style-type: none"> Basement Ground Floor Sprinkler above false ceiling 	N/A N/A N/A	Provided Provided Provided	N/A N/A N/A
11.	Internal Hydrants (common with Parking cum Commercial Building)			
	<ul style="list-style-type: none"> Size of riser/down-comer Number of hydrants Hose Box 	150 mm 01 No. 01 No.	Provided Provided Provided	M/R M/R M/R
12.	Yard Hydrants			
	<ul style="list-style-type: none"> Total number of hydrants Hose Box 	N/A N/A	07 No.'s Provided 07 No.'s Provided	N/A N/A
13.	Pumping Arrangements (common with Parking cum Commercial Building)			
	<ul style="list-style-type: none"> Ground Level <ul style="list-style-type: none"> Discharge of main Pump Head of Main pump Number of main pumps Jockey Pump out put Jockey pump head Standby Pump out put Standby Pump Head Water Curtain Pump Auto Starting/Manual Stopping 	N/A N/A N/A N/A N/A N/A N/A N/A N/A N/A	2850 LPM 90 mtrs 02 No.'s 280 LPM 90 mtrs 2850 LPM 90 mtrs 1000 LPM Provided	N/A N/A N/A N/A N/A N/A N/A N/A N/A

2/3

Building is comprised of two basements, ground plus eight upper floors and terrace but restaurant is at ground floor.
(Burger King Unit no-GF-05, Orchard Road, Janakpuri West Metro Station, New Delhi-110058)

	<ul style="list-style-type: none"> ➤ Pump House Access • Terrace level ➤ Discharge of pump ➤ Head of the pump ➤ Power Supply ➤ Auto Starting of pump 	N/A	Provided	N/A
		450 LPM	900 LPM	M/R
		40 mtrs	40 mtrs	M/R
		Required	Provided	M/R
		Required	Provided	M/R
14.	Captive Water Storage for fire fighting	(common with Parking cum Commercial Building)		
	<ul style="list-style-type: none"> • Underground tank capacity ➤ Draw-off connection ➤ Fire service inlet ➤ Access to tank • Overhead Tank capacity 	N/A	200000 Ltrs	N/A
		N/A	Provided	N/A
		N/A	Provided	N/A
		N/A	Provided	N/A
		10000	20000 ltrs	M/R
15.	Exit Signage.	Required	Provided	M/R
16.	Provision of Lifts.	(Restaurant is at GF only)		
	<ul style="list-style-type: none"> • Pressurization of Lift Shaft • Pressurization of Lift lobby • Communication In lift Car • Fireman's Grounding Switch • Lift Signage 	Required	Provided	M/R
		Required	Provided	M/R
		Required	Provided	M/R
		Required	Provided	M/R
		Required	Provided	M/R
17.	Standby power supply	Required	DG set 500 KVA X 2	M/R
18.	Refuge Area.			
	<ul style="list-style-type: none"> ➤ Total Area ➤ Location 	N/A	N/A	N/A
		N/A	N/A	N/A
19.	Fire Control Room			
	<ul style="list-style-type: none"> • Detector System Panel • Flow Switch Panel • PA System Panel • Battery backup • Building Floor Plans 	N/A	Provided	N/A
		N/A	Provided	N/A
		N/A	Provided	N/A
		N/A	Provided	N/A
		N/A	Provided	N/A
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	Provided	N/A

20
San

2/14

Building is comprised of two basements, ground plus eight upper floors and terrace but restaurant is at ground floor.
(Burger King Unit no-GF-05, Orchard Road, Janakpuri West Metro Station, New Delhi-110058)

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety measures required under the rules, it is recommended to grant Fire Safety Certificate under Rule 35 of the Delhi Fire Service Rules 2010.

Note: - The restaurant is in the Multi Level Car parking cum Commercial Area, Janak Puri West Metro Station, New Delhi and have common fire safety installations. The Multi Level Car parking cum commercial area was issued Fire Safety Certificate vide letter No. F6/DFS/MS/2015/SZ/1900 dated 23.10.2015, placed at C-1.

Sandeep
02/11/15

Signature of Inspecting Officer

Name:- Sandeep Duggal

Designation:- Asstt. Divisional Officer

~~Signature of Inspecting Officer~~

~~Name:-~~

~~Designation:-~~



D.O. (South West)

KT Grewal
31/11/15