GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110 001

No. F6/DFS/MS/ GH/2015752/2057

Dated: 16/11/15

FIRE SAFETY CERTIFICATE

(Dr.G.C.Misra) Chief Fire Officer

T.No.011-23414333

Copy to:- 1. Joint Commissioner of Police, Licensing Branch, 1st floor, P.S. Defence Colony, de L. New Delhi.

2. M/S K.W. International Guest House located at G-18, NDSE, Part-I, New Delhi.

Conditions for the validity of fire safety certificate are under:-

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.
- 5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate on form J, six

N/28

		11/20	DT		
		INSPECTION REPO	ORI	LO 40 NIDOE	
1	Name & address of the building		Guest House located a	I G-18, NDSE,	
		Part-I, New Delhi.			
2	Type of Occupancy	Residential & Lodging House "A"			
3	Building Comprised of	GF=Two Shops, 1st flo	or=Reception +8Rooms	s, 2nd	
J	Danial 19 Comprises of	floor=02Rooms. Total=25 Guest Rooms. Guest House is			
		running at 1st & 2nd floor only.			
4	Type of case	Renewal	CH/2608 Dated 19.07.20	n12	
5	Details of previous NOC	No.F6/DFS/MS/2012/GH/2608, Dated 19.07.2012.			
6	Fire safety directives letter No	Nil.			
7	Date of inspection	04.10.2015			
. 8	Name of the inspecting Officers :	: ADO(S.J.) Vedpal			
0	Name and designation of officers				
9		Mar Ideala and Ideana and Or	· ·		
	from the building side	Mr.Kuldeep Kumar, Ov	wner.		
40	Vary of construction	1972			
10	Year of construction	1972	1		
11	Applicant's letter No.	No. Nil, Dated 16.10.2	015.		
S. NO.	Minimum Standards on fire	Old NOC	Provided at site	Remarks	
J. 140.	prevention and fire safety U/R	Requirement		MR / NMR	
	33	rtoquironi			
1	Access to building				
	1) Road width	Accessible	9m Provided	MR	
	2) Gate width	N/A	N/A	N/A	
	3) Width of internal road	N/A	N/A	N/A	
2	Number, width Type & arrangem		TAIT	11477	
	a. Number of staircases	- III OI EXILS		T	
		0.4	O4 Descripted	MD	
	1. Upper floors	01no.	01no. Provided	MR	
	2. basements	N/A	N/A	N/A	
	b. Width of staircase		1		
	1. Upper floors	1.25 Mtr old Core	1. 0 5m	MR(old case)	
	2. basements	N/A	N/A	N/A	
	c. Protection of exits			1 1//	
	1. Fire check door	N/A	N/A	N/A	
		N/A	N/A	N/A	
	2. Pressurization	D. 100 State 10	1 No. Provided	MR	
	d. No. of continuous staircase	Requied	1 No. Provided	IVIT	
	to terrace	N.1/A	11/4	NI/A	
	e. Width of corridor	N/A	N/A	N/A	
	f. Door size	1 Mtr	1Mtr.	MR	
3	Compartmentation.	N//A	1.1/4	1,177	
	1. Fire check door	N/A	N/A	N/A	
	2. Sealing of electrical shafts	Required	Provided	MR	
		IN LIA	15.17.6	I K I I K	
	3. Fire Rating of shaft door	N/A	N/A	N/A	
		N/A	N/A	N/A	
	3. Fire Rating of shaft door				
4	3. Fire Rating of shaft door4. water curtain	N/A N/A	N/A N/A	N/A	
4	3. Fire Rating of shaft door4. water curtain5. Fire dampers	N/A N/A 30 a/c per hour	N/A	N/A	
4	3. Fire Rating of shaft door4. water curtain5. Fire dampersSmoke Management system.	N/A N/A	N/A N/A	N/A N/A	
4 5	3. Fire Rating of shaft door 4. water curtain 5. Fire dampers Smoke Management system. Basement Upper floors	N/A N/A 30 a/c per hour	N/A N/A	N/A N/A	
	3. Fire Rating of shaft door 4. water curtain 5. Fire dampers Smoke Management system. Basement Upper floors Fire Extinguishers	N/A N/A 30 a/c per hour	N/A N/A N/A Natural Ventilation	N/A N/A N/A MR	
	3. Fire Rating of shaft door 4. water curtain 5. Fire dampers Smoke Management system. Basement Upper floors Fire Extinguishers Total numbers	N/A N/A 30 a/c per hour	N/A N/A N/A Natural Ventilation 05 Nos	N/A N/A N/A MR	
	3. Fire Rating of shaft door 4. water curtain 5. Fire dampers Smoke Management system. Basement Upper floors Fire Extinguishers Total numbers Types	N/A N/A 30 a/c per hour 12 a/c per hour	N/A N/A N/A Natural Ventilation 05 Nos ABC, Co2,	N/A N/A N/A MR MR	
5	3. Fire Rating of shaft door 4. water curtain 5. Fire dampers Smoke Management system. Basement Upper floors Fire Extinguishers Total numbers Types ISI marking	N/A N/A 30 a/c per hour	N/A N/A N/A Natural Ventilation 05 Nos	N/A N/A N/A MR	
	3. Fire Rating of shaft door 4. water curtain 5. Fire dampers Smoke Management system. Basement Upper floors Fire Extinguishers Total numbers Types ISI marking First-Aid Hose Reels.	N/A N/A 30 a/c per hour 12 a/c per hour	N/A N/A N/A Natural Ventilation 05 Nos ABC, Co2, Yes	N/A N/A N/A MR MR MR MR	
5	3. Fire Rating of shaft door 4. water curtain 5. Fire dampers Smoke Management system. Basement Upper floors Fire Extinguishers Total numbers Types ISI marking	N/A N/A 30 a/c per hour 12 a/c per hour	N/A N/A N/A Natural Ventilation 05 Nos ABC, Co2,	N/A N/A N/A MR MR MR	
5	3. Fire Rating of shaft door 4. water curtain 5. Fire dampers Smoke Management system. Basement Upper floors Fire Extinguishers Total numbers Types ISI marking First-Aid Hose Reels.	N/A N/A 30 a/c per hour 12 a/c per hour	N/A N/A N/A Natural Ventilation 05 Nos ABC, Co2, Yes	N/A N/A N/A MR MR MR MR	

6	Fire safety directives letter No	Nil.				
7	Date of inspection	04.10.2015				
8	Name of the inspecting Officers :	ADO(S.J.) Vedpal				
0	Name and designation of officers			4		
9	Name and designation of officers	M. K. I.I. and K. and C.	A			
	from the building side	Mr.Kuldeep Kumar, Owner.				
10	Year of construction	1972				
44	Applicant's letter No	No. Nij. Dotod 46 40 2015				
11 S. NO.	Applicant's letter No. Minimum Standards on fire	No. Nil, Dated 16.10.20	Provided at site	Remarks		
3. NO.	prevention and fire safety U/R	Requirement	1 Tovided at Site	MR / NMR		
	33	Requirement				
1	Access to building					
	1) Road width	Accessible	9m Provided	MR		
	2) Gate width	N/A	N/A	N/A		
	3) Width of internal road	N/A	N/A	N/A		
2	Number, width Type & arrangeme	ent of exits				
	a. Number of staircases					
,	1. Upper floors	01no.	01no. Provided	MR		
	2. basements	N/A	N/A	N/A		
	b. Width of staircase					
	1. Upper floors	1.25 Mtr old Cost	1. 0 5m	MR(old case)		
	2. basements	N/A	N/A	N/A		
t.	c. Protection of exits			1077		
	1. Fire check door	N/A	N/A	N/A		
	2. Pressurization	N/A	N/A	N/A		
	d. No. of continuous staircase	Requied	1 No. Provided	MR		
	to terrace		# 07-35 GR-16 W 141-000 SECRETARIO 201	3 (5000)		
31	e. Width of corridor	N/A	N/A	N/A		
	f. Door size	1 Mtr	1Mtr.	MR		
3	Compartmentation.					
	1. Fire check door	N/A	N/A	N/A		
	2. Sealing of electrical shafts	Required	Provided	MR		
	3. Fire Rating of shaft door	N/A	N/A	N/A		
	4. water curtain	N/A	N/A	N/A		
	5. Fire dampers	N/A	N/A	N/A		
4	Smoke Management system.		Tour.	Taxxx		
	Basement	30 a/c per hour	N/A	N/A		
-	Upper floors	12 a/c per hour	Natural Ventilation	MR		
5	Fire Extinguishers		05 N	1.45		
	Total numbers		05 Nos	MR		
	Types ISI marking	l ISI	ABC, Co2, Yes	MR		
6	First-Aid Hose Reels.	101	res	MR		
U	Total numbers In guest house	One	01no. Provided	MR		
	Length of Hose reel hose	30 m	Provided	MR		
-	Nozzle Diameter	5 mm	Provided	MR		
7	Automatic fire detection and alar		I			
	Type of detectors	N/A	N/A	N/A		
	Location of Main Panel	N/A	N/A	N/A		
	Location of Repeater panel	N/A	N/A	N/A		
	Alternate source of power	N/A	N/A	N/A		
	hooter's location	N/A	N/A	N/A		
Renewal		IZ \A/ Intonoction	al Guest House located at G-			

		N/29		
8	MOEFA	N/A	N/A	N/A
9	Public Address System.	Required	Provided	MR
10	Automatic Sprinkler System.		. rovided	IVIIX
	Basement	N/A	N/A	N/A
	Upper floors	N/A	N/A	
	Sprinkler above false ceiling	N/A	N/A	N/A
11	Internal Hydrants	TW/ X	IN/A	N/A
	Size of riser/down-corner	N/A	N/A	INIZA
	Number of Hydrants per floor	N/A		N/A
	hose Box	N/A	N/A N/A	N/A
12	Yard Hydrants.	IN/A	IN/A	N/A
	total number of hydrants	N/A	N/A	[N. 1.4
	hose box	N/A		N/A
13	Pumping arrangements	IN/A	N/A	N/A
	1. Ground level			
	a. Discharge of main Pump	N/A	NI/A	
	b.Head of main pump	N/A	N/A	N/A
	c Number of main pumps	N/A	N/A	N/A
	d.jockey pump out put	N/A	N/A	N/A
	e.jockey pump head	N/N	N/A	N/A
	f. Standby Pump output	N/A	N/A	N/A
	g.Stanby Pump head		N/A	N/A
	h.Auto Starting/Manual stopping	N/A	N/A	N/A
	pump house access	N/A	N/A	N/A
	2.Terrace level	N/A	N/A	N/A
	a. Discharge of pump	450LDM	1,,	
	b. head of the pump	450LPM	450LPM	MR
	c. Power supply	35m	35m	MR
	d. Auto starting of pump	Required	Provided	MR
14	Captive water storage for fire	N/A	N/A	N/A
	fighting			
	1. Underground tank capacity	N/A	N/A	N/A
	a. Draw-off connection	N/A	N/A	N/A
	b. fire service inlet	N/A	N/A	N/A
	c.Access to tank	N/A	N/A	N/A
	Over head tank Capacity	2500 Itr	2500 Itrs. Provided	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of lifts.		riovided	IVII
	a. Pressurization of lift shaft	N/A	N/A	N/A
	b. pressurization of lift lobby	N/A	N/A	N/A
	c. communication in lift car	N/A	N/A	N/A
	d. Fireman's grounding switch	N/A	N/A	N/A N/A
	e. Lift signage	N/A	N/A	N/A
17	Standby power supply	Required	Provided	MR
18	Refuge Area.	1	Not Required	IIVIIX
	total area		rtot rtequired	
	location			
19	Fire control room			
13				
13		N/A	N/A	NI/A
13	a. Detector system Panel	N/A N/A	N/A	N/A
13	a. Detector system Panel b. Flow switch Panel	N/A	N/A	N/A
13	a. Detector system Panel			

20 Special Fire Protection systems for protection of special risks, if any:

The fire protection systems provided in the building were test checked randomly and found functional at the time of inspection. In view of the deemed compliance of the minimum standards on fire prevention and fire safety required under the rules the FSC issued vide letter No.F.6/DFS/MS/GH/2012/2608, dated 19.07.12 renewal under rule 35 of the Delhi Fire Service Rule 2010 is recommended.

Accordingly DFA is put up for your approval and signature please.

Signature of the inspecting officer

Name Vedpal

Designation : Assistant Divisional Officer (S.

D. O. South)

19/11/15