## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No. F6/DFS/MS/EH/2015/ND2/2065

Dated 18/11/15

## FIRE SAFETY CERTIFICATE

(**Dr. G.C. Misra**) Chief Fire Officer Ph – 011-23414333

ole

Copy to:-

1. The Medical Officer of Health, Health Department, New Delhi Municipal Council Palika Kendra, New Delhi.

2. Mr. Amit (Manager) Sagar Ratna Restaurant located at K-15, Cannaught Circus, New Delhi

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all time. The owner / occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

4. Any deviation w.r.t construction etc. shall be verified by the concerned building sanctioning authority.

5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six months prior to its expiry"

 $\wedge$ 

## **INSPECTION REPORT**

1. Name & address of the building : Sagar Ratna Restaurant located at K-15, Connaught Place

New Delhi.

2. Type of Occupancy

: Assembly Building (Ground + Mezzanine + 2 floor)

(Restaurant is running at Ground + Mezzanine floor)

3. Type of Case

: Renewal

4. Details of previous FSC

: F.6/DFS/MS/GH/2012/955 dated 16/03/12

5. Fire Safety directives Letter No.

: NA

6 Date of inspection

: 06/11/2015

7 Name of the Inspecting Officer

: Sh. G.S. Chauhan (DO/CD) & Sh. M.K. Sharma (ADO CC)

8 Name and designation of Officer

from the building side

: Mr. Amit (Manager)

9 Year of Construction

: Old Heritage

10. Applicant's letter No.

: No. Nil dated 26/10/2015.

S No	Minimum standards on fire prevention	Exiting	Provided at site	Remarks		
	and fire safety U/R 33	Requirement		MR/NMR		
1.	Access of building					
	Road width	06 Mtr.	09 Mtr.	MR		
	Gate width	NA	NA	NA		
	Width of internal road	NA	NA	NA		
2.	Number, width, Type & Arrangements of exits					
	a. Number of staircases		- 1			
	• Upper floors	02	02	MR		
	Basements	NA	NA	NA		
	b.Width of staircases					
	• Upper floors	0.86 mtr. & 1.02 mtr.	0.86 mtr. & 1.02 mtr.	MR		
	•	Exiting				
	Basements	NA	NA	NA		

	cProtection of exits			
	Fire check door	NA	NA	NA
	Pressurization	NA	NA	NA
	d. No of continuous staircase to terrace	01	01	MR
	e. Width Of Corridor	NA	NA	NA
J	f. Door Size	1.20 mtrs. Exiting	1.20 mtrs.	MR
3.	Compartmentation			
	Fire check door	NA	NA	NA
	<ul> <li>Sealing of electrical shafts</li> </ul>	NA	NA	NA
	<ul> <li>Fire Rating of shaft door</li> </ul>	NA	NA	NA
	Water Curtain	NA	NA	NA
	Fire Dampers	NA	NA	NA
4	Smoke managements System	<u></u>		
	Basements	NA	NA	NA
	• Upper floors	12 ACPH	NATURAL	MR
5	Fire Extinguishers			
	Total numbers	06	08	MR
	• Types	ABC, CO <sub>2</sub> , Wco <sub>2</sub>	ABC, CO <sub>2</sub> , Wco <sub>2</sub>	MR
	IS marking	YES	Provided	MR
5	First – Aid Hose Reels			
	Total numbers on each floor	01	01	MR
	• Length of hose reel hose	30 mt	30 mt	MR
	Nozzle diameter	05 mm	05 mm	MR
7	Automatic fire detection and alarming sys			
	Type of detectors	NA	NA	NA
	Location of Main Panel	NA	NA	NA
	Location of Repeater Panel	NA	NA	NA
	Alternate source of power	NA	NA	NA
	Hooters' Location	NA	NA	NA
	MOEFA	Required	Provided	MR
	Public Address System	NA	NA	NA
0	Automatic Sprinkler			

15	Exit Signage	Required	Provided	MR	
16	Provision of Lifts	NA	NA	NA	
	Pressurization of Lift Shaft	NA	NA	NA	
	<ul> <li>Pressurization of lift lobby</li> </ul>	NA	NA	NA	
	<ul> <li>Communication in lift Car</li> </ul>	NA	NA	NA	
	Fireman's Grounding Switch	NA	NA	NA	
	• Lift Signage	NA	NA	NA	
17	Standby power supply	Required	Provided	MR	
18	Refuge Area				
	Total area	NA	NA	NA	
	• Location	NA	NA	NA	
19	Fire control room				
	Detector system panel	NA	NA	NA	
	Flow Switch Panel	NA	NA	NA	
	PA System Panel	NA	NA	NA	
	Batter backup	NA	NA	NA	
	Building Floor Plans	NA	NA	NA	
20	Special Fire Protection Systems for Protection of special Risks, if any;	YES	ABC, Co <sub>2</sub>	MR	

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

Shortcomings communicated vide letter no. F6/DFS/ MS/EH/2012/955 dated 16/03/12 have been rectified.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter no. F6/DFS/MS/EH/2012/955 dated 16/03/2012 renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended.

Signature of the Inspecting Officer

Name:- M.K. Sharma Designation:- ADO (CC)