GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110 001

NO. F6/0F5/M5/2015/52/2126

Dated: 2/12/15

FIRE SAFETY CERTIFICATE

Certified that M/S United Free Church located at Plot No.6, Kishan Garh, Near Pocket "A", Sector "A" Vasant Kunj, New Delhi-110070, comprised of ground plus one upper floor owned/occupied by The Diocesan Society-Church of North India have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules,2010 and verified by the officer concerned of this department on dated 03.11.15 in the presence of Sh. Barket Masih, Member of Church and that the building is fit for occupancy class "Assembly" Church with effect from ... 2.1.1.5... for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of Delhi Fire Service Rules,2010.

Issued on 2/12/2 at New Delhi by

(Dr.G.C.Misra) Chief Fire Officer T.No.011-23414333

Copy to:- 1. Sh. Mohit H Hitter, Secretary, The Diocesan Society-Church of North India, 1, Church of Lane, New Delhi-110001.

Conditions for the validity of fire safety certificate are as under:-

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.
- 5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate, six month prior to its expiry.

		1470		305=	· · · · · · · · · · · · · · · · · · ·	
1	Nama & address of the building		ECTION REI		I DI I M	
1	Name & address of the building	M/S United Free Church located at Plot No.6, Kishan Garh, Ne Pocket "A", Sector "A" Vasant Kunj, New Delhi-110070.				
2	Type of Occupancy	Church (Place of Worship), "Assembly Building".				
3	Building Comprised of				moly building	9 .
		Ground plus one upper floor.				
4	Type of case	New Cas	e.			
5	Details of previous NOC	Nil.				
6	Fire safety directives letter No	No.F6/DF	S/BP/2009/	1934, dated	02.07.2009.	
7	Date of inspection	03.11.20	15			
8	Name of the inspecting Officers	: ADO(S.J	.) Vedpal			
9	Name and designation of officers					
	from the building side	-				
10	Year of construction	2009				
11	Applicant's letter No.		G-VK/2015	Dt 01.09.20	15	
S. NO.	Minimum Standards on fire			Domonico		
	prevention and fire safety U/R 33		uirement	Provided at site		Remarks MR / NMR
1	Access to building					
-	1) Road width	Accessibl	le	9m Provid	ed	MR
	2) Gate width	N/A		N/A		N/A
2	3) Width of internal road	N/A		N/A		N/A
	Number, width Type & arrangem a. Number of staircases	ent of exit	S			
				1		
	1. Upper floors	02nos.		02nos. Pro	ovided	MR
	2. basements	N/A		N/A	· · · · · · · · · · · · · · · · · · ·	N/A
	b. Width of staircase	1 E M+r (0	ach)	1		
	1. Upper floors	1.5 Mtr (e	acri)	1.5m (each)		MR
	2. basements	N/A N/A		*	N/A	
2	c. Protection of exits	Demineral				1.45
	1. Fire check door	Required N/A		Provided		MR
	2. Pressurizationd. No. of continuous staircase			N/A 1 No. Provided		N/A MR
	to terrace	Requied		T NO. FIO	vided	IVIT
	e. Width of corridor	N/A		N/A		N/A
	f. Door size	1.5 Mtr		1.8, 1.5,1.5 Mtr.		MR(Building
				1.0, 1.0, 1.0 1010		prior to 2010)
3	Compartmentation.	_				
	1. Fire check door	Required		Provided		MR
	2. Sealing of electrical shafts	Required		Provided		MR
	3. Fire Rating of shaft door	N/A		N/A		N/A
	4. water curtain	N/A		N/A		N/A
A	5. Fire dampers	N/A		N/A		N/A
4	Smoke Management system.	30 a/c per	hour	N/A	Company of the Compan	NI/A
	Basement Upper floors	12 a/c per		Natural Ve	ntilation	N/A MR
5	Fire Extinguishers	12 die pei	. 1001	Inatural ve	i illialiUH	IMIL
,	Total numbers			08 Nos		MR
	Types			ABC, Co2,		MR
	ISI marking	ISI		Yes Yes		MR
6	First-Aid Hose Reels.					
	Total numbers on each floor	One		01no. Prov	ided	MR
	Length of Hose reel hose	30 m		Provided		MR
	Nozzle Diameter	5 mm		Provided		MR
7	Automatic fire detection and alar					
	Type of detectors	N/A		N/A		N/A
	Location of Main Panel	N/A		N/A		N/A
		AL/A		NI/A		BL/A

<

N/6

8	MOEFA	Required	Provided	MR		
9	Public Address System.	Required	Provided	MR		
10	Automatic Sprinkler System.			1411		
	Basement	N/A	N/A	N/A		
	Upper floors	N/A	N/A	N/A		
	Sprinkler above false ceiling	N/A	N/A	N/A		
11	Internal Hydrants			INA		
	Size of riser/down-corner	100mm	100mm	MR		
	Number of Hydrants per floor	01no.	01no. Provided			
	hose Box	01no.	01no. Provided	MR MR		
12	Yard Hydrants.		o mo. i rovided	IVIE		
	total number of hydrants	N/A	N/A	N/A		
	hose box	N/A	N/A	N/A		
13	Pumping arrangements		1	[11//		
	1. Ground level					
	a. Discharge of main Pump	N/A	N/A	N/A		
	b.Head of main pump	N/A	N/A	N/A		
	c.Number of main pumps	N/A	N/A	N/A		
	d.jockey pump out put	N/A	N/A	N/A		
	e.jockey pump head	N/N	N/A	N/A		
	f. Standby Pump output	N/A	N/A	N/A		
	g.Stanby Pump head	N/A	N/A	N/A		
	h.Auto Starting/Manual stopping	N/A	N/A	N/A		
	pump house access	N/A	N/A	N/A		
	2.Terrace level					
	a. Discharge of pump	450LPM	450LPM	MR		
	b. head of the pump	40m	40m	MR		
	c. Power supply	Required	Provided	MR		
1.4	d. Auto starting of pump	Required	Provided	MR		
14	Captive water storage for fire fighting					
	1. Underground tank capacity	N/A	N/A	N/A		
	a. Draw-off connection	N/A	N/A	N/A		
	b. fire service inlet	N/A	N/A	N/A		
	c.Access to tank	N/A	N/A	N/A		
	Over head tank Capacity	10,000 ltr	10,000 ltrs. Provided	MR		
15	Exit Signage.	Required	Provided	MR		
16	Provision of lifts.					
	a. Pressurization of lift shaft	N/A	N/A	N/A		
	b. pressurization of lift lobby	N/A	N/A	N/A		
	c. communication in lift car	N/A	N/A	° N/A		
	d. Fireman's grounding switch	N/A	N/A	N/A		
7	e. Lift signage	N/A	N/A	N/A		
7	Standby power supply	Required	Provided	MR		
	Refuge Area.	Not Required				
	total area					
	location					
	Fire control room					
	a. Detector system Panel	N/A	N/A	N/A		
	b. Flow switch Panel	N/A	N/A	N/A		
	c. PA system Panel	N/A	N/A	N/A		
	d. Batter backup	N/A	N/A	N/A		
	e. Building floor plans	N/A	N/A	N/A		



20	-	-
	~	\mathbf{n}

Special Fire Protection systems for protection of special risks, if any:

The fire protection systems provided in the building were test checked randomly and found functional at the time of inspection. Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Accordingly DFA is put up for your approval and signature please.

Signature of the inspecting officer

Name Vedpal

Designation: Assistant Divisional Officer (S.

D.O. (South) on I