

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F 6 / DFS / MS / 2016 / EH/w2 / 1173

Dated 17/11/16

FIRE SAFETY CERTIFICATE

Certified that the M/s M/s Cafeteria and Co. (A Unit of Jumbo Restaurant Pvt Ltd), G-14,, 1st Floor, 2nd Floor & 3rd Floor, Vijay Nagar, Delhi comprised of ground and 3rd Floors owned/ occupied by Sh. Saurabh Wahie / Director have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Fire Service on **02.11.2016** in the presence of Mr Akhil/ Partner and that the building/ premises is fit for occupancy "Assembly" at 1st, 2nd & 3rd floor only with effect from 17/11/16 for a period of **03 (Three) years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule ~~38~~ of the Delhi Fire Service Rules, 2010.

Conditions for the validity of Fire Safety Certificate:

1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
3. The trained fire fighting staff should be available round the clock.
4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.
7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on WWW.dfs.Delhigovt.n.c.in
8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

Issued on 17/11/16..... at New Delhi by


(Atul Garg)

Chief Fire Officer

Ph-011-23414250

Copy to:-

1. Mr.Saurabh Wahie, M/s Cafeteria and Co. (A Unit of Jumbo Restaurant Pvt Ltd), G-14, 1st Floor, 2nd Floor & 3rd Floor, Vijay Vihar, Delhi.

N/9

INSPECTION REPORT

1. Name & address of the building : M/s Cafeteria and Co. (A Unit of Jumbo Restaurant Pvt Ltd),G-14,
1st Floor, 2nd Floor & 3rd Floor, Vijay Nagar, Delhi.
2. Type of Occupancy :Mixed Occupancy (Assembly/ Mercantile)
3. Type of Case :New Case
4. Details of previous NOC :Nil
5. Fire Safety directives letter No :NBC Part IV Ground---Shops (Other property)
6. Date of inspection :02/11/2016 First Floor---Restaurant Hall
7. Name of the Inspecting Officers :ADO (RN) Second Floor---Restaurant hall
8. Name and designation of officers Third Floor--- Kitchen
from the building side : Mr Akhil(Partner/Cafe)
9. Year of Construction : Not Known
10. Applicant's letter No. : Nil dated 07.10.2016.

	Minimum Standards on fire prevention and fire safety U/R 33	NBC Requirement	Provided at site	Remarks MR/NMR
1	Access to building			
	• Road width	06m	12m (approx)	MR
	• Gate width	4.5m	Directly accessible	MR
	• Width of internal road	NA	NA	NA
2	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases			
	• Upper Floors	01	02	MR
	• Basements	NA	NA	NA
	b. Width of staircases			
	• Upper Floors	1.50 m	1.50m & 1.25m	MR
	• Basements	NA	NA	NA
	c. Protection of exits			
	• Fire check door	NA	NA	NA
	• Pressurization	NA	NA	NA
	d. No. of continuous staircases to terrace	01	01	MR
	e. Width of Corridor	NA	NA	NA
	f. Door Size	2.0m	1.40m & 2.0m	MR
3	Compartmentation.			

N/10

	<ul style="list-style-type: none"> • Fire check door • Sealing of electrical shafts • Fire Rating of shaft door • Water Curtain • Fire Dampers 	Required to segregate Kitchen & Staircase	Provided	MR
		Required	Provided	MR
		NA	NA	NA
		NA	NA	NA
		NA	NA	NA
4	Smoke Management System.			
	<ul style="list-style-type: none"> • Basements • Upper floors 	30 a/c per hour	NA	NA
		12 a/c per hour	Natural Ventilated	MR
5	Fire Extinguishers			
	<ul style="list-style-type: none"> • Total numbers • Types • ISI marking 	08nos	10nos	MR
		ABC/Co2	10 ABC	MR
		Yes	Yes	MR
6	First-Aid Hose Reels.			
	<ul style="list-style-type: none"> • Total numbers on each floor • Length of hose reel hose • Nozzle diameter 	01	01	MR
		30 m	30m	MR
		5mm	5mm	MR
7	Automatic fire detection and alarming system.			
	<ul style="list-style-type: none"> • Type of detectors • Location of Main Panel • Location of Repeater Panel • Alternate source of power • Hooters' Location 	Required	Provided	MR
		Required	Provided	MR
		Required	Provided	MR
		Required	Provided	MR
		Required	Provided all level	MR
8	MOEFA	Required	Provided	MR
9	Public Address System.	NA	NA	NA
10	Automatic Sprinkler System.			
	<ul style="list-style-type: none"> • Basement • Upper Floor • Sprinkler above false ceiling 	NA	NA	NA
		NA	Provided	NA
		NA	NA	NA
11	Internal Hydrants			
	<ul style="list-style-type: none"> • Size of riser/down-comer • Number of hydrants per floor • Hose Box 	100mm	Provided	MR
		01	Provided	MR
		01	Provided	MR
12	Yard Hydrants.			

2/11

	<ul style="list-style-type: none"> Total number of hydrants Hose Box 	NA	NA	NA
		NA	NA	NA
13	Pumping Arrangements.			
	<ul style="list-style-type: none"> Ground Level <ul style="list-style-type: none"> Discharge of main Pump Head of Main pump Number of main pumps Jockey Pump out put Jockey pump head Standby Pump out put Standby Pump Head Auto Starting/ Manual stopping Pump House Access Terrace level <ul style="list-style-type: none"> Discharge of pump Head of the pump Power Supply Auto Starting of pump 	1620lpm	1620lpm	MR
		60m	60m	MR
		01	01	MR
		180lpm	180lpm	MR
		60m	60m	MR
		1620lpm	1620lpm	MR
		60m	60m	MR
		Required	Provided	MR
		450lpm	450lpm	MR
		40m	Provided	MR
		Required	Provided	MR
		Required	Provided	MR
14	Captive Water Storage for fire fighting.			
	<ul style="list-style-type: none"> Underground tank capacity Draw-off connection Fire service inlet Access to tank Overhead Tank capacity 	50,000 ltrs	50,000 ltr.	MR
		Required	Provided	MR
		Required	Provided	MR
		Required	Provided	MR
		5,000 ltr	5,000 ltrs	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			
	<ul style="list-style-type: none"> Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
17	Standby power supply	Required	Provided	MR
18	Refuge Area.			
	<ul style="list-style-type: none"> Total Area 	N/A	N/A	N/A

N

M/V

	> Location	N/A	N/A	N/A
19	Fire Control Room			
	• Detector System Panel	N/A	N/A	N/A
	• Flow Switch Panel	N/A	N/A	N/A
	• PA System Panel	N/A	N/A	N/A
	• Batter backup	N/A	N/A	N/A
	• Building Floor Plans	N/A	N/A	N/A
20	Special Fire Protection Systems for Protection of special Risks, if any:	NA	NA	NA

The fire protection systems provided in the building were tested/ checked and found some in working order at the time of inspection. The Party has complied all the observations issued vide this department letter of even no. 2433 dated 14.10.2016.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

ACU
03/11/16

Signature of the Inspecting Officer


Name: - Rajesh Kumar

Designation:- ADO/RN

~~DO 14/10/16~~
S Singh
4.11.16

~~Dy CRO (u2)~~
~~CFO West~~
9/11/16

ATP


03/11/16