GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F 6/DFS/MS/2016/ Se hool [w2/1175

Dated: 17 /11 /2016

FIRE SAFETY CERTIFICATE

Certified that the Swami Vivekananda Public School, Block-A, Gali no-8, Amrit Vihar, Burari, Delhi-84 comprised of Ground and 02 upper floors owned/ occupied by Swami Vivekananda Public School was issued Fire Safety Certificated vide this office letter no. F-6/MS/DFS/2006/3843 dated 28.12.2006 for building comprised of ground floor only. The premise was re-inspected by the officer concerned of this department on 27.10.2016 in the presence of Mrs. Shally Goshal/ Principal and observed that the school building is comprised of Ground + 02 floor and the school have complied with the fire prevention and fire safety arrangements as provided in the premise found in good working condition. The premise have therefore deemed complied with the requirements under rule 33 of the Delhi Fire Service Rules, 2010 and the building premise is fit for occupancy under Educational "Group B" with effect from for a period of three years in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under rule 40, subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010,

Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Ferm 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry'.
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <u>WWW.dfs.Delhigovt.nic.in</u>

Chief fire officer

Ph:-011-23414250

Copy to:-

1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi - 110054.

2. The Principal, Swami Vivekananda Public School, Block-A, Gali no-8, Amrt Vihar, Burari, Delhi-84

			0/12		
*		INSPEC	TION REPORT		
Ţ	. Name & address of the building		Vivekananda Public , Burari, Delhi-11008	School, Block-A, Ga	li no-8, Amrit
2	Type of Occupancy	: Educa			
3	Type of Case	: Renewal (Add. / Alt.) (G + 02)			
4	Details of previous NOC	:F6/MS/DFS/2006/3843 Dated: 28/12/2006 (G+1)			
5	Fire Safety directives letter No	: Director of Education Letter dated 01.03.2011/ NBC Part 4			
6	Date of inspection	: 27/10/2016			
7	Name of the Inspecting Officers	: ADO (RN)			
8	Name and designation of officers				
	from the building side	: Mrs.	Shally Goshal/ Prin	cipal	
9	Year of Construction	: 2005			
10	. Applicant's letter No.	: Nil L	Dated: 27.09.2016		
Р	lot Area-406SqY Covered area	700sqŸ,	No of student—25	0 nos, Total class	room15nos
	Minimum Standards on fire preve and fire safety U/R 33	ention	Dir. Of Education/ NBC Requirement	Provided at site	Remarks MR/NMR
	Access to building		requirement		
f	Road width		6m	6m	MR
	Gate width		4.5m	2.40m x 2	MR(Old case
	 Width of internal road 		NA	NA	NA
	Number, Width, Type & Arrangem	ent of E	xits	я	
-	a. Number of staircases				
	 Upper Floors 		02	02	MR
	Basements		NA	NA	NA
	b. Width of staircases				
	 Upper Floors 		1.50 m	1.5m & 1.25m	MR
	 Basements 		NA	NA	. NA
	c. Protection of exits				2 20
	Fire check door		NA	NA	NA
	 Pressurization 		NA	NA	NA

01

NA

1.0m

NA

01

NA

lm

NA

MR

NA MR

NA

d. No. of continuous staircases to terrace

e. Width of Corridor

Compartmentation.

• Fire check door

. Door Size

3

Mas

	 Sealing of electrical shafts 	NA	NA	NA	
	Fire Rating of shaft door	NA	NA	NA	
	Water Curtain	NA	NA	NA	
	Fire Dampers	NA	NA	NA	
4	Smoke Management System.				
	Basements	30 a/c per hour	21.1		
	Upper floors		No basement	. NA	
5		12 a/c per hour	Natural Ventilated	MR	
5	Fire Extinguishers				
	 Total numbers 	6nos	8 nos	MR	
	• Types	ABC/Co2	ABC8	MR	
	ISI marking	Yes	Yes	MR	
)	First-Aid Hose Reels.				
	Total numbers on each floor	01	01	MR	
	 Length of hose reel hose 				
	 Nozzle diameter 	30m	30m	MR	
	Automatic fire detection and a	5m	5m	MR	
	Automatic fire detection and alarming system				
	Type of detectors	NA	NA	NA	
	 Location of Main Panel 	NA	NA	NA	
	 Location of Repeater Panel 	NA	NA	NA	
	Alternate source of power	NA	NA	NA	
	Hooters' Location	NA	NA	NA	
	MOEFA	NA	NA	NA	
	Public Address System.	NA	NA	NA	
)	Automatic Sprinkler System.				
	Basement	NA	NA	. NA	
	Upper Floor	NA	NA	NA.	
	 Sprinkler above false ceiling 	NA	NA	NA	
	Internal Hydrants				
	• Size of riser/down-comer	NA	NA	NA	
	 Number of hydrants per floor 	NA	NA	NA	
	• Hose Box	NA	NA	NA	
	Yard Hydrants.				
	 Total number of hydrants 	NA	NA	NA	
	 Hose Box 	NA	NA	NA	
3	Pumping Arrangements.				

	Ground Level			a
	Discharge of main Pump	N/A	N/A	N/A
	Head of Main pump	N/A	N/A	N/A
	Number of main pumps	N/A	N/A	
	Jockey Pump out put			N/A
	Jockey pump head	N/A N/A	N/A	N/A
	Standby Pump out put		N/A	N/A
la"	Standby Pump Head	N/A	N/A	N/A
	Auto Starting/ Manual stoppingPump House Access	N/A	N/A	N/A
	Terrace level	N/A	N/A	N/A
	Discharge of pump			
	➤ Head of the pump	450lpm	4501pm	MR
	Power Supply	40m	40m	MR
		Required	Provided	MR
	S. L. L.	Required	Provided	MR
14	Captive Water Storage for fire fighting.			
	Underground tank capacity	NA	NA	NA
	Draw-off connection	NA	NA	NA
	> Fire service inlet	NA	NA	NA
	Access to tank	NA	NA	NA
	Overhead Tank capacity	10,000ltr	10,000ltr	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			2.2
	Pressurization of Lift Shaft	N/A	N/A	N/A
	Pressurization of Lift lobby	N/A	N/A	N/A
	Communication In lift Car	N/A	N/A	N/A
	Fireman's Grounding Switch	N/A	N/A	· N/A
	Lift Signage	N/A	N/A	N/A
17	Standby power supply	N/A	N/A	N/A
18	Refuge Area.			
	> Total Area	N/A	N/A	N/A
	> Location	N/A	N/A	N/A
19	Fire Control Room			
	Detector System Panel	N/A	N/A	N/A
	Flow Switch Panel	N/A	N/A	N/A

MIS

 PA System Panel 	N/A	N/A	N/A
Batter backup	N/A	N/A	N/A
Building Floor Plans	N/A	N/A	N/A
Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested/ checked randomly and found in good working condition, at the time of inspection. The management has complied all the shortcomings issued and communicated by this department vide letter of even no. 2288 dated 23.09.2016.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in Director of Education Circular / NBC Part 4, the FSC issued vide letter of even no 3843 dated 28.12.2006 renewal under rule 35 of the Delhi Fire Service Rules, 2010 is recommended

811/6

Signature of the Inspecting Officer Name: Rajesh Kumar

Designation:- ADO/RN

Dolphoo

3-11-11

cro wed all

PS