GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. PGIDESIMS | 2016/82/1222

Dated: 29/11/16

FIRE SAFETY CERTIFICATE

Certified that M/s Jewel Palace Guest house located at 2622-27, Gali No.- 03, Bank Street, Karol Bagh, New Delhi-110005, comprised of ground plus four upper floors, using ground floor as reception & shops, first floor having 13 guest rooms + 01 dining hall, second and third floor each having 19 guest rooms & fourth floor having 07 guest rooms, one hall, D.G. set room and pantry for staffs (total 58 guest rooms) was granted FSC by this department vide letter No. F.6/DFS/MS/GH/2013/SZ/934 dated 20/09/2013 for 58 guest rooms. The premises was re-inspected by the officer concerned of this department on 26/10/16 in the presence of Mr. Narang, Manager of the guest house and found that the said guest house have reduced the guest rooms from 58 guest rooms to 47 guest rooms(ground floor as reception & shops, first floor having 09 guest rooms, 01 dining hall, 01 computer room, 01 fitness room and 01 record room, second and third floor having 19 guest rooms each & fourth floor having 01 pantry for staff, 01 hall, 01 general manager office, 01 staff room, 03 store rooms, 02 vacant rooms, 01 D.G. set room) and have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class residential (guest house) up to third floor only with effect from 29 period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010.

Issued 29 /11/16 at New Delhi by.

2 S | | | (VIPEN KENTAL) CHIEF FIRE OFFICER

Copy to:-

- 1. The Manager, M/s. Hotel Jewel Palace Guest house, 2622-27, Gali No.- 03, Bank Street, Karol Bakh, refull to New Delhi-110005.
- 2. The Joint C.P.(Lic.), Police Station, Defence Colony, 1st floor, New Delhi.

Following Fire Safety Directives Must Be Adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non-functional of fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained firefighting staffs should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form "J" [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building:- M/s. Hotel Jewel Palace Guest house, 2622-27, Gali No.- 03, Bank Street, Karol Bagh, New Delhi-110005

2. Type of Occupancy

:- Residential (Guest House)

3. Type of Case

:- Renewal

4. Details of previous NOC

:- F6/DFS/MS/GH/2013/SZ/934 dated 20/09/2013

5. Fire Safety directives letter No

:- N/A

6. Date of inspection

:- 26.10.2016

7. Name of the Inspecting Officers : M.K Chattopadhyay, DO (SW)

8. Name and designation of officers

from the building side

: Mr. Narang, Manager

9. Year of Construction

: 1988-89

10. Applicant's letter No.

: 3020-21/Joint C.P./Lic(H) dated New Delhi the 28/09/2016

The said Guest house is comprised of ground floor (reception & shops), first floor guest rooms + 01 dining hall + 01 computer room + 01 fitness room + 01 record room), second and third floor (19 guest rooms each) & fourth floor (pantry for staff, hall, general manager office, 01 staff room, 03 store rooms, 02 vacant rooms, 01 D.G. set room) (Total 47 guest rooms)

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Requirements as pe letter dated 08-07-20		te Remarks MR/NMR				
1	1 Access to building							
	• Road width	06 mts	18 mts	MR				
3	• Gate width	4.5 mts	Directly accessifrom the road	ble MR				
A 1	Width of internal road	N/A	N/A	N/A				
2	Number, Width, Type & Arrangement of Exits							
	a. Number of staircases	-	- :	-				
и_	• Upper Floors	01	01	MR being old case				
	• Basements	N/A	N/A	N/A				
	b. Width of staircases	-	-	-				
	• Upper Floors	1.25 mts	1.25 mts	MR being old case N/A - N/A				
	Basements	N/A	N/A					
22	c. Protection of exits	-	-					
	• Fire check door	N/A	N/A					
	• Pressurization	N/A	N/A	N/A				
	e. No. of continuous staircases to terrace		01	MR				
	g. Width of Corridor	1.25 mts	1.50-2.15 mts	MR				
	h. Door Size	N/A	85 cm provided	MR being old case				
3	Compartmentation.							
	• Fire check door	N/A	N/A	N/A				
	Sealing of electrical shafts	N/A	N/A	N/A				
	Fire Rating of shaft door	N/A	N/A	N/A				
	Water Curtain	N/A	N/A	N/A				

	Fire Dampers	N/A	N/A	2	N/A	
	4 Smoke Management System.					
	• Basements	30 a/c per hour	N/A			N/A
	Upper floors	12 a/c per hour	Natural Vent	ilation		11/11
5	Fire Extinguishers	-	, chi	.Tidtloff	MR	
	Total numbers	1				
	• Types	05 no's at each floor	Provide	ed	M	R
>	• IS marking	WCO2, ABC, CO ₂ type ISI marked	Provide	ed	MI	2
6		151 marked	Provide	ed	MR	
	Total numbers on each flo				4	
			Provide	d	MR	
	Length of hose reel hoseNozzle diameter	30 m 5 mm	Provide	d	MR	
7		The second secon	Provided	d	MR	
,	Automatic fire detection and ala	Not Required				
	• Type of detectors		Provided	d (Smo	oke)	
	 Location of Main Panel 	Not Required	Provided	l (GF)		
75-	• Location of Repeater Panel	N/A	N/A		N/A	
	Alternate source of power	N/A		A STATE OF THE PARTY OF THE PAR		
	Hooters' Location		Provided			
	Tiones Location	N/A	N/A		N/A	
8	MOEFA	Required	Provided		MD	
9	Public Address System.	Required	Provided		MR	
10	Automatic Sprinkler System.	itomatic Sprinkler System.			MR	
	Basement	N/A	N/A		N/	'A
	Upper Floor	N/A	N/A		· N/	
	Sprikler above false	N/A	20 M2	7 2		
	CCilling	11/21	N/A		N/.	A
11	Internal Hydrants					
	• Size of riser/down-comer	N/A	N/A		N/2	A
	Number of hydrants per	N/A	N/A		N/A	1
	floor	N/A	N/A			
10	• How Rox	*	IN/A		N/A	A
12	Yard Hyd mats.			19		
-	• To Lumber of hydrants	N/A	N/A	y i	N/A	
12	• How Box	N/A	N/A		N/A	
13	Pumping Arrangements.					
	Grand Level					
	Discharge of main Pump	N/A	N/A		N/A	
	> Head of Main pump	N/A	N/A		N/A	
	Namber of main pumps	N/A	N/A		N/A	
					IN/A	

		N/A	N/A	N/A			
	> Jockey Pump out put	N/A	N/A	N/A			
	➤ Jockey pump head	N/A	N/A	N/A			
	Standby Pump out put	N/A	N/A	N/A			
	Standby Pump Head	N/A	N/A	N/A			
	> Auto Starting/ Manual	N/A	N/A	N/A			
	stopping	IV/A		-			
	> Pump House Access	-	-	MR			
	Terrace levelDischarge of pump	450 LPM	Provided				
	> Head of the pump	30 mts	Provided	MR			
> Power Supply		Required	Provided	MR			
	> Auto Starting of pump	Required	Provided	MR			
14 Contine Water Storage for fire fighting.							
14	Underground tank capacity	N/A	N/A	N/A			
		N/A	N/A	N/A			
	Draw-off connectionFire service inlet	N/A	N/A	N/A			
	To	N/A	N/A	N/A			
	 Access to tank Overhead Tank capacity 	5000 lts	5,000 lts	MR being old case			
		Required	Provided	MR			
15	Provision of Lifts. Lift is under installation						
16		N/A	N/A	N/A			
	Pressurization of Lift Shaft Pressurization of Lift lobby	N/A	N/A	N/A			
	Pressurization of Lift lobby	Required	Provided	MR			
	Communication in lift Car	Required	Provided	MR			
	Fireman's Grounding Switch	Required	Provided	MR			
	Lift Signage	Required	Provided	MR			
17	Standby power supply						
18	Refuge Area.	N/A	N/A	N/A			
	> Total Area	N/A	N/A	N/A			
	> Location	1111					
19	Fire Confro Room	N/A	N/A	N/A			
	Defector System PanelFlow Switch Panel	N/A	N/A	N/A			
		N/A	N/A	N/A			
	PA System Panel	N/A	N/A	N/A			
	Batter backup		N/A	N/A			
	Bui ding Floor Plans	N/A	14/11				

20	Special Fire Protection Systems for	N/A	N/A		N/A
	Protection of special Risks, if any			•	
				1.0	. 1

The fire protection system provided in the building were checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F.6/DFS/MS/GH/2013/SZ/934 dated 20/09/2013, renewal under rules 35 of the Delhi Fire Service Rules 2010 is recommended.

Accordingly, DFA is put up please.

(M.K. CHATTOPADHYAY)
Divisional Officer (SW)

DCFO (SZ)

My

CFO (ST)

Pl opach

410/cho52