GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001

No.F6/DFS/MS/GH/2016/12/5

Dated :- 28:11:2016

FIRE SAFETY CERTIFICATE

Certified that the Kabana Guest House, 1022-1024/18Nai Walan, Karol Bagh, New Delhi-110005 comprised of Basement, Ground + 4 Upper Floors, Basement hall, Ground floor – reception & 02 guest rooms, 1st floor & 2nd floor 02 guest rooms at each floor, 3rd floor 07 guest rooms, 4th floor 03 guest rooms total was granted FSC by this department vide letter 16 rooms dated 19.12.2013. The premises was re-No.F6/DFS/MS/GH/2013/NDZ/1324 inspected by the officer concerned of this department on 08.11.2016 in the presence of Sh. Vashisht Mahajan and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy of class Residential Group -A-1' for total 16 guest rooms only as above with effect from 28:11:2016 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010. mentioned below.

> (Vipin Kental) Chief Fire Officer Delhi Fire Service Ph: - 011-23412225

Copy to:-

1. The Joint. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi

The Licensee,
 Kabana Guest House. 1022-1024/18Nai Walan, Karol Bagh, New Delhi.

3. The Dy. Commissioner, NDMC, Karol Bagh, Anand Parbat, New Delhi. - is requested to measure the height of the building & apprise this department.

Condition:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. The means of escape shall be kept unobstructed / unlocked & remain available for speedy evacuation of occupants in case of an emergency.
- 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 4. The trained fire fighting staff should be available round the clock.
- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The height of the premises shall be got verified from building authority in accordance with clause 2-11 of BBL 1983. The licensee should contact building department for same & furnish information in this department.
- 8. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

		NSPECTION DE	DOD'T					
	1.Name & address of the build	NSPECTION RE	PORT	2.111				
		ding:- Kabana Guest House,1022-1024/18Nai Wala						
	2. Type of occupancy:-	Residenti	Karol Bagh, New Delhi-110005.					
		+ 4 Unne	Residential Group A-1 Basement, Ground					
			+ 4 Upper Floors. (16 guest rooms) Basement hall. Ground floor recention % 03					
		floor & 2 ⁿ	hall, Ground floor – reception & 02 guest rooms, 1 st floor & 2 nd floor 02 guest rooms at each floor, 3 rd floor 07 guest rooms, 4 th floor 03 guest rooms					
	3. Type of case:-	floor 07 gu						
	4. Details of previous FSC:-	Renewal	Reflewal					
	of previous 1 Sc	No. F6/D	No. F6/DFS/MS/GH/2013/NDZ/1324 dated					
	5. Fire safety directives No		19/12/2013.					
- 12	6. Date of inspection:-							
	7. Name of the inspecting officer: D.O. Carrella G.							
	8. Name & designation of officer D.O. Gurmukh Singh							
i	From the building side:		Ch Wall Land					
	9. Year of construction:-	9. Year of construction:						
	10. Applicant's letter No:-		1 19/09/16					
-		Till-Daice	1 19/09/16					
S.No	Treating Standards () Tire	Requirement/	Duorid 1 1	Old Case				
	Prevention and fire safety	Existing fire	Provided at site	Remarks				
	U/R 33	safety		MR/NMR				
		arrangements						
1.	Access to Building	Bomonito						
	1) Road width	N/A	4 mtr.) A (D)				
	2) Gate width	N/A	N/A	MR				
	3)Width of internal road	N/A		N/A				
2.	Number, Width Type & Arra	ngement of Evita	N/A	N/A				
	A. Number of staircases	ingenient of Exits						
	1. Upper floors	02 Nos.	00.31					
	2. Basements	02 Nos.	02 Nos.	MR				
	B. Width of staircase	OT IVO.	01 No.	MR				
	1. Upper floors, 2 nd staircase	106 cms.	110	***				
	originated from 3 rd floor to 4 th	100 cms.	110 cms. to 122	MR				
	floor 1 mtr.		cms. & 1 mtr.					
	2. Basements	100 cms.	100 cms.	MD				
	C. Protection of exits		200 01115.	MR				
	1. Fire check door	N/A	N/A	NI/A				
	2. Pressurization	N/A	N/A	N/A				
	D. No. of continuous	N/A	N/A	N/A				
	staircase to terrace		11//1	N/A				
	E. Width of corridor	N/A	N/A	DT/A				
2	F. Door size	1 mtr.	1 mtr.	N/A				
3.	Compartmentation		1 11111.	MR				
	1) Fire check door	N/A	NI/A					
	2) Sealing of electrical shafts	N/A	N/A	N/A				

N/A

N/A

N/A

N/A

30 ACPH

N/A

N/A

N/A

N/A

Exhaust fan

2) Sealing of electrical shafts

3) Fire rating of shaft door

Smoke Management System

4) Water curtain

5) Fire Dampers

1) Basements

4.

MR

N/A

N/A

N/A

N/A

		_					
_	2) Upper floors]	12 ACPH	N	atural		MR
5.	Fire Extinguishers						
	1) Total numbers	()8 Nos.	10	Nos.		MR
	2) Types	I	ABC & CO2	A	BC &CO2		MR
	3) ISI marking	Required		Provided			MR
6.	First-Aid Hose Reel						
	1)Total number one only	(1 no.	01 no.			MR
	2) Length of hose reel hose	30 mtr.		30 mtr.			MR
	3) Nozzle diameter	5	mm.	5 1	mm.		MR
7.	Automatic Fire Detection & Alarming System						
	1) Type of detectors		J/A	N/	'A		N/A
	2) Location of main panel	N/A		N/A			N/A
	3) Location of repeater panel	N/A		N/A			N/A
	4) Alternate source of power	N	J/A	N/A			N/A
	5) Hooter's Location	N/A		N/A			N/A
8.	MOEFA	Required		Provided			MR
9.	Public Address System /	Required		Provided			MR
	Intercom				Trovided		17110
10.	Automatic Sprinkler System		0				
	1) Basement	Required		Provided			MR
	2) Upper floors		J/A	N/A			N/A
	3) Sprinkler above false	N/A		N/A			N/A
	ceiling			1 1/			I V/ /\texts
11.	Internal Hydrants						
	1) Size of riser/down-comer	N/A		N/A			N/A
	2) Number of hydrants per	N/A		N/A			N/A
	floor	1 1/1 1		14/11			IV/A
	3) Hose box	N/A		N/A			N/A
12.	Yard Hydrants						
	1) Total number of hydrants	N	I/A	N/A			N/A
	2) Hose box	-	I/A	N/A			N/A
13.	Pumping Arrangement			1 17			IV/A
	1) Ground level		N/A		N/A		N/A
	a) Discharge of main pum	n	N/A		N/A		
	b) Head of main pump		N/A		N/A N/A		N/A
	c) Number of main pump		N/A		N/A N/A		N/A
	d) Jockey pump out put		N/A				N/A
	e) Jockey pump head		N/A		N/A		N/A
	f) Stand by pump output				N/A		N/A
	g) Stand by pump head		N/A		N/A		N/A
	h) Auto starting/Manual		N/A		N/A		N/A
	stopping		N/A		N/A		N/A
	2) Terrace level		9,				
			450 T D) 6		450 -		111111111111111111111111111111111111111
	a) Discharge of pump		450 LPM		450 LPM		MR
	b) Head of pump		30 Mtr.		30 mtr.		MR
	c) Power supply	Required		Provided			MR
	d) Auto starting of pump	Required		Provided		MR	

M

	1) Under ground tank capacity	N/A	N/A	N/A
	a) Draw-off connection	N/A	N/A	N/A
	b) Fire service inlet	N/A	N/A	N/A
	c) Access to tank	N/A	N/A	N/A
	d) Over head tank capacity	5,000 ltrs.	5,000 ltrs.	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
T	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	N/A	N/A	N/A
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for Prany:	N/A		

The fire protection system provided in the guest house were tested, checked at random and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter No. F6/MS/DFS/GH/2013/NDZ/1324 dated 19/12/2013, renewal under Rule 35 of the Delhi Fire Service rules 2010, is recommended.

Gurmukh Singh Divisional Officer

Дуско (NDZ)
2 111