GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/School/SZ/2016/ | 7 30

Dated: 01 116

FIRE SAFETY CERTIFICATE

Delhi- 110008, comprised of ground plus one upper floor, was granted Fire Safety Certificate vide letter No. F.6/DFS/MS/School/2013/SZ/994 dated 30.09.2013. The school building was reinspected by the officer concerned of this department on 10.11.2016 in the presence of Mrs. Santosh Malhotra, principal of the school and found that the school building have deemed complied with the fire prevention and fire safety requirements in accordance with Directorate of Education circular No. F.16/Estate/CC/Fire Safety/2011/3198 to 3399 dated 01.03.2011 and that the building/premises is fit for occupancy class "Educational" with effect from of period of 03 years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions printed overleaf under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on ollife at New Delhi by.

(VIPIN KENTAL) CHIEF FIRE OFFICER

Copy to: -

- 1. The Principal, Sanatan Shishu Gyan Mandir, T-137, Baljeet Nagar, New Delhi- 1 0008.
- 2. The Directorate of Education, Old Secretariat, Delhi.

Conditions for the Validity of Fire Safety Certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner/occupier shall submit a declaration every year in form 'K' Provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building

: Sanatan Shishu Gyan Mandir, T-137, Baljeet Nagar, New

Delhi- 110008

2. Type of Occupancy

: Educational

3. Type of Case

: Renewal

4. Details of previous NOC

: F.6/DFS/MS/School/2013/SZ/994 dated 30.09.2013

5. Fire Safety directives letter No

: N/A

6. Date of inspection

: 10.11.2016

7. Name of the Inspecting Officers : M.K. Chattopadhyay, Divisional Officer (South West)

8. Name and designation of officers

from the building side

: Mrs. Santosh Malhotra, principal

9. Year of Construction

: 1982-83

10. Applicant's letter No.

: Nil dated 07.10.2016.

Sanatan Shishu Gyan Mandir school is comprised of ground plus one upper floor

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Requirement as per letter dated 30.09.2013	Provided at site	Remarks MR/NMR		
1	Access to building					
	Road widthGate widthWidth of internal road	06 mts 4.5 mts	Provided Provided N/A	MR MR N/A		
2	Number, Width, Type & Arrangement			*		
	a. Number of staircases • Upper Floors • Basements b. Width of staircases • Upper Floors • Basements c. Protection of exits • Fire check door • Pressurization e. No. of continuous staircases to terrace g. Width of Corridor	02 N/A 1.5 mts or less & 0.75 mt N/A N/A N/A N/A N/A N/A	02 N/A 1.10 mts & 0.90 mt. N/A N/A N/A N/A N/A N/A	MR N/A MR N/A N/A N/A N/A N/A N/A N/A N/A		
	h. Door Size	Old Case	Provided (0.87 mt)	MR being old case		
3	Compartmentation.	*				
	Fire check doorSealing of electrical shafts	N/A N/A	N/A N/A	N/A N/A		
	Fire Rating of shaft doorWater CurtainFire Dampers	N/A N/A N/A	N/A N/A N/A	N/A N/A N/A		

	• Upper floors	12 a/c per hour	Natural ventilation provided	MR		
5	Fire Extinguishers					
	• Total numbers	09 nos.	Provided	MR		
÷	• Types	ABC type	Provided	MR		
	IS marking	ISI marked	Provided	MR		
6	First-Aid Hose Reels.		N/A	N/A		
	 Total numbers on each floor 		N/A			
	 Length of hose reel hose 	30 m	N/A	N/A		
	Nozzle diameter	5 mm	N/A	N/A		
7	Automatic fire detection and alarming s	required				
	Type of detectors	N/A	N/A	N/A		
	Location of Main Panel	N/A	N/A	N/A		
	Location of Repeater Panel	N/A	N/A	N/A		
	Alternate source of power	N/A	N/A	N/A		
	Hooters' Location	N/A	N/A	N/A		
8	MOEFA	N/A	N/A	N/A		
9	Public Address System.	N/A	N/A	N/A		
10	Automatic Sprinkler System					
	Basement	N/A	N/A	N/A		
	Upper Floor	N/A	N/A	N/A		
	Sprinkler above false ceiling	N/A	N/A	N/A		
11	Internal Hydrants					
	Size of riser/down-comer	N/A	N/A	N/A		
>	Number of hydrants per floor	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
12	Yard Hydrants.					
	Total number of hydrants	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
13	Pumping Arrangements					
	Ground Level	:				
	Discharge of main Pump	N/A	N/A	N/A		
	➤ Head of Main pump	N/A	N/A	N/A		
	> Number of main pumps	N/A	N/A	N/A		
	Jockey Pump out put	N/A	N/A	N/A		
	> Jockey pump head	N/A	N/A	N/A		
	> Standby Pump out put	N/A	N/A	N/A		

	Standby Pump Head	N/A	N/A	N/A		
	> Auto Starting/ Manual	N/A	N/A	N/A		
	stopping	N/A	N/A	N/A		
	Pump House Access		`			
	Terrace level	N/A	N/A	N/A		
	Discharge of pump	N/A	N/A	N/A		
	➤ Head of the pump	N/A	N/A	N/A		
	> Power Supply	N/A	N/A	N/A		
1.4	Auto Starting of pump					
14	Captive Water Storage for fire fightin		DT/A	NT/A		
	Underground tank capacity	N/A	N/A	N/A		
	Draw-off connection	N/A	N/A	N/A		
	Fire service inletAccess to tank	N/A N/A	N/A N/A	N/A N/A		
	Overhead Tank capacity		N/A	N/A		
	o vernead rank capacity	N/A				
15	Exit Signage.	Required	Provided	MR		
16	Provision of Lifts.	Not Applica	able			
	Pressurization of Lift Shaft	N/A	N/A	N/A		
	Pressurization of Lift lobby	N/A	N/A	N/A		
	Communication In lift Car	N/A	N/A	N/A		
	Fireman's Grounding Switch	N/A	N/A	N/A		
	Lift Signage	N/A	N/A	N/A		
17	Standby power supply	N/A	N/A	N/A		
18	Refuge Area.					
	> Total Area	N/A	N/A	N/A		
	> Location	N/A	N/A	N/A		
19	Fire Control Room					
	Detector System Panel	N/A	N/A	N/A		
	Flow Switch Panel	N/A	N/A	N/A		
	PA System Panel	N/A	N/A	N/A		
	Batter backup	N/A	N/A	N/A		
	Building Floor Plans	N/A	N/A	N/A		
			01 ABC type fire	MR		

The fire protection systems provided in the building were tested / checked and found functional at

In view the deemed compliance of the minimum standards on fire prevention and fire safet measures as required under the rules, the NOC issued vide letter No. F.6/DFS/MS/School/2013/SZ/994 dated 30.09.2013, renewal under the Directorate of Education circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01-03-2011 is recommended.

DFA is put up for approval & signature please

Signature of the Inspecting Officer

(M.K. CHATTOPADHYAY)

Divisional Officer, (South West)

DCFO (SZ)

157h

m.scey

F.T. letter is put up for Sign

De la

please.

F- T.

dia