GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

No. F6/DFS/MS/EH/SZ/2016) 17 47

Dated: 2/12/16

FIRE SAFETY CERTIFICATE

Certified that the Nanking Chinese Restaurant at C-6, Plot No.-6, Opp. D.P.S. Vasant Kunj, New Delhi, building comprised of Ground plus two upper floors (Restaurant running at ground, first & second floor) was granted FSC by this department vide letter No. F.6/DFS/MS/EH/2013/SZ/1126 dated 23/10/2013. The premises was re-inspected by the officer concerned of this department on 02.11.2016 in the presence of Mr. Nirbhay, (Manager) and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fir for occupancy class-D "Assembly Building" (Restaurant) with effect from 2/12/16 for a period of Three years in accordance with rule 36 unless renewed under rile 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 2/12/16 at New Delhi by

Vipin Kental Chief Fire Officer Ph.: 011-23412225

Copy to: -

- 1. M/s Nanking Chinese Restaurant at C-6, Plot No.-6, Opp. D.P.S. Vasant Kunj, ND-110070
- 2. Dy. Health Officer, MCD, South Zone, Green Park, New Delhi.
- 3. Assistant Commissioner (Restt. Branch), O/o the Commissioner of Excise, Entt. & Tax, Govt. of NCT of Delhi, L & J Block, IP Estate, Vikas Bhawan, New Delhi-110002

Conditions for the validity of Fire Safety Certificate

- 1. All the fire safety and means of escape facilities shall be maintained in good working condition at all time. Any lapse rendering the fire safety or means of evacuation facilities non-functional shall be the responsibility of the management.
- 2. Building Sanctioning authority may verify any deviation with regard to construction/occupancy in the building. In case of any deviation, the fire safety certificate stands null & void.
- 3. The staff shall be trained for operating fire fighting system and mock evacuation drill be conducted at regular interval and record be maintained.
- 4. The basement shall be used strictly as per the provisions of Building Bye Laws.
- 5. The Owner/Occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules, 2010. The form is available on www.dfs.delhigovt.nic.in.
- 6. The Owner/Occupier shall apply for renewal of this Fire Safety Certificate to the Director in the form 'J' [sub rule (1) of rule 37] along with copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in.

	INSPECTION	ON REPORT					
1	Name & Address of the Building	NANKING CHINESE RESTAURANT at C-6,					
		Plot - 6, Opp. DI	S School, Vasant Kunj, 1	New Delhi			
2	Type of Occupancy	Assembly Building "Group-D" Restaurant					
3	Building Comprised of	Ground + 02 upp					
4	Type of Case	Renewal					
5	Details of Previous NOC	F.6/DFS/MS/EH	/2013/SZ/1126 Dated 23	/10/2013			
6	Fire Safety Directives Letter No	Nil					
7	Date of Inspection	02.11.2016					
8	Name of the Inspecting Officers	ADO R.N. Singh	1				
9	Name & Designation of Officers from the	Mr. Nirbhay (Manager)					
	building side	, at ad					
10	Year of construction	Restt running at Ground, 1 st & 2 nd floor.					
11	Applicant letter No.	Nil dated 28/09/2016					
S. No	Minimum standards on Fire Prevention and Fire Safety U/R 33	Old NOC 14/12/2006	Provided at Site	Remarks MR/NMF			
1	A 4 . D	Requirements					
_1	• Road width	Accessible	6 Mts	MR			
	57.5 (America 1950) 4271 429 1 (Sp. 400) 500	N/A	N/A	N/A			
	Gate width						
	Width of internal road	N/A	N/A	N/A			
2	Number, width, type and arrangements of exits.						
	a. Number of Staircase	D 1	Tr.	MD			
	Upper floors	Required	Two	MR			
	Basement floor	N/A	N/A	N/A			
	b. Width of Staircase		T				
	Upper floors	Required	1.10 m & 0.60 m	MR "			
	Basement floor	N/A	N/A	N/A			
	c. Protection of exits	- 20	1				
	Fire check door	N/A	N/A	N/A			
	Pressurization	N/A	N/A	N/A			
	d. No. of continuous staircase to terrace	One	One	MR			
	e. Width of corridor	N/A	N/A	N/A			
	f. Door size	Required	1.10 m & 1.10 m (Final Exit)	MR .			
3	Compartmentation.	,					
	Fire check door.	N/A	N/A	N/A			
	 Sealing of electrical shafts. 	N/A	N/A	N/A			
	 Fire rating of shaft door. 	N/A	N/A	N/A			
	Water curtain	N/A	N/A	N/A			
	Fire dampers.	N/A	N/A	N/A			
4.	Smoke Management system.						
	Basement	N/A	N/A	N/A			
	Upper floors	Required	Exhaust fans provided	MR			
	Fire Extinguishers.						
5.		Eine Endingeriale	r 08 Nos.	MR			
5.	Total numbers	Fire Extinguishe					
5.	Total numbers	Fire Extinguisne	ABC-04/ W.Co2-04	MR			
5.	Total numbersTypes	ISI Marked	ABC-04/ W.Co2-04 Provided	MR MR			
	Total numbersTypesISI Marking						
5.6.	 Total numbers Types ISI Marking First Aid Hose Reels. 	ISI Marked	Provided	MR			
	Total numbersTypesISI Marking						

Renewal

Nanking Chinese Restt, C-6, Opp. DPS School, Vasant Kunj

7	Automatic Fire Detection and Alarn	ning system				
/	Type of detectors	N/A	N/A	N/A		
	 Location of Main Panel 	N/A	N/A	N/A		
	Location of Nam Fanci Location of Repeater Panel	N/A	N/A	N/A		
	Alternate source of power	N/A	N/A	N/A		
	Hooter's location	N/A	N/A	N/A		
8.	MOEFA	Required	Provided	MR		
9.		N/A	N/A	N/A		
10.	Public Address System Automatic Sprinkler System	IN/A	IN/A	IN/A		
10.	Basement	N/A	N/A	N/A		
		Required	Provided	MR		
	Upper floors Sprinkly above false seiling	N/A	N/A	N/A		
11	Sprinkler above false ceiling	IN/A	IN/A	IN/A		
11.	Internal Hydrants.	Dagwinad	100 mm mayidad	MR		
	Size of Riser / Down-comer	Required	100 mm provided			
	Number of Hydrant per floor	One	One	MR		
	Hose box.	One	One	MR		
12.	Yard Hydrants.	Tayle	127/4	1274		
	 Total number of hydrants. 	N/A	N/A	N/A		
	• 2. Hose box.	N/A	N/A	N/A		
13.	Pumping arrangements.					
	Ground Level					
	Discharge of main pump.	N/A	N/A	N/A		
	Head of main pump.	N/A	N/A	N/A		
	Number of main pumps.	N/A	N/A	N/A		
	Jockey Pump output.	N/A	N/A	N/A		
	Jockey Pump head.	N/A	N/A	N/A		
	Standby Pump output.	N/A	N/A	N/A		
	Standby Pump head.	N/A	N/A	N/A		
	Auto Starting / Manual Stoppi	ng. N/A	N/A	N/A		
	Access to pump house	N/A	N/A	N/A		
	Terrace Level					
		Fire & Jockey	450 & 180 LPM	MR		
	Discharge of pump.	Pump	respectively			
	Head of pump.	Required	35 Mtr	MR		
	Power supply.	Required	Provided	MR		
	> Auto starting of pump.	N/A	Provided	N/A		
14.	Captive water storage for Fire Fight	ing.				
	Underground tank capacity.	N/A	N/A	N/A		
	Draw-off connection.	N/A	N/A	N/A		
	Fire Service Inlet.	N/A	N/A	N/A		
	Access to tank.	N/A	N/A	N/A		
	Overhead tank capacity.	Required	5,000 Ltr	MR		
15.	Exit Signage.	Required	Provided	MR		
16.	Provision of Lifts.					
	Pressurization of lift shaft.	N/A	N/A	N/A		
	 Pressurization of lift lobby. 	N/A	N/A	N/A		
	Communication in lift car.	N/A	N/A	N/A		
	• Fireman's switch.	N/A	N/A	N/A		
	Lift signage.	N/A	N/A	N/A		
17	Standby Power Supply	Required	Provided (DG Set)	MR		
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Required	riovided (DG Set)	IVIN		
18.	Refuge Area	N/A	N/A	N/A		
	Total area					
	 Location 	N/A	N/A C-6, Opp. DPS School	N/A		



19.	Fire Control Room.			
	Detector System Panel.	N/A	N/A	N/A
	Flow Switch Panel.	N/A	N/A	N/A
	PA system Panel.	N/A	N/A	N/A
	Battery backup	N/A	N/A	N/A
	Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for the	N/A	N/A	N/A
	Protection of special Risk, if any:			

The Fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F.6/DFS/MS/EH/2013/SZ/1126 Dt. 23/10/2013, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

: R.N. Singh Name Designation: ADO

Renewal

Nanking Chinese Restt, C-6, Opp. DPS School, Vasant Kunj

Div. Officer (SD)

Spoken with ADORNS