GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI- 110001

No. F-6/PFS/MS/2016/NDZ/1763

Dated: 7-12-16

FIRE SAFETY CERTIFICATE

Certified that the Cross River Mall at plot no. 9B & 9C,CBD Shahdra, Delhi-32, owned/occupied by M/s STC Developers Pvt. Ltd., comprised of two basements, granted vide letter upper floors was ground plus three F6/MS/DFS/2013/NDZ/1259 dated-28/11/13. The Multiplex building was re-inspected by the team of officer concerned of this department on 05.12.2016 in the presence of Sh. Manoj Sharma (Mall Manager) and found that the Multiplex building have deemed complied with the fire prevention and fire safety requirements in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and that the building is fit for occupancy Group "Multiplex Building" with effect from for a period of three years, subject to conditions printed overleaf.

Issued on at New Delhi by

Chief Fire Officer

Delhi Fire Service

To,

M/s STC Developers Pvt. Ltd Cross River Mall Plot no.9B & 9C,CBD, Shahdra,Delhi -110032.

CONDITIONS:

- 1. All the means of escape shall be kept free of all the type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
- 5. This Fire Safety Certificate can not be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 6. All comments/ directions of the Licensing Department shall always be permitted and followed.
- 7. The owner /occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry"
- 8. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

1. Name & address of the building: Cross River Mall at plot no. 9B & 9C,

CBD, Shahdara, Delhi-32.

2. Building is comprised of : 2 Basement, ground+ three upper floors

3. Type of Occupancy : Multiplex (Mall)

4. Type of Case : Renewal

5. Details of Previous FSC letter : F6/MS/DFS/2013/NDZ/1259 dated-

28/11/13

6. Fire safety direction letter No. : F6/MS/DFS/BP/2004/1629 dated-

27/07/04

7. Date of Inspection : Q3.12. 20168. Name of the Inspecting officers : ADO R.K. Yadav

9. Name and designation of

Officer from the building side : Sh. Manoj Sharma (Manager)

10. Year of Construction : 2006

11. Applicant's letter No : Dated 28/11/16

S	Minimum Standards on fire	NBC & BBL	Provided at Site	Remark			
1	prevention and fire safety U/R33	Requirement					
	Access to building						
	Road width	12 M	24 M	MR			
	Gate width	4.5 M	07 M	MR			
	Width of internal road	06 M	06 M	MR			
2	Number, Width, Type and Arrangement of Exits						
	a. Number of Staircases						
	Upper Floor	11 Nos.	13 Nos.	MR			
	Basement	11 Nos.	13 Nos+2 ramp	MR			
	B. Width of Staircases	9					
and the second	 Upper Floor 	1.5 M	1.5 M& 2.0 M	MR			
	Basement	1.5 M	1.5 M& 2.0 M	MR			
and the contract of the contra	c. Protection of exits						
	Fire check door	Required	Provided	MR			
	Pressurization	Required	Provided	MR			
	e. No. of continuous staircases to terrace	04 Nos	06 Nos	MR			
	g. Width of Corridor	2.0 M	2.5 M	MR			
	h. Door Size	1.25 M	1.0 M & 1.25 m	MR			
3 Compartmentation.							
	Fire check door	Required	Provided	MR			
	 Sealing of electrical shafts 	Required	Provided	MR			
	Fire rating of shaft door	02 hrs.	02 hrs.	MR			
	Water curtain	N/A	N/A	N/A			
100	Fire Dampers	Required	Provided	MR			
1	Smoke Management System.						
T	Basement	Required	Provided	MR			
	Upper floor	Required	Provided	MR			
	Fire Extinguishers						
	Total numbers	120 Nos.	140 Nos.	MR			
-	• types	ABC & Co2	ABC & Co2	MR			
	IS marking	ISI marked	ISI marked	MR			

NIS

5	First-aid-Hose Reels. Total numbers of each floor	06 Nos	Provided	MR		
	 Length of hose reel hose 	30 M	Provided	MR		
	Nozzle diameter	05 mm	Provided	MR		
	Automatic fire detection and alarming system.					
		Heat & Smoke	Provided	MR		
		Control room	Provided	MR		
	Location of main panel	Security room	Provided	MR		
	Location of repeater panelAlternate source of power	Battery & DG Set	Provided	MR		
	Hooter's location	Staircase	Provided	MR		
8	MOEFA	Required	Provided	MR		
9	Public address System.	Required	Provided	MR		
10	Automatic Sprinkler System.					
10	Basement	Required	Provided	MR		
	8	Required	Provided	MR		
	upper floor sprinkler above false ceiling	Required	Provided	MR		
44						
11	Internal Hydrants • size of riser/down-comer	150mm	Provided	MR		
	Number of hydrants per floor	06 Nos.	Provided	MR		
1	Hose Box	06 Nos.	Provided	MR		
12	Yard Hydrants.			145		
	 Total number of hydrants 	11 Nos.	13 Nos.	MR		
	Hose Box	11 Nos.	13 Nos.	MR		
13	Pumping Arrangements.			1.45		
	Ground Level	Required	Provided	MR		
	Discharge of main Pump	2850 Lpm	2850 Lpm	MR		
	Head of Main Pump	60 M	60 M	MR		
	Number of main pumps	2 Nos.	2 Nos.	MR		
	Jockey pump out put	180 Lpm	2 No of 180 Lpm	MR		
	Jockey pump head	60M	60M	MR		
Land english (Artist	Standby pump out put	2850 Lpm	2850 Lpm	MR		
	Standby pump Head	60 M	60 M	MR		
	 Auto Starting /Manual stopping 	Required	Auto	MR		
	Pump House Access	Required	Provided	MR		
	Terrace Level		B.1/A	B1/A		
	Discharge of pump	N/A	N/A	N/A		
	Head of the Pump	N/A	N/A	N/A		
	> Power supply	N/A	N/A	N/A		
	> Auto Starting of pump	N/A	N/A	N/A		
14	Fighting.		0.00.00014	MF		
	 Underground tank capacity 	2,00,000 Ltrs	2,00,000 Ltrs			
	Draw-off connection	Required	Provided	MF		
	> Fire service inlet	Required	Provided	MF		
-	> Access to tank	Required	Provided	MF		
	Overhead Tank capacity	50,000Ltrs	50,000Ltrs	MF		
-	Exit Signage.	Required	Provided	MF		

16	Provision of Lifts.				
1	 Pressurization of Lift Shaft 	Required	Provided	MR	
	 Pressurization of Lift lobby 	Required	Provided	MR	
	Communication in lift car	Required	Provided	MR	
	Firemen's grounding switch	Required	Provided	MR	
	Lift Signage	Required	Provided	MR	
17	Standby power supply	Required	Provided	MR	
18	Refuge Area.				
	Total area	N/A	N/A	N/A	
	Location	N/A	N/A	N/A	
19	Fire Control Room				
	 Detector system panel 	Required	Provided	MR	
	 Flow switch panel 	Required	Provided	MR	
	 PA system panel 	Required	Provided	MR	
	Battery backup	Required	Provided	MR	
	 Building Floor Plans 	Required	Provided	MR	
20	Special Fire Protection systems for protection of special Risks, if any:	Required	Provided in all LT & HT Panels	MR	

The inspection was carried out to check the shortcomings issued vide letter no. F.6/DFS/MS/2016/2791 dated 02/12/2016. The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules. The Fire Safety Certificate issued vide letter no. F6/MS/DFS/2013/NDZ/1259 dated-28/11/13 renewal under rule 35 of the Delhi Fire Service Rule 2010 is recommended.

Signature of the Inspecting Officer

Name: R. K. Yadav

DOLED

Designation: ADO (LN)

Submitted pl.

Defo (NOSZ)

M 5/12