GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DLEHI - 110 001

No. F.6/DFS/MS/FH/2016/SZ/ 1768

Dated: 08 12 16

FIRE SAFETY CERTIFICATE

Certified that the Ram Farms (M/s Glamor Impex Pvt. Ltd.) Kh. No. 683, 685, 686/1 & 711, Bund Road, Village Gadaipur, New Delhi-110074 comprised of ground floor & First Floor has already been issued FSC by this department vide letter No. F6/MS/DFS/FH/2013/SZ/966 Dated 25/09/2013. The Farm House was re-inspected by the officer concerned of this department on 01/12/16 in the presence of Mr. Mathur & found to have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building is fit for occupancy class D "Assembly Building Farm House" with effect 32 (72)--2016 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010.

(Vipin Kental) Chief Fire Officer Ph:-011-23412235

Copy to:-

1. The Assistant Engineer (Bldg)-II, SDMC, South Zone, Green Park, New Delhi.

2. The Authorized Signatory, Ram Farms (M/s Glamor Impex Pvt. Ltd.), Kh. No. 683, 685, 686/1&711, Bund Road, Village Gadaipur, New Delhi-110074

Conditions for the validity of fire safety certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of firefighting system.

4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.

5. This fire safety certificate may not in any way be treated as regularization of unauthorized

construction, if any.

6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

INSPECTION REPORT 1. Name & address of the building: Ram Farms (M/s Glamor Impex Pvt. Ltd.) Kh. No. 683, 685, 686/1&711, Bund Road, Village Gadaipur, New Delhi-110074 : Group A "Assembly" Building(farm House) Type of Occupancy 2. : Renewal [GF+1st F] : F6/MS/DFS/FH//2013/SZ/966 Dated 25/09/2013 3. Type of Case 4. Details of Previous NOC 5. Fire Safety directives letter No : NIL : 01/12/2016 6. Date of inspection : A.K. Malik. 7. Name of Inspecting Officer 8. Name and designation of officers : Mr. Mathur From the building side : NIL 9. Year of Construction : Nil dated 28.10.2016, outdoor diary no. 11199 dated 28/10/16 10. Applicant's letter No. Remarks Provided at site Old NOC Minimum Standards on fire prevention MR/NMR S. (11-02-2010)and fire safety U/R 33 No Requirement Access to building MR 1. 24m Required Road width MR 4.5m Required -NA-Gate width 6m -NA-Width of internal road Number, Width, Type & Arrangement of Exits 2. a. Number of staircases MR One Required Upper Floors -NA--NA--NA-**Basements** b. Width of staircases MR(Old 0.95mRequired Case) Upper Floor -NA--NA--NA-Basements c. Protection of exits -NA--NA-Fire check door -NA--NA--NA--NA-Pressurization d. No. of continuous staircases to terrace MR One Required NA NA e. Width of Corridor NA NA 1m (Final Exit) NA Door Size Compartmentation 3. -NA--NA--NA-Fire check door -NA--NA--NA-Sealing of electrical shafts -NA--NA-Fire Rating of shaft door -NA--NA--NA--NA-Water Curtain -NA--NA--NA-Fire Dampers Smoke Management System 4. -NA--NA--NA-**Basements** MR Natural ventilation 12 ACPH Upper floors Fire Extinguishers 5. MR Total 26 No's (non-Total numbers functional) Portable Fire MR ABC-16 No's, Types Extinguishers W.Co₂&Co₂-10 No's MR Yes IS marking First-Aid Hose Reels 6. MR One Total numbers on each floor MR 30m Hose Reels Length of hose reel hose MR 5mm Nozzle diameter Automatic fire detection and alarming system 7. -NA--NA--NA-Type of detectors -NA--NA--NA-Location of Main Panel -NA--NA-Location of Repeater Panel -NA-

Ram Farms, Kh. No. 665, 665, 666, 147, 11,

		Ram Parms, 18th 1960	Required	Provided	MR
3.	MOEI		-NA-	-NA-	-NA-
).	Public	Address System	-IVA-		
0.	Automatic Sprinkler System		-NA-	-NA-	-NA-
	•	Basement	-NA-	-NA-	-NA-
	•	Ground Floor	-NA-	-NA-	-NA-
	•	Sprinkler above false ceiling	-1477		
11.	Interr	nal Hydrants	-NA-	-NA-	-NA-
	•	Size of riser/down-comer	-NA-	-NA-	-NA-
	•	Number of hydrants per floor	-NA-	-NA-	-NA-
	•	Hose Box			
12.	Yard	Hydrants	Required	4 No's provided	MR
	•	Total number of hydrants	Required	4 No's provided	MR
	•	Hose Box	Required		***
13.	Pumping Arrangements				
	•	Ground Level	-NA-	-NA-	-NA-
		Discharge of main Pump	-NA-	-NA-	-NA-
		Head of Main pump	-NA-	-NA-	-NA-
		Number of main pumps	-NA-	-NA-	-NA-
		Jockey Pump out put		-NA-	-NA-
		> Jockey pump head	-NA-	-NA-	-NA-
	-	Standby Pump out put	-NA-	-NA-	-NA-
		> Standby Pump Head	-NA-		-NA-
*		> Auto Starting/Manual Stopping	-NA-	-NA-	-NA-
		> Pump House Access	-NA-	-NA-	-INA-
) (D
	1	Terrace levelDischarge of pump	Boosting	450 & 180 LPM	MR
		Head of the pump	Required	46m& 30m	MR MR
		> Power Supply	Required	Provided	MR
		> Auto Starting of pump	Required	Provided	IVIIX
		W. A. Starage for fire fighting	2		5
14	I. Ca	ptive Water Storage for fire fighting	-NA-	-NA-	-NA-
		Underground tank capacity	-NA-	-NA-	-NA-
	-	> Draw-off connection		Provided	MR
		> Fire service inlet	Required -NA-	-NA-	-NA-
		> Access to tank	5,000 & 2,500 Lts		MR
		Overhead Tank capacity	Required	Provided	MR
1		it Signage.	Required		
10	6. Pr	ovision of Lifts.	NT A	-NA-	-NA-
		 Pressurization of Lift Shaft 	-NA-		-NA-
		 Pressurization of Lift lobby 	-NA-	-NA-	-NA-
		• Communication In lift Car	-NA-		-NA-
		Fireman's Grounding Switch	-NA-	-NA-	
		Lift Signage	-NA-	-NA-	-NA-
-	15 0	tandby power supply	Required	Provided	MR
-		Lefuge Area.			NTA
-	18. R	> Total Area	-NA-	-NA-	-NA-
		> Location	-NA-	-NA-	-NA-
+	19. F	Fire Control Room		271	-NA-
	17.	Detector System Panel	-NA-	-NA-	
		Flow Switch Panel	-NA-	-NA-	-NA-
			-NA-	-NA-	-NA-
		PA System Panel	-NA-	-NA-	-NA-
		Battery backup	-NA-	-NA-	-NA-
		Building Floor Plans		Dicks if any:	-NA-

Ram Farms, Kh. No. 683, 685, 686/1&711, Bund Road, Village Gadaipur, New Delhi-110074

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection. The shortcomings communicated vide letter no F6/DFS/MS/FH/2016/SZ/2616 dated 04/11/16 found complied.

Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, It is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Accordingly FSC in shape of DFA is put up for approval.

Signature of Inspecting Officer

Name: A. K. Malik Designation: DO (SD)

