## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/Hospital/2016/SZ | 1765

Dated: 07/12/16

## FIRE SAFETY CERTIFICATE

Certified that the **Sardar Vallabh Bhai Patel Hospital**, Patel Nagar, New Delhi comprised of ground floor plus three upper floors, owned/occupied by Govt. of NCT of Delhi was issued NOC by this department vide letter F6/DFS/MS/HQ/2012/4395 dated 27.11.2012. The Hospital building was re-inspected by the officers concerned of this department on 27.10.2016 in the presence of Dr. Rajeev Kapoor (Medical Superintendent) and found that Sardar Vallabh Bhai Patel Hospital have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class Group-C "Institutional Building" Sub. Div. C-1 w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed as below.

(VIPIN KENTAL)
CHIEF FIRE OFFICER

Copy to:-

Medical Superintendent, Sardar Vallabh Bhai Patel Hospital, Patel Nagar, New Delhi

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape arrangements shall be kept unlocked & unobstructed for speedy evacuation of occupants in case of an emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

14.	. 1-1	INSPECTION	REPORT		*
	<ol> <li>Type of Occ</li> <li>Type of Cas</li> <li>Details of Properties</li> <li>Fire Safety of Date of Inspose</li> <li>Name of Inspose</li> <li>Name and description</li> <li>Year of Con</li> <li>Applicant's</li> </ol>	: Renewal revious NOC : F6/DFS/MS/ directives letter No : F6/MS/DFS/F ection : 27.10.2016 pecting Officer : D.O. M.K. C esignation of officers uilding side : Dr. Rajeev K struction : 2001-2002	oh Bhai Patel Hospi Building (Hospital) HQ/2012/4395 date Hospital/2001/1152 hattopadhyay & A.: apoor (Medical Su 6-17/SVBPH/PWD NBC/BBL	ed 27.11.2012 dated 15.6.2001 D.O. Sandeep Dug	gal
No.	safety U/R 33		Requirement	site	MR/NMR
1.	Access to buil	ding			
2.			12 mtrs. 05 mtrs. N/A	12 mtrs 05 & 4.8 mtrs. N/A	MR MR N/A
	N. I. C		1		
	5.05	staircases r Floors nents	03 No.'s	03 No.'s & 01 No. ramp	MR
	b. Width of st	i e	N/A	N/A	N/A
		r Floor nents	200 cms	200 cms X 03 no.'s & 223 cms ramp from GF to FF	MR
	• Basel	nents	N/A	N/A	N/A
			3		
	Protection of e	xits	Required	Provided	MR
	- N	heck door	N/A	N/A	N/A
	• Press	urization	11/11	11/12	1 1/11
	d. No. of con	tinuous staircases to			
	terrace	×	Required	Two	MR
	Wild Co		N/A	240 cms	N/A
	e. Width of C	orridor	N/A	140 cms	N/A
3.	f. Door Size Compartmenta	rtion ,			300 3370 33
5,	Comparement				
		neck door	Required	Provided	MR
		g of electrical shafts ating of shaft door	Required	Provided	MR
		Curtain	02 Hour	Provided	MR
		ampers	N/A	N/A	N/A
4	Smoles Man-	amant Systam	N/A	N/A	N/A
4.	Smoke ivianag	ement System			
	Basen	ents	N/A	N/A	N/A
	Upper	floors	Required	Natural Ventilation	MR
5.	Fire Extinguis	ners		,	
		numbers	12 no's/floor ABC/CO <sub>2</sub> /WCO <sub>2</sub>	Provided	MR
	• Types		ABC/CO <sub>2</sub> /WCO <sub>2</sub>	Provided	MR
	• IS ma		ISI marked	ISI marked	MR
6.	First-Aid Hose		02 no 20/E10	Provided	MR
	A CONTRACTOR OF THE CONTRACTOR	numbers on ground floor h of hose reel hose	02 no.'s/Floor 30 mtrs	Provided Provided	MR
		e diameter	5 mm	Provided	MR
	TAUZZI		J 111111	TIOVIGOU	11111

	Automatic fire detection and alarming system						
	Type of detectors	Smoke & Heat	Provided	MR			
	<ul> <li>Location of Main Panel</li> </ul>	N/A	N/A	N/A			
	<ul> <li>Location of Repeater Panel</li> </ul>	N/A	N/A	N/A			
	Alternate source of power	Required	Provided	MR			
	Hooters' Location	N/A	N/A	N/A			
•	MOEFA	Required	Provided	MR			
	Public Address System	Required	Provided	MR			
0.	Automatic Sprinkler System						
•	Basement	N/A	N/A	N/A			
	Ground Floor	N/A	N/A	N/A			
	<ul> <li>Sprinkler above false ceiling</li> </ul>	· N/A	N/A	N/A			
1.	Internal Hydrants		100 7 0	I (D			
	<ul> <li>Size of riser/down-comer</li> </ul>	Required	100 MM	MR			
	<ul> <li>Number of hydrants</li> </ul>	Required	Two	MR			
	Hose Box	Required	Two	MR			
2.	Yard Hydrants						
	Total number of hydrants	N/A	Two	N/A			
	Hose Box	N/A	Two	N/A			
3.	Pumping Arrangements						
<i>.</i>	Ground Level						
	The state of the s	2850 LPM	Provided	MR			
	Discharge of main Pump	60 mtrs	Provided	MR			
	Head of Main pump	One	Provided	MR			
	Number of main pumps	220 LPM	Provided	MR			
	Jockey Pump out put	60 mtrs	Provided	MR			
	Jockey pump head	2850 LPM	Provided	MR			
	Standby Pump out put	60 mtrs	Provided	MR			
	Standby Pump Head	Required	Provided	MR			
	Auto Starting/Manual Stopping Pump House Access	Required	Provided	MR			
	• Terrace level	N/A	N/A	N/A			
	Discharge of pump Head of the pump	N/A	N/A	N/A			
	Power Supply	N/A	N/A	N/A			
	Auto Starting of pump	N/A	N/A	N/A			
4.	Captive Water Storage for fire fighting		4				
	Underground tank capacity	50000 ltrs	Provided	MR			
	Draw-off connection	Required	Provided	MR			
	Fire service inlet	Required	Provided	MR			
	Access to tank	Required	Provided	MR			
	<ul> <li>Overhead Tank capacity</li> </ul>	20000 ltrs	Provided	MR			
		Required	Provided	MR			
5.	Exit Signage.	Required	Tiovided				
6	Provision of Lifts.						
6.	Provision of Lifts.     Pressurization of Lift Shaft	N/A	N/A	N/A			
	Pressurization of Lift lobby	N/A	N/A	N/A			
	Communication In lift Car	N/A	N/A	N/A			
	Fireman's Grounding Switch	Required	Provided	MR			
	Lift Signage	Required	Provided	MR			
		Required	Provided	MR			
17.	Standby power supply	Daggerand	Provided	IV/I RC			

)	to the second se			
).	Fire Control Room	Required	Provided	MR
	Detector System Panel	N/A	N/A	N/A
	Flow Switch Panel	Required	Provided	MR
	PA System Panel	Required	Provided	MR
	<ul><li>Battery backup</li><li>Building Floor Plans</li></ul>	N/A	N/A	N/A
0	Special Fire Protection System for Protection of	N/A	N/A	N/A
0.	special Risks, If any:			

The fire protection systems provided in the building were checked, found functional at the time of inspection.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the NOC issued vide letter No. F6/DFS/MS/HQ/2012/4395 dated 27.11.2012, renewal under rule 37 of the Delhi Fire Service rules 2010 is recommended.

Note:- Status of shortcomings issued vide letter no. ADO/JKP/103 dated 16.3.2016 is mentioned below:-

- 1. Automatic fire detection and alarm system is not functional:- Complied
- 2. Illuminated Exit signs are not functional at number of places:- Complied
- Emergency lights are missing at number of places:- Complied

Floor marking is not visible at number of places:- Complied

Signature of Inspecting Officer

Name: - M.K. Chattopadhyay

Designation:- Divisional Officer

Signature of Inspecting Officer

Name:- Sandeep Duggal

Designation:- Assistant Divisional Officer

Dy.C.F.O.(South Zone)

M. SCELL LY JII

F. T. Loker is Dut up for signature please

Sounded

M. SCELL LIZE

M. SCELL LIZE

M. SCELL LIZE

M. SCELL LY 2/12