## GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

No. F6/DFS/MS/2016/SZ/ <sub>しつつつ</sub>

Dated: 09/12/16

## FIRE SAFETY CERTIFICATE

Certified that the JSS Spiritual & Cultural Centre, Plot No. 18 & 19, Sector-VI, Pushp Vihar, Saket, New Delhi, comprised of Basement, Ground + 03 upper floors Owned/Occupied by Jagadguru Sri Veerasimhasana Math was granted FSC by this department vide letter No. F6/MS/DFS/2013/74 dated 14.03.2013. The premises was re-inspected by the officer concerned of this department on 11.11.2016 in the presence of Prof. Nagraj M (Manager) and found that the said building/premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fir for occupancy class "Assembly Building, Group-D" (Spiritual Education cum Residential) with effect from 69 12 2016 for a period of Three years in accordance with rule 36 unless renewed under rile 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on OS 12/16 at New Delhi by

Vipin Kental Chief Fire Officer Ph.: 011-23412225

Copy to: -

1. The Manager, JSS Spiritual & Cultural Centre, Plot No. 18 & 19, M.B. Road, Sector.-VI, Saket, New Delhi-110017

2. The Executive Engineer (Bldg.), Building Department, S.D.M.C, Civic Center, Minto Road, New Delhi-110002

## Conditions for the validity of Fire Safety Certificate

- 1. All the fire safety and means of escape facilities shall be maintained in good working condition at all time. Any lapse rendering the fire safety or means of evacuation facilities non-functional shall be the responsibility of the management.
- 2. Building Sanctioning authority may verify any deviation with regard to construction/occupancy in the building. In case of any deviation, the fire safety certificate stands null & void.
- 3. The staff shall be trained for operating fire fighting system and mock evacuation drill be conducted at regular interval and record be maintained.
- 4. The basement shall be used strictly as per the provisions of Building Bye Laws.
- 5. The Owner/Occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules, 2010. The form is available on www.dfs.delhigovt.nic.in.
- 6. The water capacity of 50,000 Ltr shall always remain available in the swimming pool for firefighting purpose all the time.
- 7. The Owner/Occupier shall apply for renewal of this Fire Safety Certificate to the Director in the form 'J' [sub rule (1) of rule 37] along with copy of this certificate, six months prior to its expiry. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>.

	INCDECTI	ON REPORT			
1	Name & Address of the Building		Cultural Centre Sri	Suttur Bhawan	
1	Name & Address of the building	JSS Spiritual & Cultural Centre, Sri Suttur Bhawan, Plot No-18 &19, Sec-VI, Pushp Vihar, Saket, ND-17			
2	Type of Occupancy	Assembly Buildi		Saket, ND-17	
2	Type of Occupancy				
2	Duilding Commissed of	(Spiritual Education cum Residential)  Basements, Ground plus three upper floors			
3	Building Comprised of	Renewal	ind plus three upper fic	0018	
	Type of Case  Details of Previous NOC		3/74 dated 14.03.2013	•	
5					
6	Fire Safety Directives Letter No	F.6/DFS/MS/BP/2007/2869 dated 04.10.2007			
7	Date of Inspection	11/11/2016			
8	Name of the Inspecting Officers	ADO R.N. Singh			
9	Name & Designation of Officers from the building side	Prof. Nagraj M (Manager)			
10	Year of construction	2012			
11	Applicant letter No.	ATN/ire/Sake/15	-16/2 Dt. 14.10.2016		
S. No	Minimum standards on Fire			Remarks	
	Prevention and Fire Safety U/R 33	Dt. 14/03/2013		MR/NMR	
		requirements			
1	Access to Building.				
	Road width	12 Mts.	12 Mts.	MR	
	2. Gate width	Required	5 Mts.	MR	
	3. Width of internal road	NA	NA.	NA	
2	Number, width, type and arrangements	of exits.	Application of the second seco		
18	a. Number of Staircase				
	Upper floors	Two	Two	MR	
	2. Basement floor	Two	Two	MR	
	b. Width of Staircase	1 WO	1 110	IVIIC	
	1. Upper floors	Required	1.20m & 1.08m	MR (old case)	
	2. Basement floor	Required		MR (old case)	
	c. Protection of exits	required	1.2011 & 1.0011	iviix (old case)	
	1. Fire check door	Required	Provided	MR	
	2. Pressurization	NA	NA	NA	
	d. No. of continuous staircase to terrace	Two	Two	MR	
		NA NA			
	e. Width of corridor		NA 1.25	NA	
	f. Door size	1.25 m	1.25 m	MR	
3	Compartmentation.	NTA.	NTA.	274	
	1. Fire check door.	NA	NA	NA	
	2. Sealing of electrical shafts.	Required	Provided	MR	
	3. Fire rating of shaft door.	NA	NA	NA	
	4. Water curtain	NA	NA	NA	
4	5. Fire dampers.	Yes	Provided	MR	
4.	Smoke Management system.  1. Basement	Dagwinad	Exhaust for mayida	4 MD	
	- NOT TO DECEMBER AND THE PROPERTY OF THE PROP	Required	Exhaust fan provided		
-	* *	Required	Exhaust fan provided	u   IVIR	
5.	Fire Extinguishers.	Г:	25 N	MD	
	1. Total numbers	Fire	25 Nos.	MR	
	2. Types	Extinguisher	W. Co2- 20, Co2- 05		
	3. ISI Marking	ISI Marked	Yes	MR	
6.	First Aid Hose Reels.	T	T_		
	Total numbers on each floor.	Hose reel	Two	MR	
	2. Length of hose-reel hose.		30 m	MR	
	3. Nozzle Diameter		05 mm	MR	
Renewal		JSS Spiritual & Cultural Centre, Saket.			

7 A	utomatic Fire Detection and Alarming s			1.00			
	Type of detectors	Required	Smoke	MR			
	2. Location of Main Panel	Required	Basement	MR			
	3. Location of Repeater Panel	Required	Basement	MR			
	4. Alternate source of power	Required	DG Set	MR			
	5. Hooter's location	Required	Every floor	MR			
8. M	IOEFA	Required	Provided	MR			
9. Pt	ublic Address System	NA	NA	NA			
0. A	Automatic Sprinkler System						
	1. Basement	Required	Provided	MR			
	2. Upper floors	NA	NA	NA			
	3. Sprinkler above false ceiling	NA	NA	NA			
1. In	Internal Hydrants.						
	1. Size of Riser/Down-comer	Required	150 mm	MR			
	2. Number of Hydrant per floor	Required	2 Nos.	MR			
	3. Hose box.	Required	2 Nos.	MR			
2. Y	Yard Hydrants.						
	Total number of hydrants.	Required	5 Nos.	MR			
	2. Hose box.	Required	5 Nos.	MR			
3. P	umping arrangements.						
a							
	Discharge of main pump.	2280 LPM	2280 LPM	MR			
	<ul><li>Head of main pump.</li></ul>	70 mtr	70 mtr	MR			
	<ul><li>Number of main pumps.</li></ul>	One	One	MR			
	> Jockey Pump output.	180 LPM	180 LPM	MR			
	Jockey Pump head.	60 m	60 m	MR			
	Standby Pump output.	2280 LPM	2280 LPM	MR			
	Standby Pump head.	70 mtr	70 mtr	MR			
	> h) Auto Starting/Manual Stopping.	Required	Provided	MR			
b)	b) Terrace Level						
	Discharge of pump.	900 LPM	900 LPM	MR			
	<ul><li>Head of pump.</li></ul>	40 mtr	40 mtr	MR			
	> Power supply.	Required	Provided	MR			
	<ul><li>d) Auto starting of pump.</li></ul>	N/A	NA	NA			
4. C	Captive water storage for Fire Fighting.						
	1. Underground tank capacity.	Required	50000 Ltr.	MR			
	2. Draw-off connection.	NA	Provided	MR			
	3. Fire Service Inlet.	Required	Provided	MR			
	4. Access to tank.	NA	Provided	MR			
	<ol> <li>Overhead tank capacity.</li> </ol>	10,000 Ltr.	10,000 Ltr.	MR			
15. E	exit Signage.	Required	Provided	MR			
	Provision of Lifts.	1					
1	1. Pressurization of lift shaft.	NA	NA	NA			
	2. Pressurization of lift lobby.	NA	NA	NA			
	3. Communication in lift car.	Required	Provided	MR			
	4. Fireman's switch.	Required	Provided	MR			
	5. Lift signage.	Required	Provided	MR			
17		Required	DG Set Provided	MR			
	standby Power Supply	Required	DO SEL LIVINEU	1411			
18. R	Refuge Area	NA	NA	NA			
	1. Total area	NA NA	NA NA	NA NA			
	2. Location		JSS Spiritual & Cultural				

19.	Fire Control Room.		S. C.	
	Detector System Panel.	Required	Provided	MR
	2. Flow Switch Panel.	NA	NA	NA
	3. PA system Panel.	NA	NA	NA
•	<ul><li>4. Battery backup</li><li>5. Building floor plan</li></ul>	Required	Provided	MR
		NA	NA	NA
20.	Special Fire Protection System for t	the Protection of specia	al Risk, if any:	NA

The Fire protection systems provided in the building were checked and found functional at the time of inspection. The shortcomings communicated vide letter no. F.6/DFS/MS/2016/977 dated 18.04.2016 have been rectified.

In view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the Fire Safety Certificate issued vide letter No. F.6/DFS/MS/2013/74 dated 14.03.2013, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name : R.N. Singh

Designation: ADO

Renewal

JSS Spiritual & Cultural Centre, Saket.

v Officer (SD)

Div. Officer (SD)

DO(5)47/ 25/11/16

Disay 1275 68

426 cho 52

Dy (Ro (52)

26/4

Ct.o.Col

FTM

migcell le 28/11