## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI- 110001

No. F6/OFS/ans/Honkidal/2015/402/2117 Dated: 0

Dated: 01/12/15

## FIRE SAFETY CERTIFICATE

Certified that the Deepak Memorial Hospital at 5,6 Institutional Area, Vikas Marg Extn., Delhi-92 ,owned/occupied by M/s Deepak Gupta Memorial Foundation ,comprised of ground certificate fire safety upper floor was granted no.F6/DFS/MS/Hospital/2012/3852 dated 17.10.12.The Hospital building was inspected by the officers concerned of this department on 04.11.15 in the presence of Dr.Atish Sinha (MS) and found that the Hospital building have deemed complied with the fire prevention and fire safety requirements in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 and that GF+FF+SF+TF of the building is fit for occupancy Group C " Institutional Building" with overleaf.

(Dr.G.C.Misra) Chief Fire Officer 011-23414333

Reefy V

To,

Dr.Atish Sinha (Medical Superintendent) Deepak Memorial Hospital 5,6 Institutional Area,Vikas Marg Extn., Delhi-92

## CONDITIONS:

1. All the means of escape shall be kept free of all type of obstruction all the time.

2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.

3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall

be responsible.

4. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned

5. This Fire Safety certificate can not be treated in any case for regularizations of

unauthorized if any.

6. "The owner /occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form'J'[sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry"

7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on

www.dfs.delhigovt.nic.in

1. Name & address of the building: Deepak Memorial Hospital at 5,6 Institutional Area,

Vikas Marg Extn., Delhi-92

2. Building is comprised

: Ground +3, upper floors.

3. Type of Occupancy

: Institutional (Hospital)

4. Type of Case

: Renewal

5. Details of Previous FSC

:F.6/DFS/MS/Hospital/2012/3852 Dated 17.10.12

6.Fire Safety direction letter No :F.6/MS/DFS/BP/2004/644 dated 24/03/2004

7. Date of Inspection

: 04/11/15

8. Name of the Inspecting officers : DO Virendra Singh & ADO Suresh Singh

9. Name and designation of Officer:

from the building side

: Dr.Atish Sinha (MS)

10. Year of Construction

: 1985 & 2004

11. Applicant's letter:

: 11.09.15

S.NO.	Minimum Standards on fire prevention and fire safety U/R33	Requirement	Provided at Site	Remarks MR/NMR
1	Access to building			
*	Road width	12 Mtrs.	30 Mtrs.	MR
	Gate width	4.5 Mtrs.	4.5 Mtrs.	MR
	Width of internal road	4.5 Mtrs.	5.0 Mtrs.	MR
2	Number, Width, Type and Arrangement of	Exits		
	a. Number of Staircases			
	Upper Floor	2 nos.	3 nos.	MR
	Basement	N/A	N/A	N/A
	B. Width of Staircases			
	Upper Floor	2.0 Mtrs.	2.0 Mtrs., 1.4 Mtrs.& .90 Mtrs.	MR Y
	Basement	N/A	N/A	N/A
	c. Protection of exits			
	Fire check door	N/A	N/A	N/A
	<ul> <li>Pressurization</li> </ul>	N/A	N/A	N/A
	e. No. of continuous staircases to terrace	1no.	3 nos.	MR
	g. Width of Corridor h. Door Size	1.9 Mtrs.	1.9 Mtrs.	MR
		1.0 Mtr.	1.9 Mtr.	MR
3	Compartmentation.	1.0 10101.	1.0 With	14/11
3		N/A	N/A	N/A
	Fire check door  Continue of all attrices shorts	Required	sealed	MR
	Sealing of electrical shafts  Size ratios of shaft door.	N/A	N/A	N/A
	Fire rating of shaft door	N/A	N/A	N/A
	Water curtain     Fire Democra	·		
	Fire Dampers	N/A	N/A	N/A
4	Smoke Management System.	T /-	1 21/2	N1 / A
	<ul> <li>Basement</li> </ul>	N/A	N/A	N/A
	Upper floor	N/A	Natural	MR
			Ventilation	
5.	Fire Extinguisher	1	FON	NAD
	Total numbers	15 Nos.	50 Nos.	MR
	Types	ABC & Co2	ABC & Co2	MR
	IS marking	ISI marked	ISI marked	MR

Mild accepted in parlier

	Tabel f f f	01 nc	01 no	MR			
	<ul><li>Total numbers of each floor</li><li>Length of hose reel hose</li></ul>	01 no.	01 no.	IVIK			
	Nozzle diameter	30 m	30 m	MR			
	NOZZIG GIGITICECT	5 mm	5 mm	MR			
	Automatic fire detection and alarming system.						
	Type of detectors	N/A	N/A	N/A			
	Location of main panel	N/A	N/A	N/A			
	<ul> <li>Location of repeater panel</li> </ul>	N/A	N/A	N/A			
	<ul> <li>Alternate source of power</li> </ul>	N/A	N/A	N/A			
	Hooters's location	N/A	N/A	N/A			
	MOEFA	Required	Provided	MR			
	Public address System.	Required	Provided	MR			
0	Automatic Sprinkler System.						
8	Basement	N/A	N/A	N/A			
	upper floor	N/A	N/A	N/A			
	sprinkler above false ceiling	N/A	N/A	N/A			
1	Internal Hydrants						
	size of riser/down-comer	100 mm	100 mm	MR			
	Number of hydrants per floor	01 No.	01No.	MR			
	Hose Box	01 No.	01 No.	MR			
2	Yard Hydrants.						
	Total number of hydrants	N/A	Provided	MR			
	Hose Box	N/A	Provided	MR			
3	Pumping Arrangements.						
-1	Ground Level	Required	Provided	MR			
	Discharge of main Pump	2850 LPM	2850 LPM	MR			
	> Head of Main Pump	60 M	80 M	MR			
	Number of main pumps	1 No.	1 No.	MR			
	Jockey pump out put	180 LPM	180 LPM	MR			
	Jockey pump head	40 M	80 M	MR			
	Standby pump out put	2850 LPM	2850 LPM	MR			
	Standby pump Head	60 M	80 M	MR			
	Auto Starting / Manual stopping	Auto	Provided	MR			
	Pump House Access	Required	Provided	MR			
	Terrace Level	Required	Provided	MR			
	Discharge of pump	N/A	450LPM	MR			
	Head of the Pump	N/A	40 M	MR			
	Power supply	Required	Provided	MR			
	Auto Starting of pump	Required	Provided	MR			
.4	Captive Water Storage for Fire Fighting.						
	Underground tank capacity	1,40 ,000 Ltrs.	1,40,000 Ltrs.	MR			
	> Draw-off connection	Required	Provided	MR			
	> Fire service inlet	Required	Provided	MR			
	Access to tank	Required	Provided	MR			
	Overhead Tank capacity	2500 Ltrs.	10,000 Ltrs.	MR			
.5	Exit Signage.	Required	Provided	MR			
.6	Provision of Lifts.						
	Pressurization of Lift Shaft	N/A	N/A	N/A			
	Pressurization of Lift lobby	N/A	N/A	N/A			
	Communication in lift car	Required	Provided	MR			
	Firemen's grounding switch	Required	Provided	MR			
	Lift Signage	Required	Provided	IVIII			

1 (

17	Standby power supply	Required	Provided	MR
18	Refuge Area.			
10	Total area	N/A	N/A	N/A
	Location	N/A	N/A	N/A
19	Fire Control Room			1 2
	Detector system panel	N/A	N/A	N/A
	Flow switch panel	N/A	N/A	N/A
	PA system panel	N/A	N/A	N/A
	Battery backup	N/A	N/A	N/A
	Building Floor Plans	N/A	N/A	N/A
N/A	Special Fire Protection systems for protection of special Risks, if any:	N/A	N/A	

The fire protection systems provided in the building were tested checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules. The fire safety certificate issued vide letter no.: F.6/DFS/MS/Hospital/2012/3852 Dated 17.10.2012 renewal under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

Signature of the Inspecting Officer Name:-Suresh Singh

Designation :-ADO(Shah.)