GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI- 110001

NO. F6/DFS/MS/EH/2015/SZ/ 1124

Dated: 2/12/15

FIRE SAFETY CERTIFICATE

Certified that the Mc Donalds Family Restaurant located at Eros Metro Mall , Plot No-8, Sector-14, Dwarka, New Delhi-110075, running at first floor of the building comprised of three tier basement, ground plus three upper floors was granted NOC by this department vide letter no. F6/DFS/MS/EH/2012/4609 Dated 13.12.2012. The premises have been re-inspected by the officers concerned of this department on 13.11.2015 in presence of Sh. Vikash Gahlot (Restro. Manager) and found that the building have deemed complied with fire prevention & fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building is fit for occupancy class D Assembly building (Restaurant) with effect from 2012 115 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed overleaf.

Issued on at New Delhi by

(Dr. G C Misra) Chief Fire Officer Ph.011-23414333

Copy To:

ou

- 1. DHO/West Zone, Deputy Health Office, Municipal Corporation of Delhi, Najafgarh Zone New Delhi-110043.
- 2. Authorized signatory, Mc Donalds Family Restaurant located at Eros Metro Mall Plot No-8, Sector-14, Dwarka, New Delhi-110075.

CONDITIONS

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
- 5. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
- 6. All comments / directions of licensing Department shall always be permitted and followed.
- 7. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The owner / occupier shall apply for renewal of this **Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37)**along with copy of the certificate, six months prior to its expiry.

			INSPECTION R	EPORT			
	1	Name & address of the building	Restaurant at EROS METRO MAI 0075.	LL , Plot No. 8,			
	2	Type of Occupancy	Assembly (Restaurant)				
	3	Type of case					
	4	Details of previous NOC	2/4609 Dated. 13.12.2012				
	5	Fire safety directives letter No	Nil 13.11.2015				
	6	Date of inspection					
	7	Name of the inspecting Officers :					
	8	Name and designation of officers	DO Sanjay tomar & ADO Satpal Bhardwaj				
		from the building side	Sh.Vikash Gahlot (Restro. Manager) 2011				
	9	Year of construction					
	10	Applicant's letter No.	Nil 26.10.2015				
-	0. NO		Restaurant at Ground				
	S. NO.	Minimum Standards on fire prevention and fire safety U/R 33	NBC Requirement	Provided at site	Remarks MR / NMR		
	1	Access to building					
		1) Road width	20 Meters	20 Meters	MR		
		2) Gate width	2.20 Meters	2.20 Meters, Main Entrance	MR		
-	0	3) Width of internal road	N/A	6 Meters	MR		
-	2	Number, width Type & arrangement of	exits	A7			
		a. Number of staircases					
		1. Upper floors	N/A	Restraurant at ground floor	N/A		
		2. basements	N/A	N/A	N/A		
		b. Width of staircase					
		1. Upper floors	N/A	N/A	N/A		
		2. basements	N/A	N/A	N/A		
		c. Protection of exits					
		1. Fire check door	N/A	N/A	N/A		
		2. Pressurizationd. No. of continuous staircase to	N/A	N/A	N/A		
		terrace to terrace					
		e. Width of corridor	N/A 03 Mtrs.	N/A	N/A		
		f. Door size	2.20 Mtrs.	03 Mtrs.	MR		
		Compartmentation.	2.20 Milis.	Two of 2.20 Mtrs.& one .78 Mtrs.	MR		
		1. Fire check door	Required	Provided	MD		
		2. Sealing of electrical shafts	Required	Sealed	MR MR		
		3. Fire Rating of shaft door	N/A	N/A	N/A		
		4. water curtain	N/A	N/A	N/A		
	The second secon		N/A	N/A	N/A		
		Smoke Management system.					
		basement	N/A	N/A	N/A		
			Required	Exahaust fan provided	MR		
			N/A	N/A	N/A		
-123		Fire Extinguishers total numbers					
	Charles To Australia	Tunas	10 Nos.		MR		
	No. of Concession, Name of Street, or other party of the last of t	101 1 :	Co2 & ABC, Wco2		MR		
			Required	Provided	MR		

6	First-Aid Hose Reels.			
	total numbers on each floor	2 Nos.	2 Nos.	MR
	Length of Hose reel hose	30 M	Provided	M
	Nozzle Diameter	5 mm	Provided	MR
7	Automatic fire detection and alar		[. revided	JIVIK
	Type of detectors	Smoke / Heat	Provided	MR
	location of Main Panel	Required	Control room	MR
	location of Repeater panel	N/A	Provided	MR
	Alternate source of power	Required	DG Set & Battery Backup	MR
	hooter's location	Appropriate Place		MR
8	MOEFA	Required	Provided	MR
9	Public Address System.	Required	Provided	MR
10	Automatic Sprinkler System.	Connected with M	Main system of mall	IVIIX
	basement	Required	Provided	MR
	upper floors	Required	Provided	MR
	sprinkler above false ceiling	Required	Provided	MR
11	Internal Hydrants		Connected with Main system of m	
	Size of riser/down-corner	150 mm	200 mm	MR
	Number of Liveling to a second	4 Nos.	04 Nos.	IVIIX
	Number of Hydrants per floor hose Box			MR
12		Required	Provided	MR
12	Yard Hydrants.			
	total number of hydrants hose box	6 Nos.	6 Nos.	MR
13		Required	Provided	MR
10	Pumping arrangements 1. Ground level			
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			
	a. Discharge of main Pump	2850 LPM	2850 LPM	MR
	b.Head of main pump	70 M	70 M	MR
	c.Number of main pumps	2 Nos.	2 Nos.	MR
	d.jockey pump out put	2 X 180 LPM	2 X 180 LPM	MR
	e.jockey pump head	70 M	70 M	MR
	f. Standby Pump output	2850 LPM	2850 LPM	MR
	g.Stanby Pump head	75 Mtrs.	75 M	MR
	h.Auto Starting/Manual stopping	Required	Provided	MR
	I. pump house access 2.Terrace level	Required	Provided	MR
	C (3)	NI/A		
	a. Discharge of pump	N/A	N/A	N/A
	b. head of the pump	N/A	N/A	N/A
	c. Power supply	N/A	N/A	N/A
4.	d. Auto starting of pump	N/A	N/A	N/A
14	Captive water storage for fire fighti	ng		
	Underground tank capacity	At ground level	1,00,000 Ltrs.	MR
	a. Draw-off connection	Required	Provided Provided	MR
	b. fire service inlet	Required	Provided	MR
	c.Access to tank	Required	Provided	MR
	Over head tank Capacity	25000 Lts.	25000 Lts.	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of lifts.		Restaurant at Ground Floor	IVII
	a. Pressurization of lift shaft	Required	Provided Provided	MR
	b. pressurization of lift lobby	Required	Provided	MR
	c. communication in lift car	Required	Provided	MR
	d. Fireman's grounding switch	Required	Provided	MR
	e. Lift signage	Required	Provided	MR

18	Refuge Area.			
	total area	N/A	N/A	N/A
7	location	N/A	N/A	
100	Fire control room		11477	N/A
	a. Detector system Panel	Required	Provided	MD
19	b. Flow switch Panel	Required	Provided	MR
	c. PA system Panel	Required	Provided	MR
	d. Battery backup	Required		MR
	e. Building floor plans		Provided	MR
	or ballaring floor plans	Required	Provided	MR
20	Special Fire Protection System for Protection of special Risks, if any:		Co2 quota	n Provided.

The fire protection systems provided in the building were checked and found functional at the time of inspection.

Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety required under the rules, renewal of Fire Safety Certificate issued vide letter no.F6/DFS/MS/EH/2012/4609 dated 13.12.2012 is recommended under rules 35 of the Delhi Fire Service Rules 2010.

Accordingly DFA is put up for approval and signature please.

Signature of the Industries Offi

Signature of the Inspecting Officer

Name Sanjay Tomer

Designatio DO (South West)

Name

S.P. Bhardwaj

Designation

Signature of the Inspecting

ADO (Dwarka)