

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI-110001.

E-mail:- cfohq.dlfire@nic.in

No. F.6/DFS/MS/EH/2015/52) 2184


Fax: - 011-23412593

Dated: 14/12/15

FIRE SAFETY CERTIFICATE

Certified that the building of **Mc Donald's Family Restaurant**, located at 30/4 & 30/4A, Double Storey, Tihar-II, Ashok Nagar, New Delhi-110018, is comprised of ground floor plus three upper floors. The restaurant is running at ground floor plus one upper floor only. The above restaurant was issued FSC vide Letter No. F6/DFS/MS/EH/2013/225 dated 14.01.2013 owned/ occupied by M/S Connaught Plaza Restaurant Pvt. Ltd. The Restaurant building was re-inspected by the officers concerned of this department on 08.12.2015 in the presence of Sh. Sh. Ankur Mohan (Restaurant Manager) and found that the M/S Connaught Plaza Restaurant Pvt. Ltd. have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the restaurant building (**at ground floor plus one upper floor only**) is fit for occupancy class Group D assembly building w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed overleaf.

Issued on.....14/12/15.....at New Delhi.


(DR. G.C. MISRA)
CHIEF FIRE OFFICER
DELHI FIRE SERVICE

Dr. G.C. Misra
14/12/15

Copy to:-

1. The Manager,
Mc Donald's Family Restaurant, located at 30/4 & 30/4A,
Double Storey, Tihar-II, Ashok Nagar, New Delhi-110018.

Following fire safety directives must be adhered to:-

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
3. The trained staff should be available round the clock.
4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
6. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

Building is comprised of ground plus three upper floors but Restaurant is running at ground plus one upper floor only (Mc Donald's Family Restaurant, located at 30/4 & 30/4A, Double Storey, Tihar-II, Ashok Nagar, New Delhi-110018)

INSPECTION REPORT

1. Name & address of the building: Mc Donald's Family Restaurant, located at 30/4 & 30/4A, Double Storey, Tihar-II, Ashok Nagar, New Delhi-110018.
2. Type of Occupancy : Group D (Assembly)
3. Type of Case : Renewal
4. Details of Previous NOC : F6/DFS/MS/EH/2013/225 dated 14.01.2013.
5. Fire Safety directives letter No : Nil.
6. Date of inspection : 08.12.2015
7. Name of Inspecting Officer : D.O. S.K. Tomar and A.D.O. Sandeep Duggal
8. Name and designation of officers
From the building side : Sh. Ankur Mohan (Restaurant Manager)
9. Year of Construction : Before 2010
10. Applicant's letter No. : Nil dated 20.11.2015

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	NBC/ BBL Requirement	Provided at site	Remarks MR/NMR
1.	Access to building			
	<ul style="list-style-type: none"> • Road width • Gate width • Width of internal road 	<p style="text-align: center;">Accessible</p> <p style="text-align: center;">—</p> <p style="text-align: center;">—</p>	<p style="text-align: center;">09 mtrs</p> <p style="text-align: center;">2.3 mtrs.</p> <p style="text-align: center;">—</p>	<p style="text-align: center;">M/R</p> <p style="text-align: center;">M/R</p> <p style="text-align: center;">—</p>
2.	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases			
	<ul style="list-style-type: none"> • Upper Floors • Basements 	<p style="text-align: center;">02 No.'s</p> <p style="text-align: center;">N/A</p>	<p style="text-align: center;">03 No.'s</p> <p style="text-align: center;">N/A</p>	<p style="text-align: center;">M/R</p> <p style="text-align: center;">No Basement</p>
	b. Width of staircases			
	<ul style="list-style-type: none"> • Upper Floor • Basements 	<p style="text-align: center;">150 cms</p> <p style="text-align: center;">N/A</p>	<p style="text-align: center;">170, 110 & 90 Cms</p> <p style="text-align: center;">N/A</p>	<p style="text-align: center;">M/R</p> <p style="text-align: center;">No Basement</p>
	Protection of exits			
	<ul style="list-style-type: none"> • Fire check door • Pressurization 	<p style="text-align: center;">N/A</p> <p style="text-align: center;">N/A</p>	<p style="text-align: center;">N/A</p> <p style="text-align: center;">N/A</p>	<p style="text-align: center;">N/A</p> <p style="text-align: center;">N/A</p>
	d. No. of continuous staircases to terrace			
		N/A	One	N/A
	e. Width of Corridor			
		N/A	N/A	N/A
	f. Door Size			
		—	02 mtrs	M/R
3.	Compartmentation			
	<ul style="list-style-type: none"> • Fire check door • Sealing of electrical shafts • Fire Rating of shaft door • Water Curtain • Fire Dampers 	<p style="text-align: center;">N/A</p> <p style="text-align: center;">N/A</p> <p style="text-align: center;">N/A</p> <p style="text-align: center;">N/A</p> <p style="text-align: center;">N/A</p>	<p style="text-align: center;">N/A</p> <p style="text-align: center;">N/A</p> <p style="text-align: center;">N/A</p> <p style="text-align: center;">N/A</p> <p style="text-align: center;">N/A</p>	<p style="text-align: center;">N/A</p> <p style="text-align: center;">N/A</p> <p style="text-align: center;">N/A</p> <p style="text-align: center;">N/A</p> <p style="text-align: center;">N/A</p>
4.	Smoke Management System			
	Basements	N/A	N/A	No Basement

Sar

N/6

Building is comprised of ground plus three upper floors but Restaurant is running at ground plus one upper floor only (Mc Donald's Family Restaurant, located at 30/4 & 30/4A, Double Storey, Tihar-II, Ashok Nagar, New Delhi-110018)

	Upper floors	—	Natural Ventilation	M/R
5.	Fire Extinguishers			
	Total numbers	08 no's	Provided	M/R
	Types	ABC/CO ₂	Provided	M/R
	IS marking	ISI marked	ISI marked	M/R
6.	First-Aid Hose Reels (Restaurant at Ground Floor only)			
	Total numbers on ground floor	One/Floor	Provided	M/R
	Length of hose reel hose	30 mtrs	Provided	M/R
	Nozzle diameter	5 mm	Provided	M/R
7.	Automatic fire detection and alarming system			
	Type of detectors	Smoke & Heat	Provided	M/R
	Location of Main Panel (Common with Janak Place)	—	Near reception	M/R
	Location of Repeater Panel	—	—	—
	Alternate source of power	Required	DG Set 180 KVA	M/R
	Hooters' Location	—	Near staircase	M/R
8.	MOEFA	Required	Provided	M/R
9.	Public Address System	Required	Provided	M/R
10.	Automatic Sprinkler System			
	Basement	N/A	N/A	N/A
	Ground Floor	Required	Provided	M/R
	Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants			
	Size of riser/down-comer	N/A	100 MM	M/R
	Number of hydrants	N/A	One	M/R
	Hose Box	N/A	One	M/R
12.	Yard Hydrants			
	Total number of hydrants	N/A	one	M/R
	Hose Box	N/A	one	M/R
13.	Pumping Arrangements			
	Ground Level			
	Discharge of main Pump	N/A	N/A	N/A
	Head of Main pump	N/A	N/A	N/A
	Number of main pumps	N/A	N/A	N/A
	Jockey Pump out put	N/A	N/A	N/A
	Jockey pump head	N/A	N/A	N/A
	Standby Pump out put	N/A	N/A	N/A
	Standby Pump Head	N/A	N/A	N/A
	Auto Starting/Manual Stopping	N/A	N/A	N/A

Sam

Building is comprised of ground plus three upper floors but Restaurant is running at ground plus one upper floor only (Mc Donald's Family Restaurant, located at 30/4 & 30/4A, Double Storey, Tihar-II, Ashok Nagar, New Delhi-110018)

		N/A	N/A	N/A
	Pump House Access			
	Terrace level	450 LPM & 180 LPM	Provided	M/R
	Discharge of pump	30 mtrs	Provided	M/R
	Head of the pump	Required	Provided	M/R
	Power Supply	N/A	N/A	N/A
	Auto Starting of pump			
14.	Captive Water Storage for fire fighting			
	Underground tank capacity	N/A	N/A	N/A
	Draw-off connection	N/A	N/A	N/A
	Fire service inlet	N/A	N/A	N/A
	Access to tank	N/A	N/A	N/A
	Overhead Tank capacity	10,000 ltrs	Provided	M/R
		Required	Provided	M/R
15.	Exit Signage.			
16.	Provision of Lifts.			(No Lift)
	Pressurization of Lift Shaft	N/A	N/A	N/A
	Pressurization of Lift lobby	N/A	N/A	N/A
	Communication In lift Car	N/A	N/A	N/A
	Fireman's Grounding Switch	N/A	N/A	N/A
	Lift Signage	N/A	N/A	N/A
		Required	Provided	M/R
17.	Standby power supply			
18.	Refuge Area.			
	Total Area	N/A	N/A	N/A
	Location	N/A	N/A	N/A
19.	Fire Control Room			
	Detector System Panel	N/A	Basement	N/A
	Flow Switch Panel	N/A	N/A	N/A
	PA System Panel	N/A	N/A	N/A
	Battery backup	N/A	Provided	M/R
	Building Floor Plans	N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A


San

2/8

Building is comprised of ground plus three upper floors but Restaurant is running at ground plus one upper floor only (Mc Donald's Family Restaurant, located at 30/4 & 30/4A, Double Storey, Tihar-II, Ashok Nagar, New Delhi-110018)

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the Fire Safety Certificate issued vide letter number F6/DFS/MS/EH/2013/225 dated 14.01.2013 renewal under rule 35 of the Delhi Fire Service Rules 2010 is recommended.


Signature of Inspecting Officer

Name:- S.K. Tomar

Designation:- Divisional Officer


Signature of Inspecting Officer

Name:- Sandeep Duggal

Designation:- Asstt. Divisional Officer

