GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/WZ/2015/ EH/2141

FIRE SAFETY CERTIFICATE

Certified that the Mc Donald's Family Restaurant at G-1, Block-G, Pushkar Enclave, Pashim Vihar, New Delhi-110063 was granted NOC / FSC by the department vide letter No. F6/DFS/MS/2012/EH/3774/dated 12/10/2012. The premises was re-inspected by the officer concerned of this department on dated 13/11/2015 in presence of Mr. Rajinder Singh (Asst. Manager) & found that building have deemed complied with the Fire Prevention and Fire Safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises fit for class D (Assembly) occupancy with effect from and approximate for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 04/12/15 at New Delhi by.

(Santokh Singh)
Chief Fire Officer
Delhi Fire Service
Tel. -011-23424250

Dated: 04/12/15

Copy to :-

Authorized Signatory, Mc Donald's Family Restaurant, Connaught Plaza Restaurants Private Limited, Corp. Off. 13A, Jor Bagh Market, New Delhi-110003.

Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided their in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. The class rooms shall not have more than 45 students in any case.
- 7. "The owner / Occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule37] along with a copy of this Certificate, six months prior to its expiry".
- 8. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The from is available on WWW.dfs.Delhigovt.nic.in

To see the compliance of office letter no. F6/DFS/MS/EH/2015/2163 dated 18/09/2015

INSPECTION REPORT

1. Name & address of the building: Mc Donald's Family Restaurant, G-1, Block-G,

Pushkar Enclave, Pashim Vihar, New Delhi-110063.

2. Type of Occupancy

: Assembly (Restaurant)

3. Type of Case

:Renewal

Ground Floor + One Upper only Plot Area :- 1215 m²

Covered Area GF:- 416m², FF:-296m²

4. Fire Safety directives Letter No.: F6/DFS/MS/2012/EH/3774/dated 12/10/2012

5. Date of inspection : 13/11/2015

6. Name of the Inspecting Officer: A. K.-Jaiswal A.D.O. (Jwp.)

7. Name and designation of Officer

from the building side

: Mr. Rajinder Singh (Asst. Manager)

8. Year of Construction : 2006-07

9. Applicant's letter No.:-CPRPL/FM/OM/NOC/2015-16/228 DATED 26/10/15

S No	Minimum standards on fire	NBC Part-IV	Provided at	Remarks		
	prevention and fire safety U/R 33	Requirements	site	MR/NMR		
1.	Access of building					
	 Road width 	12 mtr.	Provided	MR		
	Gate width	4.5 mtr.	Provided	MR		
	 Width of internal road 		Provided	MR		
2.	Number, width, Type & Arrar	ngements of exits				
	a. Number of staircases					
	Upper floors	Restaurant at Ground Floor Only	2	MR		
	 Basements 	2	3	MR		
	b. Width of staircases		8			
	Upper floors	Restaurant at Ground Floor Only	NA	NA		
	Basements	1.50mtr.	1.50mtr,1.20 mtr,&1.25mtr	MR		
	c. Protection of exits		, , , , , , , , , , , , , , , , , , , ,			
	 Fire check door 	Required	provided	MR		
	 Pressurization 	NR	NR	NR		
	d. No of continuous staircase to terrace	NA	NA	NA		
	e. Width Of Corridor	Halls Only	Halls Only	MR		
	f. Door Size	1.50x2 mtr.	Provided	MR		
3.	Compartmentation					
	Fire check door	Required	Provided	MR		
	 Sealing of electrical shafts 	NR	NR	NR		
	Fire Rating of shaft door	NR	NR	NR		
	Water Curtain	NR	NR	NR		
	• Fire Dampers	NR	NR	NR		
4.	Smoke managements System					
	• Basements	Required	Provided	MR		
	Upper floors	Restaurant at Ground Floor Only	Provided	MR		
5	Fire Extinguishans					

6.	First – Aid Hose Reels						
	Total numbers on	One	Provided	MR			
	each floor						
	 Length of hose reel 	30mtr.	Provided	MR			
	hose						
	 Nozzle diameter 	5 mm	Provided	MR			
7.	7. Automatic fire detection and alarming system						
	Type of detector	Smoke	Provided	MR /			
	 Location of Main 	Required	Provided	MR			
	Panel						
	 Location of Repeater 	Required	Provided	MR			
	Panel						
	Alternate source of	Required	Provided	MR			
	power	<u> </u>					
	Hooters' Location	Required	Provided	MR			
8.	MOEFA	Required	Provided	MR 🗸			
9.	Public Address System	NR	NR	NR			
10.	Automatic Sprinkler System						
	Basements	Required	Provided	MR ✓			
	• Upper Floor	(Restaurant at	Provided	MR			
	Sanial land f-l	Ground floor only) Required	Provided	- NAD			
	• Sprinkler above false ceiling	Required	Provided	MR			
11.	Internal Hydrants						
11.	Size of riser/down-	NR	NR	NR			
	comer			1414			
	Number of hydrants	NR	NR	NR			
	per floor						
	Hose Box	NR	NR	NR			
12.	Yard Hydrants						
	Total number of	NR	NR	NR			
	hydrants						
	Hose Box	NR	NR	NR			
13.	Pumping Arrangements						
•	Ground Bever	N/A	9				
•	Bisenaige of main painp	NR .	NR	NR			
700	Head of main pump	NR	NR	NR			
	Number of main pumps	NR	NR	NR			
	Jockey pump out put	NR	NR	NR			
	Jockey pump headStandby Pump out put	NR	NR	NR			
	Standby Pump out putStandby Pump Head	NR NR	NR NR	NR			
	Auto Staring/Manual	NR	NR	NR NR			
	stopping	TVIX	IVIX	INIX			
- >	Pump House Access	NR	NR	NR			
•	Table 1 Sales - Sales	7					
>	Discharge of pump	900 LPM	Provided	MR			
>		60 MH	Provided	MR			
	Power supply	Required	Provided	MR			
- >		Required	Provided	MR			
14.	Captive water Storage for fire		NID	NID			
	Underground tank capacity	NR	NR	NR			
	capacity > Draw of connection	NR	NR	NR			
	Fire service inlet	NR	NR	NR			
	A 1	111	1411	INIA			

T	15	Exit Signage	13/N		*
	16.	Provision of Lifts	Required	Provided	MR
17.		Pressurization of Lift Shaft	NR	NR	NR
		Pressurization of lift lobby	NR	NR	NR
		Communication in lift Car Fireman's Grave Li	NR	NR	NR
		Switch	NR	NR	NR
	7	ant biginage	NR	NR	NR ·
18		Standby power supply Refuge Area	NR	NR	NR
		> Total area	N/A	N/A	1411
		> Location	N/A	N/A	N/A
19).]	Fire control room	N/A	N/A	N/A
		 Detector system panel Flow Switch Panel PA System Panel Battery backup 	N/A N/A N/A	N/A N/A N/A	N/A N/A N/A N/A
20.	S	pecial Fire Prot	N/A	N/A	N/A
	S	ystems for Protection of pecial Risks, if any;	N/A	N/A	N/A

Note: MCB / ELCB and metal conduit wiring (Concealed Type) have been Provided.
The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter No. F6/DFS/MS/2012/EH/3774/dated 12/10/2012 renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

Signature of the Inspecting Officer

Name : Ashok Kumar Jaiswal

Designation: A.D.O. (Jwala Puri)