## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

Fax: 23412593, E-mail: cfohq.dlfire@nic.in, Tel:- 011-23414333

NO.F6/DFS/MS/EH/2015/ 52 /2/42

Dated: 4/12/15

## **FIRE SAFETY CERTIFICATE**

Certified that M/s. McDonald's Family Restaurant located at Showroom No. 22-29, Grindlays Cinema, New Friends Colony, New Delhi is running at ground floor was granted FSC by this department vide letter No. F.6/DFS/MS/EH/2012/4767 dated 27-12-2012. The premises was re-inspected by the officer concerned of this department on 04-11-2015 in the presence of Mr. Anil, manager and found that the said eating house have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules 2010 and that the premises / building is fit for occupancy Class- D Assembly (restaurant) with effect from <u>D4/12-115</u> for a period of 3(three) years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi fire service Rules, 2010.

Issued on oy/12/15 at New Delhi by.

(Dr. G.C. MISRA) CHIEF FIRE OFFICER

Copy to: -

1. The Addl.C.P (Lic.), Police Station, Defence Colony, 1st floor, New Delhi.

2. The Manager, M/s. McDonald's Family Restaurant, Showroom No. 22-29, Grindlays Cinema, New Friends Colony, New Delhi.

## Conditions for the validity of fire safety certificate

- a. All the fire safety and means of escape facilities shall be maintained in good working conditions at all time. Any lapse rendering fire safety or means of evacuation facilities rendering non-functional shall be the responsibility of the management.
- b. Building Sanctioning authority may verify any deviation with regard to the construction / occupancy in the building. In case of any deviation, the fire safety certificate stands null and void.
- c. The staffs shall be trained for operating fire fighting system and mock evacuation drills be conducted at regular intervals and record be maintained.
- d. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on website <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>

## INSPECTION REPORT

1. Name & address of the building : M/s. McDonald's Family Restaurant, Showroom No. 22-29, Grindlays Cinema, New Friends Colony, New Delhi.

2. Type of Occupancy : Assembly, Group-D

3. Type of Case : Renewal

4. Details of previous NOC : F.6/DFS/MS/EH/2012/4767 dated 27-12-2012

5. Fire Safety directives letter No : N/A

6. Date of inspection : 04-11-2015

7. Name of the Inspecting Officers : M.K.Chattopadhyay, ADO(M.Rd)

8. Name and designation of officer

9. from the building side : Mr. Anil, Manager

10. Year of Construction : 2006-07

11. Applicant's letter No. : nil dated 26.10.2015.

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	NBC/BBL Requirement	Provided at site	Remarks MR/NMR		
	Access to building					
	Road width	06 mts	Provided	MR		
	Gate width	4.5 mts	Provided	MR		
	Width of internal road	N/A	N/A	N/A		
	Number, Width, Type & Arrangement of Exits					
	a. Number of staircases	Ground Floor only				
	Upper Floors	N/A	N/A	N/A		
	Basements	N/A	N/A	N/A		
	b. Width of staircases	Ground Floor only	-			
	Upper Floors	N/A	N/A	N/A		
	Basements	N/A	N/A	N/A		
	c. Protection of exits					
	• Fire check door	N/A	N/A	N/A		
	• Pressurization	N/A	N/A	N/A		
	d. No. of continuous staircases to terrace	N/A	N/A	N/A		
	e. Width of Corridor	N/A	N/A	N/A		
	f. Door Size	Old case	1.60 mts, 0.90 mt	MR		
	Compartmentation.					
	Fire check door	N/A	N/A	N/A		
	Sealing of electrical shafts	N/A	N/A	N/A		
	Fire Rating of shaft door	N/A	N/A	N/A		
	Water Curtain	N/A	N/A	N/A		
	Fire Dampers	N/A	N/A	N/A		
1	Smoke Management System.					

	Basements	30 a/c per hour	N/A	N/A		
	Upper floors	12 a/c per hour	Venting provided in kitchen	MR		
5	Fire Extinguishers		Rection	4		
	Total numbers	06	Provided	MR		
	• Types	ABC, CO <sub>2</sub>	Provided	MR		
	IS marking	ISI marked	Provided	MR		
6	First-Aid Hose Reels.					
	Total numbers on each floor	01	Provided	MR		
	Length of hose reel hose	30 m	Provided	MR		
	Nozzle diameter	5 mm	Provided	MR		
7	Automatic fire detection and alarming s					
	Type of detectors	Heat/Smoke	Provided near restaurant	MR		
-	Location of Main Panel	Required	Provided	MR		
		N/A	N/A	N/A		
	Location of Repeater Panel	Required	Provided	MR		
	Alternate source of power	-				
	Hooters' Location	Required	Provided	MR		
8	MOEFA	Required	Provided	MR		
9	Public Address System.	N/A	N/A	N/A		
10	Automatic Sprinkler System.					
	Basement	N/A	N/A	N/A		
	Upper Floor	Required	Provided	MR		
	<ul> <li>Sprinkler above false ceiling</li> </ul>	N/A	N/A	N/A		
11	Internal Hydrants					
	• Size of riser/down-comer	100 mm	Provided	MR		
	<ul> <li>Number of hydrants per floor</li> </ul>	01 Nos.	Provided near restaurant	MR		
	Hose Box	01 Nos.	Provided near restaurant	MR		
12	Yard Hydrants.					
	<ul> <li>Total number of hydrants</li> </ul>	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
13	Pumping Arrangements.					
	Ground Level	-	-	-		
	<ul><li>Discharge of main Pump</li></ul>	2850 LPM	Provided in Mall	MR		
	➤ Head of Main pump	70 mts	Provided in Mall	MR		
	Number of main pumps	02	Provided in Mall	MR		
	Jockey Pump out put	950 LPM	Provided in Mall	MR		
100	Jockey pump head	70 mts	Provided in Mall			
	Standby Pump out put	2850 LPM	Provided in Mall	MR MR		
	<ul><li>Standby Pump Head</li></ul>	70 mts	Provided in Mall	MR		
	, suridoj i dilip liedd	, 0 11165		MIN		

	> Auto Starting/ Manual	Required	Provided in Mall	MR		
	stopping	Required	Provided in Mall	MR		
	<ul><li>Pump House Access</li><li>Terrace level</li></ul>					
		N/A	N/A	N/A		
	Discharge of pump	N/A	N/A	N/A		
	➤ Head of the pump	N/A N/A	N/A	N/A		
	> Power Supply  Auto Starting of nump	N/A	N/A	N/A		
14	<ul> <li>Auto Starting of pump</li> <li>Captive Water Storage for fire fighting</li> </ul>		and an analysis of the second			
.4		2,00,000 lts	Provided in Mall	MR		
	<ul> <li>Underground tank capacity</li> <li>Draw-off connection</li> </ul>	Required	Provided in Mall	MR		
	Fire service inlet	Required	Provided in Mall	MR		
	> Access to tank	Required	Provided in Mall	MR		
	Overhead Tank capacity	25,000 lts	Provided in Mall	MR		
			Duranidad	MR		
15	Exit Signage.	Required	Provided	MK		
16	Provision of Lifts.	N/A	N/A	N/A		
	Pressurization of Lift Shaft		NT/A	N/A		
	Pressurization of Lift lobby	N/A	N/A	IN/A		
	Communication In lift Car	N/A	N/A	N/A		
	Fireman's Grounding Switch	N/A	N/A	N/A		
	Lift Signage	N/A	N/A	N/A		
17	Standby power supply	Required	Provided	MR		
18	Refuge Area.					
	> Total Area	N/A	N/A	N/A		
	> Location	N/A	N/A	N/A		
19	Fire Control Room					
	Detector System Panel	Required	Provided	MR		
	• Flow Switch Panel	N/A	N/A	N/A		
	PA System Panel	N/A	N/A	N/A		
	Batter backup	N/A	N/A	N/A		
	Building Floor Plans	N/A	N/A	N/A		
20	Special Fire Protection Systems for Protection of special Risks, if any:	Required	02 ABC type fire extinguishers found provided near elect. panel	MR		

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the NOC issued vide letter No. F.6/DFS/MS/EH/2012/4767 dated 27-12-2012, renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

DFA is put up for approval & signature please.

Signature of the Inspecting Officer
Name M.K.CHATTOPADHYAY
Designation: - Asstt. Div. Officer (M.Rd)

Do(sx) - leave)
D cfo(sx) / [1] / 3