GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/EH/2015/ MDZ/2/93

Dated: 17/12/15

FIRE SAFETY CERTIFICATE

Certified that the Odeon Social (A Unit of Impresario Entertainment and Hospitality Pvt. Ltd.) located at 23, Odeon Building, 1st floor, D-Block, Connaught Place, New Delhi comprises of Ground + 03 upper floor, Restaurant is running at First floor only owned /occupied by Odeon Social (A Unit of Impresario Entertainment and Hospitality Pvt. Ltd.) has complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Delhi Fire Service on 08-12-2015 in the presence of Sh. Sanjay (Project Manager) that the building / premises, is fit for occupancy class Assembly Building Group-D of Sub-Division D-5, Restaurant is running at First floor only with effect from -17-115--- for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

(Dr. G.C. Misra) Chief Fire Officer Ph-011-23414333

Copy to:-

1. The Medical Officer of Health, NDMC, Palika Kendre, New Delhi.

2. The Manager, Odeon Social (A Unit of Impresario Entertainment and Hospitality Pvt. Ltd.), 23, Odeon Building, 1st floor, D-Block, Connaught Place, New Delhi

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.

5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

-11/1-

INSPECTION REPORT

1. Name & address of the building: Odeon Social (A Unit of Impresario

Entertainment and Hospitality Pvt. Ltd.) located at 23, Odeon Building, 1st floor, D-

Block, Connaught Place, New Delhi

2. Type of occupancy:- Assembly Building

Gr. + 3 upper floor

(Restaurant at first floor only)

3. Type of case:- Fresh

4. Details of previous NOC:- NA5. Fire safety directives No.- N/A

6. Date of inspection: 08/12/15

7. Name of the inspecting officer:- Sh. Gurmukh Singh Chauhan DO/CD &

Sh. Manoj Kumar Sharma ADO/CC

8. Name & designation of officer
From the building side:- Sh. Sanjay (Project Manager)

9. Year of construction:- Old

10. Applicant's letter No:- MHO/D711/(Lic.)/SI-I dated 30/11/15

Old Case S.No. Minimum Standards on fire Requirement Provided at site Remarks Prevention and fire safety Existing MR/NMR U/R 33 1. Access to Building 1) Road width 09 mtr. 12 mtr. MR 2) Gate width N/A N/A N/A 3) Width of internal road N/A N/A N/A 2. Number, Width Type & Arrangement of Exits A. Number of staircases 1. Upper floors 02 Nos. 03 Nos. MR 2. Basements N/A N/A N/A B. Width of staircase 1. Upper floors 1.25 mtr. 1 Nos. 1.50 to MR 1.50 mts. 1.75 mtr., 1 Nos. 1.50 mtr. 1 Nos. 1.60 mtr. 2. Basements N/A N/A N/A C. Protection of exits N/A 1. Fire check door N/A N/A 2. Pressurization N/A N/A N/A D. No. of continuous 02 02 MR staircase to terrace N/A E. Width of corridor N/A N/A F. Door size 2 mtr. 2 mtr. MR 3. Compartmentation 1) Fire check door N/A N/A N/A 2) Sealing of electrical shafts N/A N/A N/A 3) Fire rating of shaft door N/A N/A N/A 4) Water curtain N/A N/A N/A

h

Man

	5) Eine D				
4.	5) Fire Dampers	N/A	N/A	N/A	
7.	Smoke Management Syste 1) Basements				
		N/A	N/A	N/A	
5.	2) Upper floors	12 a/c per	Natural	MR	
5.	Fire Extinguishers			AAAA	
	1) Total numbers	08	08	MR	
	2) Types	ABC & CO2	ABC & CO2	MR	
	3) ISI marking	ISI	Provided	MR	
6.	First-Aid Hose Reel			IVIIC	
, , , , , , , , , , , , , , , , , , ,	1) Total number	01	01	MR	
	2) Length of hose reel hose	30 m	30 m	MR	
	3) Nozzle diameter	5 mm	6	MR	
7.	Automatic Fire Detection & Alarming System				
	1) Type of detectors	N/A	N/A	NI/A	
	2) Location of main panel	N/A	N/A	N/A	
	3) Location of repeater panel	N/A	N/A	N/A	
	4) Alternate source of power	N/A	N/A	N/A	
	5) Hooter's Location	N/A	N/A	N/A	
8.	MOEFA	Required		N/A	
9.	Public Address System	N/A	Provided	MR	
10.	Automatic Sprinkler System	IWA	N/A	N/A	
	1) Basement	N/A	77/4		
	2) Upper floors,		N/A	N/A	
	3) Sprinkler above false	Required N/A	Provided	MR	
	ceiling	IN/A	N/A	N/A	
11.	Internal Hydrants	L •			
	1) Size of riser/down-comer	100			
	2) Number of hydrants per	100 mm	100 mm	MR	
	floor	01	01	MR	
	3) Hose box each floor	0.1			
2.	Yard Hydrants	01	01	MR	
	1) Total number of 1				
	 Total number of hydrants Hose box 		N/A	N/A	
3.		N/A	N/A	N/A	
,	Pumping Arrangement	common			
	1) Ground level				
	a) Discharge of main	1650 LPM	1650 LPM	MR	
	pump				
	b) Head of main pump	70 mtr.	70 mtr.	MR	
	c) Number of main pump	02	02	MR	
	d) Jockey pump out put	180 LPM	180 LPM	MR	
	e) Jockey pump head	70 mtr.	N/A		
And the state of t	f) Stand by pump output	1650 LPM	1650 LPM	MR	
	g) Stand by pump head	70 mtr.	Provided	MR	
	h) Auto starting/Manual	Required	Provided	MR	
	stopping	roquirou	Trovided	MR	
	2) Terrace level				
	a) Discharge of pump	450 LPM	450 I DN4		
	b) Head of pump	1.0	450 LPM	MR	
		TO IIII.	40 mtr.	MR	

	c) Power supply	Required	Provided	MR	
	d) Auto starting of pump	Required	Provided	MR	
14.	Captive Water Storage for Fire Fighting				
	Under ground tank capacity	100,000	100,000	MR	
	a) Draw-off connection	N/A	N/A	N/A	
	b) Fire service inlet	N/A	N/A	N/A	
Senta	c) Access to tank	N/A	N/A	N/A	
	d) Over head tank capacity	2 0,000 ltrs.	20,000 Ltr.	MR	
15.	Exit Signage.	Required	Provided	MR	
16.	Provision of Lifts.			3	
	a) Pressurization of lift shaft	N/A	N/A	N/A	
	b) Pressurization of lift lobby	N/A	N/A	N/A	
	c) Communication in lift car	N/A	N/A	N/A	
	d) Fireman's switch	N/A	N/A	N/A	
	e) Lift signage	N/A	N/A	N/A	
17.	Stand by Power Supply	Required	Provided	MR	
18.	Refuge Area	N/A	N/A	N/A	
	Total area location	N/A	N/A	N/A	
19.	Fire Control Room	N/A	N/A	N/A	
	a) Detector system panel	N/A	N/A	N/A	
	b) Flow switch panel	N/A	N/A	N/A	
	c) PA system panel	N/A	N/A	N/A	
	d) Battery backup	N/A	N/A	N/A	
	e) Building floor plan	N/A	N/A	N/A	
20.	Special Fire Protection Syste Risk, if any:	MR			

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules, grant of fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010 / is recommended please.

Signature of the Inspecting Officer

Signature of the Inspecting Officer

Name: - M.K. Sharma Designation: - ADO (CC)

Name:- G.S Chauhan Designation:- DO (CD)