GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE **NEW DELHI-110 001.**

E-mail:- cfohq.dlfire@nic.in

No.F.6/DFS/MS/School/2015/ 52/2243

Fax: - 011-23412593 Dated: 23/12/15

FIRE SAFETY CERTIFICATE

Certified that the building of Govt. Co-Ed. Sr. Sec. School, Mitraon, New Delhi-110049, is comprised ground plus one upper floor only. The school is owned/occupied by the school management was inspected by the officer concerned of this department on 15.12.2015 in the presence of Sh. D.S Dalal (Vice-Principal) and found that the school management have complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the school building/ premises is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed as under.

Issued on 23/12/15 at New Delhi.

(DR. G.C. MISRA) CHIEF FIRE OFFICER **DELHI FIRE SERVICE**

Copy to:-

1. The Principal, Govt. Co-Ed. Sr. Sec. School, Mitraon, New Delhi-110043.

2. Director of Education. Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning
- 5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 6. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available www.dfs.delhigovt.nic.in.
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

Building is comprised of Ground plus one upper floor. (Govt. Co-Ed. Sr. Sec. School, Mitraon, New Delhi-110043.)

INSPECTION REPORT

1. Name & address of the building: Govt. Co-Ed. Sr. Sec. School, Mitraon, New Delhi-110043.

2. Type of Occupancy Educational

3. Type of Case New 4. Details of Previous NOC N/A 5. Fire Safety directives letter No : N/A

6. Date of inspection 15.12.2015

7. Name of Inspecting Officer A.D.O. Sandeep Duggal

8. Name and designation of officers

From the building side : Sh. D.S Dalal (Vice-Principal)

9. Year of Construction 2013

10.	Applicant's letter No. : Letter No. J65	dated 30.11.2015		
S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Dir. Of Edu. Circular dt. 01.03.2011	Provided at site	Remarks MR/NMR
1.	Access to building			
	Road width	Accessible	12 mtrs	M/R
	Gate width		3.5 mtrs.	
	 Width of internal road 			
2.	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases		*	
	 Upper Floors 	02 No's	03 No's	M/R
	 Basements 	N/A	N/A	No basement
	b. Width of staircases			
	Upper FloorBasements	150 cms	162 _{Cm} (2 No.'s) & 164 cms	M/R
		N/A	N/A	No basement
	c. Protection of exits	N/A	N/A	N/A
	Fire check door	N/A	N/A	N/A
	 Pressurization 			
	d. No. of continuous staircases to	N/A	N/A	N/A
	terrace	150 cms	215 cms	M/R
	e. Width of Corridor f. Door Size	100 cms	100 cms (double door)	M/R
3.	Compartmentation			
	Fire check door	N/A	N/A	N/A
	Sealing of electrical shafts	N/A	N/A	N/A
	Fire Rating of shaft door	N/A	N/A	N/A
	Water Curtain	N/A	N/A	N/A
	Fire Dampers	N/A	N/A	N/A
4.	Smoke Management System		. 1	1
is:	Basements	N/A	N/A	No basement



Pla

Building is comprised of Ground plus one upper floor. (Govt. Co-Ed. Sr. Sec. School, Mitraon, New Delhi-110043.)

	Upper floors	N/A	Natural Ventilation	M/R		
5.	Fire Extinguishers			1.670		
	Total numbers	10 no's	Provided	M/R		
	• Types	ABC/CO2 type	Provided	M/R		
	IS marking	ISI marked	ISI marked	M/R		
6.	First-Aid Hose Reels					
	Total numbers on each floor	N/A	N/A	N/A		
	 Length of hose reel hose 	N/A	N/A	N/A		
	Nozzle diameter	N/A	N/A	N/A		
-	Automatic fire detection and alarming system					
7.	Type of detectors	N/A	N/A	N/A		
	Location of Main Panel	N/A	N/A	N/A		
	Location of Name and Location of Repeater Panel	N/A	N/A	N/A		
	Alternate source of power	N/A	N/A	N/A		
	Hooters' Location	N/A	N/A	N/A		
		N/A	N/A	N/A		
8.	MOEFA	N/A N/A	Provided	N/A		
9.	Public Address System	IN/A	Tiovided	11111		
10.	Automatic Sprinkler System	N/A	N/A	N/A		
	Basement	N/A	N/A	N/A		
	Ground Floor Good Hard Server false spiling	N/A	N/A	N/A		
11.	Sprinkler above false ceiling Internal Hydrants	14/71	1771			
11.	internal flydrants					
	Size of riser/down-comer	N/A	N/A	N/A		
	Number of hydrants per floor	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
12.	Yard Hydrants					
	Total number of hydrants	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
13.	Pumping Arrangements					
	Ground Level					
	Discharge of main Pump	N/A	N/A	N/A		
	Head of Main pump	N/A	N/A	N/A		
	Number of main pumps	N/A	N/A	N/A		
	Jockey Pump out put	N/A	N/A	N/A		
	> Jockey pump head	N/A	N/A	N/A		
	> Standby Pump out put	N/A	N/A	N/A		
	> Standby Pump Head		N/A	N/A		
	Auto Starting/Manual Stopping			N/A		
	-	N/A	N/A N/A	N/A N/A		
	Pump House Access	N/A	IN/A	14/71		



2)5

Building is comprised of Ground plus one upper floor. (Govt. Co-Ed. Sr. Sec. School, Mitraon, New Delhi-110043.)

	special Risks, if any:			
20.	Special Fire Protection System for Protection of	N/A	N/A	N/A
		N/A	N/A	N/A
	Building Floor Plans	N/A	N/A	N/A
	Battery backup	N/A	N/A	N/A
	Flow Switch PanelPA System Panel	N/A	N/A	N/A
	Detector System Panel Flow Switch Panel	N/A	N/A	
19.	Fire Control Room			N/A
		N/A	N/A	N/A
	➤ Total Area ➤ Location	N/A	N/A	N/A
18.	Refuge Area.	27/4		
17.	Standby power supply	11/11		
		N/A	N/A	N/A
	Lift Signage	N/A N/A	N/A	N/A
	Fireman's Grounding Switch	N/A	N/A	N/A
	Communication In lift Car	N/A N/A	N/A N/A	N/A N/A
	 Pressurization of Lift Shaft Pressurization of Lift lobby 			N/A
6.	Provision of Lifts.	N/A	N/A	(No Lift) N/A
5.	Exit Signage.			
		N/A	N/A	N/A
	Overhead Tank capacity	N/A	N/A	N/A
	> Access to tank	N/A	N/A	N/A
	> Fire service inlet	N/A	N/A	N/A
	> Draw-off connection	N/A	N/A	N/A
14.	Captive Water Storage for fire fighting • Underground tank capacity	N/A	N/A	N/A
	Auto Starting of pump	N/A	N/A	N/A
	Power Supply	N/A	N/A	N/A
	➢ Head of the pump	N/A	N/A	N/A
	Discharge of pump	N/A	N/A	N/A

Sin

9/6

Building is comprised of Ground plus one upper floor. (Govt. Co-Ed. Sr. Sec. School, Mitraon, New Delhi-110043.)

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Keeping in view of the above substantial compliance of the minimum standards of fire prevention and fire safety measures as required in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Signature of Inspecting Officer

Name: - Sandeep Duggal

Designation:- Asstt. Divisional Officer

Signature of Inspecting Officer

Name

Designation

Divisional Officer (South West)

04 Januar