GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/2015/ NO2/2223

Dated: 22/12/15

FIRE SAFETY CERTIFICATE

Issued -22/12/12 -- at New Delhi by.

(Dr. G.C. Misra) Chief Fire Officer Ph-011-23414333

Copy to:-

- 1. The Joint Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi Ref. No. 1020/Joint C.P. /Lic.(H) dated 23/07/2015
- 2. Sh. Amit Sharma (Manager),
 Prince Guest House, 2325-26, Tilak Gali, Chuna Mandi, Pahar Ganj, New Delhi
 Condition for the validity of fire safety certificate
 - 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
 - 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
 - 3. The trained fire fighting staff should be available round the clock.
 - 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
 - 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
 - 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
 - 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

INSPI	ECTION REPORT
Name & address of the building:-	Prince Polonia Guest House located at 2325-26,
2. Type of occupancy:-	Tilak Gali, Chuna Mandi, Pahar Ganj, New Delhi Residential, Sub Division-A-1
3. Type of case:-	B + Gr. + 04 Upper floors (total 29 Guest rooms) Renewal
4. Details of previous FSC:-	No. F6/DFS/MS/GH/2012/4062 dated
5. Di	30/10/12.
5. Fire safety directives No	N/A
6. Date of inspection:-	02/10/15
7. Name of the inspecting officer:-	Sh. Manoj Kumar Sharma (ADO/CC)
8. Name & designation of officer	Trainer Sharmar (ADO/CC)
From the building side:-	Sh. Amit Sharma (Manager)
9. Year of construction:-	1994
10. Applicant's letter No:- No.	. 1020/Joint. C.P. /Lic.(H) dated 23/07/2015

0.27	/			Old Case
S.No.	Minimum Standards on fire Prevention and fire safety	Requirement Existing	Provided at site PSS	Remarks MR/NMR
4	U/R 33			
1.	Access to Building			
	1) Road width	N/A	06 mtr.	N/A
	2) Gate width	N/A	N/A	N/A
	3)Width of internal road	N/A	N/A	N/A
2.	Number, Width Type & Arı	rangement of Ex		14/11
	A. Number of staircases			
	1. Upper floors	01 Nos.	01 Nos.	MR
	2. Basements	01 Nos.	02 Nos.	MR
	B. Width of staircase			
	1. Upper floors	0.80 mtr.	1.22 to 1.29 mtr.	MR
	2. Basements	0.80 mtr	(i) 1.15 mtr. (ii) 1.58 mtr.	MR
	C. Protection of exits			
	1. Fire check door	N/A	N/A	N/A
	2. Pressurization	N/A	N/A	N/A
	D. No. of continuous staircase to terrace	01	01	MR
	E. Width of corridor	N/A	N/A	N/A
	F. Door size	1 mtr.	1 mtr.	MR
3.	Compartmentation	•		
	1) Fire check door	N/A	N/A	N/A
	2) Sealing of electrical shafts	N/A	N/A	N/A
	3) Fire rating of shaft door	N/A	N/A	N/A
	4) Water curtain	N/A	N/A	N/A
	5) Fire Dampers	N/A	N/A	N/A
4.	Smoke Management System			

	1) Basements	30 ACPH	Exhaust fans	MR	
	2) Upper floors	12 a/c per	Natural Ventilation	MR	
	2) Opport floors	hour			
5.	Fire Extinguishers			1.00	
3.	1) Total numbers	12 Nos.	12 Nos.	MR	
	2) Types	ABC & CO2	ABC & CO2	MR	
	3) ISI marking	Required	Provided	MR	
6.	First-Aid Hose Reel				
0	1) Total number of eachfloor	01	01	MR	
	2) Length of hose reel hose	30 m	30 m	MR	
	3) Nozzle diameter	05 mm	05 mm	MR	
7.	Automatic Fire Detection &	Alarming Syst	tem	1571	
1.	1) Type of detectors	N/A	N/A	N/A	
	2) Location of main panel	N/A	N/A	N/A	
	3) Location of repeater panel	N/A	N/A	N/A	
	4) Alternate source of power	N/A	N/A	N/A	
	5) Hooter's Location	N/A	N/A	N/A	
8.	MOEFA	Required	Provided	MR	
	Public Address System	Required	Provided	MR	
9.	Intercom				
10.	Automatic Sprinkler System				
10.	1) Basement	Required	Provided	MR	
	2) Upper floors	N/A	N/A	N/A	
	3) Sprinkler above false	N/A	N/A	N/A	
	ceiling				
11.	Internal Hydrants		N		
11.	1) Size of riser/down-comer	N/A	N/A	N/A	
	2) Number of hydrants per	N/A	N/A	N/A	
	floor		· · · · · · · · · · · · · · · · · · ·		
	3) Hose box	N/A	N/A	N/A	
12.	Vord Hydrants				
14.	1) Total number of hydrants	N/A	N/A	N/A	
	2) Hose box	N/A	N/A	N/A	
12	Pumping Arrangement		6		
13.	1) Ground level	N/A	N/A	N/A	
	a) Discharge of main	N/A	N/A	N/A	
	pump	ency Allenda for			
	b) Head of main pump	N/A	N/A	N/A	
	c) Number of main pun		N/A	N/A	
	d) Jockey pump out put	1	N/A	N/A	
	e) Jockey pump head	N/A	N/A	N/A	
	f) Stand by pump output		N/A	N/A	
	1 1		N/A	N/A	
	. 73.5		N/A	N/A	
	,	1 11/12	17		
	stopping 2) Terrace level				
	The state of the s	450 LPM	450 LPM	MR	
	a) Discharge of pump	30 mtr	30 mtr	MR	
	b) Head of pump	30 11111	30 11101		

	c) Power supply	Required	Provided	MR		
	d) Auto starting of pump	Required	Provided	MR		
14.		Captive Water Storage for Fire Fighting				
	 Under ground tank capacity 	N/A	N/A	N/A		
	a) Draw-off connection	N/A	N/A	N/A		
	b) Fire service inlet	N/A	N/A	N/A		
	c) Access to tank	N/A	N/A	N/A		
	d) Over head tank capacity	5000 ltr.	5000 ltr.	MR		
15.	Exit Signage.	Required	Provided	MR		
16.	Provision of Lifts.					
	a) Pressurization of lift shaft	N/A	N/A	N/A		
	b) Pressurization of lift lobby	N/A	N/A	N/A		
	c) Communication in lift car	Required	Provided	MR		
	d) Fireman's switch	Required	Provided	MR		
	e) Lift signage	Required	Provided	MR		
17.	Stand by Power Supply	Required	Provided	MR		
18.	Refuge Area	N/A	N/A	N/A		
	Total area location	N/A	N/A	N/A		
19.	Fire Control Room	N/A	N/A	N/A		
	a) Detector system panel	N/A	N/A	N/A		
	b) Flow switch panel	N/A	N/A	N/A		
	c) PA system panel	N/A	N/A	N/A		
	d) Battery backup	N/A	N/A	N/A		
	e) Building floor plan	N/A	N/A	N/A		
20.	Special Fire Protection Syste Risk, if any:	NA				

The fire protection systems provided in the guest house building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/2012/4062 dated 30/10/2012 renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended.

Signature of the Inspecting Officer

Name: - M.K. Sharma Designation: - ADO (CC)

18-17 2041

Doles)

13hm/ 17/12/15