FORM 'H'

FORM FOR ISSUING FIRE SAFETY CERTIFICATE

[Refer sub - rule (1) of rule 35]

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD OUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE

NEW DELHI

No. FO D FILMS/ EN/2015/ Was 2236

Dated: 23/12/15

FIRE SAFETY CERTIFICATE

(Santokh Singh) Chief Fire Officer, Ph:011-23414250.

O/L Byle

Copy to:

- 1. M/s Spice Grill (A Unit of Dap & Company), Ground and First Floor, 39, Club Road, West Punjabi Bagh, New Delhi – 110026.
- 2. Dy. Health Officer, West Zone, SDMC, Public Health Department, Vishal Enclave, New Delhi.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 6. The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.

1/6

INSPECTION REPORT

1. Name & address of the building: M/s Spice Grill (A Unit of Dap & Company) located at Ground and First Floor, 39, Club Road, West Punjabi Bagh, New Delhi – 110026.

2. Type of Occupancy : Assembly on ground & first floor only in a building comprised of Ground + 2 Upper Floors.

: Nil

3. Type of Case : New

Ground & First Floor=Restaurant Second Floor = Residence

T

4. Details of previous NOC

5. Fire Safety directives Letter No.: Nil

6. Date of inspection : 04-12-2015

7. Name of the Inspecting Officer: Mukesh Verma ADO (MN)

8. Name and designation of Officer

from the building side : Sh. Amarjeet Singh (Prop.)

9. Year of Construction : 2008

10. Applicant's letter No. : D – 2132/HD/WZ dated 15-10-2015

	N				
S	Minimum standards on fire	NBC	Provided at	Remarks	
No	prevention and fire safety U/R	Requirements	site	MR/NMR	
	33				
1.	Access of building	3			
	 Road width 	6 m	Provided	MR	
	 Gate width 	NA	NA	NA	
	 Width of internal road 	NA	NA	NA	
2.	Number, width, Type & Arrangements of exits				
	a. Number of staircases				
	Upper floors	2	Provided 1	MR	
	 Basements 	NA	NA	NA	
	b. Width of staircases				
	Upper floors	1X1.5m, 1X1m	Provided	MR	
	Basements	NA	NA	NA	
	c. Protection of exits		3 2		
	 Fire check door 	NA	NA	NA	
	Pressurization	NA	NA	NA	
	d. No of continuous	NA	NA	NA	
	staircase to terrace		-		
	e. Width Of Corridor	NA *	NA	NA	
	f. Door Size	2m & 1m	Provided on	MR	
	*		both floors		
3.	Compartmentation				
	 Fire check door 	Required	Provided	MR	
	 Sealing of electrical 	NA	NA	NA	
	shafts				
				The second second	

		10h		NA
	• Fire Rating of shaft door	NA	NA	NA
	• Water Curtain	NA	NA	NA
	• Fire Dampers	NA	NA	INT
4.	Smoke managements System		274	NA
4.	Basements	NA	NA	MR
	• Upper floors	12 a/c per hour	Provided	IVIIC
	Fire Extinguishers		. 1 1	MR
5.	1	06 nos.	Provided	MR
,		ABC & CO ₂	Provided	MR
	TypesIS marking	ISI marked	Provided	IVIIX
	First – Aid Hose Reels			MR
6.	the I have on each	1	Provided	MIN
	floor			MR
	r at a Chara reel hase	30 m	Provided	MR
	 Length of flose reet flose Nozzle diameter 	5 min	Provided	TVIIX
	Automatic fire detection and ala	rming system		
7.	Automatic life detection and the	NR	NR	NR
	Type of detectors	NR	NR	NR
	Location of Main Panel	NR	NR	NR
	• Location of Repeater			NID.
	Panel	NR	NR	NR
	 Alternate source of 			7 117
	power	NR	NR	NR
	 Hooters' Location 	Required	Provided	MR
8.	MOEFA	NR	NR	NR
9.		1110		
1 (NIA	NA	NA
	 Basements 	NA	Provided	NR
	 Upper Floor 	NR	NR.	NR
	 Sprinkler above false 	NR		
	ceiling			Annual Management of the Control of
1	1. Internal Hydrants:	1.00	Provided	MR
	 Size of riser/down- 	100 mm	Tiovided	
	comer	4	Provided	MR
	 Number of hydrants p 	er 1	110,160	
	floor		Provided	MR
	• Hose Box	Required	1107100	
-	12. Yard Hydrants	NI A	NA	NA ·
	 Total number of 	NA	1.12	
	hydrants	NA	NÅ	NA
	Hose Box	INA		
	13. Pumping Arrangements:		()	
	• Ground Level	NIA	NA	NA
	 Discharge of main present 	ump NA NA	NA	NA
	> Head of main pump	41	NA NA	NA
	> Number of main pur		NA NA	NA
	> Jockey pump out pu	t NA	NA	NA
	> Jockey pump head	NA NA	NA NA	NA
	> Standby Pump out p	out NA	NA	NA
	> Standby Pump Head	NA NA	NA NA	NA
	> Auto Staring/Manua	al NA	177	
	stopping	S NIA	NA	NA
	> Pump House Acces	s NA	11/1	

	~18					
	ferrace level					
	Discharge of pump	450 lpm	720 lpm	MR		
			Provided			
	Head of the pump	40 m	Provided	MR		
	Power supply	Required	Provided	MR		
	Auto starting of pump	Required	Provided	MR		
	Captive water Storage for fire fighting:					
1	 Under ground tank 	NA	NA	NA		
	capacity			DY A		
	Draw off connection	NA	NA	NA		
	> Fire service inlet	NA	NA	NA		
	Access to tank	NA	NA	NA		
	 Overhead Tank capacity 	10000 litres	Provided	MR		
15	Exit Signage	Required	Provided	MR		
16.	Provision of Lifts					
	Pressurization of Lift	NA	NA	NA		
	Shaft			A CONTRACTOR OF THE PROPERTY O		
	Pressurization of lift	NA	NA	NA		
	lobby			3.7.4		
	Communication in lift	NA	NA	NA		
	Car		37.000	X 7 4		
	Fireman's Grounding	NA	NA	NA		
	Switch			211		
	Lift Signage	NA	NA	NA		
17.	Standby power supply	Required	Provided	MR		
18.	The state of the s			NA		
	> Total area	NA	NA	NA		
	Location	NA	NA	NA.		
19.	Fire control room	The second secon		N I A		
	Detector system panel	NA	NA	NA .		
	Flow Switch Panel	NA	NA	NA		
	PA System Panel	NA	NA	NA NA		
	Battery backup	NA	NA	NA		
	Building Floor Plans	NA	NA	NA 30		
20	Special Fire Protection Systems	NA	NA	NA		
	for Protection of special Risks,					
	if any;			1 0		

The fire protection systems provided in the building were test checked and found functional at

the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and tire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010/issue shortcomings as noted at serial numbers

Note In addition to the two staircases for first floor, one internal spiral staircase of width 72 cms is provided from ground floor kitchen to first floor kitchen. The staircase is segregated by means of fire check door. The residence on second floor is segregated from restaurant and served with

2. Earlier restaurant namely Punjobi By Noture at G.f. is now closed.

Signature of the Inspending Office 1/1/8
Name
Designation

Designation

Designation

Designation

Designation

Signature of the Inspecting Officer

Name

Designation