FORM 'H'

FORM FOR ISSUING FIRE SAFETY CERTIFICATE

[Refer sub - rule (1) of rule 35]

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE

NEW DELHI

No. F6/DFS/MS/S/2015/W2/02/

Dated: 01/01/16

FIRE SAFETY CERTIFICATE

Certified that the Pind Balluchi Restaurant, located at 114 to117- 119 to 122, 1st Floor, PP Tawerl, Netaji Subhash Place, Pitam Pura, New Delhi – 110036 was issued FSC vide Letter No. F6/DFS/MS/EH/2012/167 Dated- 19-01-2012. The premises was re inspected by the team officers of this department on 19-11-2015 in the presence of Mr. Himansu (Manager) and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rule, 2010 and that the premises is fit for occupancy class "Assembly" Group D with effect from 61 61 64 64 66 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on . D. J. J. J. J. L. at New Delhi by.

(Santokh Singh) Chief Fire Officer, Ph: 011 - 23414250

54

Copy to:

- 1. Deputy Health Officer (Civil Line Zone), Public Health Department (NDMC),16, Rajpur Road, Delhi 110054.
- 2. Sh. Himansu(Manager) Pind Balluchi Restaurant, 114 to117- 119 to 122, 1st Floor, PP Tawerl, Netaji Subhash Place, Pitam Pura, New Delhi 110036

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 6. Basement shall be used as per building bye laws.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.

N)14 INSPECTION REPORT

 Name & address of the building: Pind BalluchiRestaurant, located at 114 to 117-119 to 122, 1st Floor, PP Tawerl, Netaji Subhash Place, Pitam Pura, New Delhi – 110036

2. Type of Occupancy: Assembly (Restaurant) Building (Class-D)Located at 1st Floor, PP Tawerl, Netaji Subhash Place, Pitam Pura, New Delhi

3. Type of Case

: Renewal

4. Details of previous NOC

: F6/DMS/MS/2012/167 Dated 19-01-2012 -

5. Fire Safety directives Letter No.:

6. Date of inspection

: 19-11-2015

7. Name of the Inspecting Officer: DO/W & ADO (WP)

8. Name and designation of Officer

from the building side

: Sh. HIMANSU, (Manager)

9. Year of Construction

10. Applicant's letter No.

: Nil dated Nil

Sr.	Minimum standards on fire		NBC	Provided at site	Remarks
No	preve U/R 3	ntion and fire safety	Requirements		MR/NMR
1. Access of building					
	0	Road width	9mtr	Provided	MR
	9	Gate width	05 mtrs	Provided(In mall)	MR
	0	Width of internal road	NA	NA	NA
2.	Numb	er, width, Type & Arra	ngements of exit	S	
	a.	Number of staircases		The state of the s	
	0	Upper floors	2	Three Provided	MR
	٥	Basements	NA	NA	NA
	b.	Width of staircases		and the control of th	
	9	Upper floors	1 X 1.5, & 1 X 1m	Provided	MR
	0	Basements	NA	NA	NA
	C.	Protection of exits			1
	0	Fire check door	NA	NA	NA
	0	Pressurization	NA	NA	NA
		No of continuous staircase to terrace	Required	Provided(In Mall)	MR
		Width Of Corridor	NA	NA	NA
	f.	Door Size	1x2 m &1x1m,	Old case	MR

H/15

				11,112	
3.	Con	npartmentation			
		• Fire check door	NA	NA	NA
		 Sealing of electrical 	NA	NA	
		shafts	. 12 1	1 1 1 1	NA
		• Fire Rating of shaft	NA	NA	NA
		door			INA
		Water Curtain	NA	NA	NA
1		Fire Dampers	NA	NA	NA NA
4.		ke managements Syster	Control and the Control of the Contr		
	0	Dascincias	30 a/c per h		NA
5	D: 0	Upper floors	12 a/c per h	r Required	Provided
5.	Fire	Extinguishers			
	9	Total numbers	02	Provided	MR
	9	1) 1000	ABC/CO2	Provided	MR
	9	IS marking	ISI marked	Provided	
6.		– Aid Hose Reels		Trovided	MR
	Com	mon with mall &			2
		d functional			
	9	Total numbers on each	1	Provided	MR
		floor			17110
	٥	Length of hose reel hose	30 m	Provided	MR
7.	Autor	Nozzle diameter	5 mm	Provided	MR
		matic fire detection and			
	. 0	Type of detectors	NA	Provided	NA
	•	Location of Main Panel	NA	Provided	. NA
	•	Location of Repeater Panel	NA	NA	NA
	0	Alternate source of	NA	Provided	NA
		power			1 1 1
	9	Hooters' Location	NA	Provided	NA
	MOEF		Required	Provided	MR
	Public	Address System	NA	NA	NA
0.		atic Sprinkler System		- Landau - L	1177
	9	Basements	NA	NA	NA
	9	Upper Floor	NA	NA	NA
	•	Sprinkler above	NA	NA	NA
1	Y	false ceiling			
1.	Interna	l Hydrants: Common w	ith mall & fou	nd functional	
	Ф	Size of riser/down- comer	150 mm	Provided	MR
		Number of hydrants per floor	1	Provided	MR
		Hose Box	1	Provided	MD
	The second of th	ydrants		. 10 11100	MR
		The same with the same with the same of th	NA	Provided	NY A
			NA	Provided	NA
		Hose Box		TTOVICE	NA

3.	Pumping Arrangements: Commo	n with mall &	found functional		
	 Ground Level 			NA	
	 Discharge of main pump 	NA /	Provided	NA NA	
	Head of main pump	NA	Provided	NA NA	
	Number of main pumps	NA	Provided		
	Jockey pump out put	NA	Provided	NA	
	Jockey pump head	NA	Provided	NA	
	Standby Pump out put	NA	Provided	NA	
	Standby Pump Head	NA	Provided	NA	
	Auto Staring/Manual stopping	NA	Provided	NA	
	Pump House Access	NA	Provided	NA	
	 Terrace level 				
	Discharge of pump	450 lpm	Provided	MR	
	➤ Head of the pump	40 m	Provided	MR	
	Power supply	Required	Provided	MR	
	Auto starting of pump	Required	Provided	MR	
14.	Captive water Storage for fire fig		128	274	
	 Under ground tank capacity 	NA	Provided	NA	
	Draw off connection	NA	Provided	NA	
	Fire service inlet	NA	Provided	NA	
	Access to tank	NA	Provided	NA	
	 Overhead Tank capacity 	10, 000 liter	s Provided	MR	
15	Exit Signage	Required	Provided	MR	
16.	Provision of Lifts				
	Pressurization of Lift Shaft	NA	NA	NA	
	Pressurization of lift lobby	NA	NA.	NA	
	Communication in lift	NA	ŅĀ	NA	
	Fireman's Grounding Switch	NA	NA	NA	
	> Lift Signage	NA	NA	NA	
17.	Standby power supply	NA	NA	NA	
18.	Refuge Area			N.T.A.	
	> Total area	NA	NA	NA	
	> Location	NA	NA -	NA	
	Fire control room				
19.	The control toom	3.7.1	NA	NA	
19.		NA	1 17 7		
19.		NA NA	NA	NA	
19.	Detector system panelFlow Switch Panel		The second secon	NA NA	
19.	Detector system panelFlow Switch Panel	NA	NA		

1 1

-

KD	17
17	17

Special Fire Protection Systems 20. NA NA for Protection of special Risks, NA if any;

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

n view of the deemed compliance of minimum standards on fire prevention and fire safety as required under the rules the NOC issued vide Letter No. F6/DFS/MS/EH/2012/167 Dated- 19-01-2012 renewal under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

Note;-FSC for the PP Tower in which the Restaurant is located is due for renewal however the Restaurant having one separate stair(open to sky) exclusively for restaurant and other common stair open to sky. The firefighting system common with mall & found functional during inspection. The restaurant has been

Signature of the Inspecting Officer

Officer

Name Udas Ur Sigh
Designation ADA

Signature of the Inspecting

Name Sh Sumil Chaudhory
Designation Do/w