GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

E-mail:- cfohq.dlfire@nic.in No.F.6/DFS/MS/School/2016/SZ / / 25 Fax: - 011-23412593

Dated:

18/01/16

FIRE SAFETY CERTIFICATE

Certified that the building of **R.S.M Convent School**, RZ-706-707 (Old No.-6 C), Gali No.-4, Main Sagarpur, New Delhi-110046, is comprised of ground floor plus two upper floors, was issued Fire Safety Certificate by this department vide letter F6/DFS/MS/2012/School/3669 dated 05.10.2012. The School building was re-inspected by the officer concerned of this department on 31.12.2015 in the presence of Sh. Anshul Tanwar (Chairman) and found that the school management have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed as below.

(DR. G.C. MISRA) CHIEF FIRE OFFICER DELHI FIRE SERVICE

Copy to:-

1. The Manager, R.S.M Convent School, RZ-706-707 (Old No.-6 C), Gali No.-4, Main Sagarpur, New Delhi-110046.

2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 6. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

Ground plus two upper floors (R.S.M Convent School, RZ-706-707 (Old No.-6 C), Gali No.-4, Main Sagarpur, New Delhi-110046)

INSPECTION REPORT

1. Name & address of the building: R.S.M Convent School, RZ-706-707 (Old No.-6 C), Gali No.-4, Main

Sagarpur, New Delhi-110046.

Educational Type of Occupancy Renewal 3. Type of Case

F6/DFS/MS/2012/School/3669 dated 05.10.2012 4. Details of Previous NOC

5. Fire Safety directives letter No : N/A

31.12.2015 6. Date of inspection

: A.D.O. Sandeep Duggal 7. Name of Inspecting Officer

8. Name and designation of officers

Sh. Anshul Tanwar (Chairman) From the building side

2003 9. Year of Construction

S. No.	Minimu	ant's letter No. : Dec/2/15 m Standards on fire prevention and ty U/R 33	NBC/ Dt. of edu. Requirement	Provided at site	Remarks MR/NMR
		building	111	06 mtrs	M/R
•		Road width	Accessible	3.5 mtrs	IVIIIC
	•	Gate width	·	3.5 mas	-
		Width of internal road			
	Number	, Width, Type & Arrangement of Exit	S		
4.	a. Num	per of staircases		02 No's	M/R
	•	Upper Floors	02 No.	A CONTRACTOR OF THE PARTY OF TH	No basement
	•	Basements	N/A	N/A	No basement
	b. Widt	n of staircases			
	•	Upper Floor		1.09 & 1.0 mtrs	M/R
	•	Basements	N/A	N/A	No basement
	c. Prote	ction of exits			
	•	Fire check door	N/A	N/A	N/A
	•	Pressurization	N/A	N/A	N/A
	d. No.	of continuous staircases to		Trace	N/A
	terra	ace	N/A	Two	M/R
	e. Wid	Ith of Corridor	1.5 mtrs.	mtrs.	No. A CONTRACTOR OF THE PARTY O
	f. Do	or Size	100 cms	100 to 107 cms	M/R (Students less than 45 in each class
3.	Compa	rtmentation	27/4	N/A	N/A
	•	Fire check door	N/A	4.00.00000.00	N/A
	•	Sealing of electrical shafts	N/A	N/A	90 SM-91 C.C.
	•	Fire Rating of shaft door	N/A	N/A	N/A
	•	Water Curtain	N/A	N/A	N/A
	•	Fire Dampers	N/A	N/A	N/A
4.	Smoke Management System				
7.	•	Basements	N/A	N/A	No basement



Ground plus two upper floors (R.S.M Convent School, RZ-706-707 (Old No.-6 C), Gali No.-4, Main Sagarpur, New Delhi-110046)

	Upper floors	_	Natural ventilation	M/R			
	Fire Extinguishers						
5.	Total numbers	07 no's	Provided	M/R			
	Types	ABC/CO2 type	Provided	M/R			
	IS marking	ISI marked	ISI marked	M/R			
6.	First-Aid Hose Reels	T	Provided	M/R			
	 Total numbers on each floor 	Two 30 mtrs	Provided	M/R			
	 Length of hose reel hose 	5 mm	THE STREET, AND ADDRESS OF THE STREET,	M/R			
	Nozzle diameter	3 11111	Provided	IVI/ K			
7.	Automatic fire detection and alarming system						
	 Type of detectors 	N/A	N/A	N/A			
	 Location of Main Panel 	N/A N/A	N/A	N/A			
	 Location of Repeater Panel 	N/A N/A	N/A	N/A			
	 Alternate source of power 	N/A	N/A	N/A			
	Heaters' Location	1	N/A	N/A			
8.	Hooters' Location MOEFA	N/A	N/A	N/A			
2	D III A I I I I I I I I I I I I I I I I	N/A	N/A	N/A			
9. 10.	Public Address System N/A Automatic Sprinkler System						
10.	Automatic Springer System			27/4			
	Basement	N/A	N/A	. N/A			
	Ground Floor	N/A	N/A	N/A			
	Sprinkler above false ceiling	N/A	N/A	N/A			
11.	Internal Hydrants						
	Size of riser/down-comer	N/A	100 mm	N/A			
	Number of hydrants per floor	N/A	one	N/A			
	Hose Box	N/A	one	N/A			
12.	Yard Hydrants						
-	Total number of hydrants	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
13.	Pumping Arrangements						
	Ground Level						
	Discharge of main Pump	N/A	N/A	N/A			
	> Head of Main pump	N/A	N/A	N/A			
	Number of main pumps	N/A	N/A	N/A			
	Jockey Pump out put	N/A	N/A	N/A			
	Jockey pump head	N/A	N/A	N/A			
	Standby Pump out put	N/A	N/A	N/A			
	Standby Pump Head	711111111111111111111111111111111111111		N/A			
		N/A	N/A	IN/A			

N)18

Ground plus two upper floors (R.S.M Convent School, RZ-706-707 (Old No.-6 C), Gali No.-4, Main Sagarpur, New Delhi-110046)

	Auto Starting/Manual Stopping	N/A	N/A	N/A				
	Pump House AccessTerrace level	N/A	N/A	N/A				
	➤ Discharge of pump	450 I D) 6						
	> Head of the pump	450 LPM	Provided	M/R				
	> Power Supply	40 mtrs	Provided	M/R				
		N/A	N/A	N/A				
	Auto Starting of pump	N/A	Provided	N/A				
14.	Captive Water Storage for fire fighting							
	Underground tank capacity	N/A	N/A	N/A				
	Draw-off connection	N/A	N/A	N/A				
	Fire service inlet	N/A		Machine Control of the Control of th				
	Access to tank		Provided	N/A				
	Overhead Tank capacity	N/A	N/A	N/A				
		10000 ltrs	Provided	M/R				
15.	Exit Signage.	Required	Provided	M/R				
	 Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage 	N/A N/A N/A N/A N/A	N/A N/A N/A N/A N/A	N/A N/A N/A N/A N/A				
7.	Standby power supply	N/A	N/A	N/A				
18.	Refuge Area.							
	Total AreaLocation	N/A	N/A	N/A				
	Location	N/A	N/A	N/A				
9.	Fire Control Room							
	 Detector System Panel 	N/A	N/A	N/A				
	Flow Switch Panel	N/A	N/A	N/A				
	PA System Panel	N/A	N/A	2-200-00-00 to 2				
	Battery backup	NACTORIAL TABLE		N/A				
	Building Floor Plans	N/A	N/A	N/A				
- Article		N/A	N/A	N/A				
0.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A				

2/19

Ground plus two upper floors (R.S.M Convent School, RZ-706-707 (Old No.-6 C), Gali No.-4, Main Sagarpur, New Delhi-110046)

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the Fire Safety Certificate issued vide letter number F6/DFS/MS/2012/School/3669 dated 05.10.2012 renewal under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

Sanderhold

Signature of Inspecting Officer

Name:- Sandeep Duggal

Designation:- Asstt. Divisional Officer

Signature of Inspecting Officer

Name

Designation

D.O. (South West)

Dy (FO(52)