## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

Fax: 011-23412593, Ph. 011-23414333

No. F.6/DFS/MS/EH/2016/SZ/ 195

Dated: 20/01/16

## FIRE SAFETY CERTIFICATE

Certified that Adyar Ananda Bhawan Sweets & Restaurant , S-18, Green Park, Main Market, New Delhi, ground floor is for sweets shop and restaurant is running at 1<sup>st</sup> & <sup>2nd</sup> floor of the building comprised of ground plus two upper floors was granted NOC by this department vide letter No. F6/MS/DFS/EH/2007/2629 dated. 19.09.2007. The premises was re-inspected by the officer concerned of Delhi Fire Service on 06.01..2016 in the presence of Sh. Manoj Gupta (Manager) of the restaurant and observed that fire safety norms as required under Rule 33 of Delhi Fire Service Rules, 2010 have complied and that the building / premises is fit for occupancy class-D "Assembly building Restaurant" with effect from \_\_\_\_\_\_ for a period of Three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rule 2010.

Issued on ..... at New Delhi by

(Dr. G.C. Misra) Chief Fire Officer

Te time (ADO (SLO)

Copy to: -

- 1. The DHO(South Zone), Office of Deputy Health Officer, M.C.D. Health Department South Zone, Green Park, New Delhi,
- 2. The Manager, M/s Adyar Ananda Bhawan Sweets & Restaurant , S-18, Green Park, Main Market, New Delhi.

## Conditions for the validity of Fire Safety Certificate

- 1. All the Fire Safety and means of escape facilities shall be maintained in good working conditions at all time. Any lapse rendering fire safety or means of evacuation facilities non-functional shall be the responsibility of the management.
- 2. Building Sanctioning Authority may verify any deviation with regard to the construction/occupancy in the building. In case of any deviation, the fire safety certificate stands null and void.
- 3. The staff shall be trained for operating fire fighting system and mock evacuation drills be conducted at regular intervals and record be maintained.
- 4. The Basement shall be used strictly as per the provisions of Building Bye Laws.
- 5. The owner/occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form "J" [ sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in

1		INSPECTION RE	PORT		
•	1 Name & address of the building	Adyar Ananda Bhawan Sweets & Restaurant , S-18, Green Park, Main			
	2 Building Comprised of	Market, New Delhi Ground floor -(Sweetshop), 1st & 2nd floor- Restaurant (G+2 upper floors)			
	3 Type of Occupancy	Assembly building "D" Restaurant			
	4 Type of case	Renewal			
22	F				
	Details of previous NOC	F6/MS/DFS/EH/2007/2629 dated. 19.09.2007			
	6 Fire safety directives letter No	Nil			
	Date of inspection	6.01.2016			
	Name of the inspecting Officers :	D.O. (South) D.P. Bhardwaj, ADO (BCP) D.B. Mukherjee			
	9 Name and designation of officers				
	from the building side	Sh. Manoj Gupta ( Manager),			
4	Year of construction				
	11 Applicant's letter No.	Nil dated 17.12.2015 & DHO/SZ/2015/D/2213 dated 03.12.15			
S. NO.	Minimum Standards on fire prevention	NBC Requirement	Provided at site	Remarks	
	and fire safety U/R 33	•		MR / NMR	
	1 Access to building				
	1) Road width	Required	6 Mtr	MR	
	2) Gate width	N/A	N/A	N/A	
	3) Width of internal road	N/A	N/A	N/A	
	2 Number, width Type & arrangement of	exits		T	
	a. Number of staircases				
		_		145	
	1. Upper floors	Two	Provided	MR	
	2. basements	N/A	N/A	N/A	
	b. Width of staircase				
	1. Upper floors	Required Old Case	1.06 & 0.82 Mtr	MR (Old Case)	
	2. basements	N/A	N/A	N/A	
	c. Protection of exits				
į.	1. Fire check door	N/A	N/A	N/A	
	2. Pressurization	N/A	N/A	N/A	
	d. No. of continuous staircase to t	One	One	MR	
	e. Width of corridor	N/A	N/A	N/A	
			1.07 & 0.88 mtrs Provided		
		Required Old Case		MR	
	f. Door size				
3	Compartmentation.	NI/A	NI/A	N/A	
	1. Fire check door	N/A	N/A N/A	N/A	
	2. Sealing of electrical shafts	N/A N/A	N/A	N/A	
	Fire Rating of shaft door     water curtain	N/A	N/A	N/A	
	5. Fire dampers	N/A	N/A	N/A	
4	Smoke Management system.	TV//	114/71	1,47.1	
-	basement	30 a/c per hour 12 a/c per hour	N/A	N/A	
			Exhust Fans	MR	
5	upper floors Fire Extinguishers				
3	total numbers		8 Nos	MR	
	Types		ABC, Co2 Provided	MR	
	ISI marking	ISI	Yes	MR	

The street was				
6	First-Aid Hose Reels.	One	Provided	MR
	total numbers on each floor		Provided	MR
	Length of Hose reel hose	30 Mtr	Provided	MR
	Nozzle Diameter	5 MM	Provided	
7	Automatic fire detection and alarming sy	stem:-	Provided	MR
	Type of detectors	Required	Provided	MR
	location of Main Panel	Ground floor	N/A	N/A
	location of Repeater panel	N/A Required	Provided	MR
	Alternate source of power	Required	Provided	MR
	hooter's location	Required	Provided	MR
8	MOEFA	N/A	N/A	N/A
9	Public Address System.	IN/A		
10	Automatic Sprinkler System.	N/A	N/A	N/A
	basement	Required	Provided	MR
	upper floors	N/A	N/A	N/A
	sprinkler above false ceiling	13//3		
11	Internal Hydrants	Required	Provided	MR
	Size of riser/down-corner	One	Provided	MR
	Number of Hydrants per floor	One	Provided	MR
-	hose Box			
12	Yard Hydrants. total number of hydrants	N/A	N/A	N/A
		N/A	N/A	N/A
10	hose box  Pumping arrangements			
13	1. Ground level			
	a. Discharge of main Pump	N/A	N/A	N/A
	b.Head of main pump	N/A	N/A	N/A
	c.Number of main pumps	N/A	N/A	N/A
	d.jockey pump out put	N/A	N/A	N/A
	e.jockey pump head	N/A	N/A	N/A
	f. Standby Pump output	N/A	N/A	N/A
	g.Stanby Pump head	N/A	N/A	N/A
	h.Auto Starting/Manual stopping	N/A	N/A	, N/A
	pump house access	N/A	N/A	N/A
	pump needs			
	2.Terrace level			140
	a. Discharge of pump	450 & 180 LPM	Provided	MR
	b. head of the pump	35 Mtr	Provided	MR
	c. Power supply	Required	Provided	MR
	d. Auto starting of pump	Required	Provided	MR
14		N/A	N/A	N/A
	Underground tank capacity	N/A	N/A	N/A
	a. Draw-off connection	Required	Provided	MR
	b. fire service inlet	N/A	N/A	N/A
	c.Access to tank	5,000 Ltr	Provided	MR
	Over head tank Capacity	Required	Provided	MR
15	THE STATE OF THE S			
16	a. Pressurization of lift shaft	N/A	N/A	N/A
	b. pressurization of lift lobby	N/A	N/A	N/A
	c. communication in lift car	N/A	N/A	N/A
	d. Fireman's grounding switch	N/A	N/A	N/A
	e. Lift signage	N/A	N/A	N/A
	Standby power supply	Required	Provided	MR

	El control y am				
	a. detector system Panel b. Flow switch Panel c. PA system Panel d. Batter backup	N/A	N/A	N/A	
		N/A	N/A	N/A	
		N/A	N/A	N/A	
		N/A	N/A	N/A	
		N/A	N/A	N/A	
	e. Building floor plans  Special Fire Protection systems for protection of special risks, if any: No.				
20	Special Fire Frotection systems for	D. C.			

The shortcoming issued vide letter no. F6/DFS/MS/2011/EH/2580 dated 17.10.2011 has been rectify.

The fire protection systems provided in the building were checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules of NOC issued vide letter no.F6/MS/DFS/EH/2007/2629 dated. 19.09.2007 renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

Accordingly DFA is put up for your approval and signature please.

Signature of the inspecting officer D. P. Bhardwai

Name

Designation: Divisional Officer (South)

Signature of the inspecting officer

D.B. Mukherjee Name

Designation : ADO (BCP)