

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE  
NEW DELHI- 110 001

No. F6/DFS/MS/EH/2016/MDZ/168

Dated: 25/1/16

FIRE SAFETY CERTIFICATE

Certified that the "Kaanch Club situated at 33,34,35 & 55,56,57 ground floor of Aditya Mega Mall, Plot No.9D,CBD Shahdara, Delhi-32,owned/occupied by M/s A unit of Crudex LNG Petroleum Pvt. Ltd., have complied with the fire prevention and fire safety requirements in accordance with N.B.C. Part IV and verified by the officers concerned of this department on 09.11.15 in the presence of Sh.Pramod Choudhary and that the part of building (33,34,35 &55,56,57 ground floor ) is fit for occupancy Group –D 'Assembly building' (Kaanch Club) with effect from .....25/1/16 for a period of three years in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010, printed overleaf.

Issued on.....25/1/16..... at New Delhi by



(Dr.G.C.Misra)  
Chief Fire Officer  
Ph.011-23414333

O/c  
R/S

To,  
The Joint Commissioner of Police (Lic.),  
First Floor, Police Station,  
Defence Colony, New Delhi.

Copy to:-  
M/s Kaanch Club  
33,34,35 & 55,56,57 ground floor  
Aditya Mega Mall, Plot No.9D,CBD Shahdara, Delhi-32.

### CONDITIONS:

1. All the means of escape shall be kept free of all type of obstruction all the time.
2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.
5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction/ unauthorized use of land if any.
6. All comments/directions of the Licensing Department shall always be permitted and followed.
7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on [www.dfs.delhigovt.nic.in](http://www.dfs.delhigovt.nic.in)
8. "The owner /occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form'J'[sub rule(1) of rule 37] along with a copy of this certificate,six months prior to its expiry".

1. Name & address of the building: Kaanch Club running at 33,34,35 & 55,56,57 Gf at Aditya Mega Mall,CBD Shahdara, Delhi.
2. Building is comprised of : basement, Ground + two floors.
- 3.Type of Occupancy : Assembly
- 4.Type of Case : New Case
- 5.Details of Previous NOC letter : Nil
6. Fire Safety direction letter No :NBC Part IV
- 7.Date of Inspection : 09.11.2015 &20.01.16
- 8.Name of the Inspecting officers : DO Virendra Singh & ADO Suresh Singh
- 9.Name and designation of Officer  
from the building side :Sh.Pramod Choudhary (Owner)
- 10.Year of Construction :2003
11. Applicant's letter No : 586-88/Jt.C.P/Lic.(Amst.) dated 12/01/16

S.NO.	Minimum Standards on fire prevention and fire safety U/R33	NBC Requirement	Provided at Site	Remarks MR/NMR
1	Access to building	12 Mtrs.	30 Mtrs.	MR
	<ul style="list-style-type: none"> <li>• Road width</li> <li>• Gate width</li> <li>• Width of internal road</li> </ul>	4.5 Mtrs.	6 Mtrs.	MR
		N/A	N/A	N/A
2	Number, Width, Type and Arrangement of Exits			
	a. Number of Staircases			
	<ul style="list-style-type: none"> <li>• Upper Floor</li> <li>• Basement</li> </ul>	N/A	N/A	N/A
		N/A	N/A	N/A
	B. Width of Staircases			
	<ul style="list-style-type: none"> <li>• Upper Floor</li> <li>• Basement</li> </ul>	N/A	N/A	N/A
		N/A	N/A	N/A
	c. Protection of exits			
	<ul style="list-style-type: none"> <li>• Fire check door</li> <li>• Pressurization</li> </ul>	N/A	N/A	N/A
		N/A	N/A	N/A
	e. No. of continuous staircases to terrace	N/A	N/A	N/A
	g. Width of Corridor	N/A	N/A	N/A
	h. Door Size	2 m	2.0 & 1.60 M	MR
3	Compartmentation.			
	<ul style="list-style-type: none"> <li>• Fire check door</li> <li>• Sealing of electrical shafts</li> <li>• Fire rating of shaft door</li> <li>• Water curtain</li> <li>• Fire Dampers</li> </ul>	N/A	N/A	N/A
		Required	Sealed	MR
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
4	Smoke Management System.			
	<ul style="list-style-type: none"> <li>• Basement</li> <li>• Upper floor</li> </ul>	N/A	N/A	N/A
		Required	Provided	MR
5.	Fire Extinguisher			
	<ul style="list-style-type: none"> <li>• Total numbers</li> <li>• Types</li> <li>• IS marking</li> </ul>	04 nos.	06 Nos.	MR
		ABC & Co2	ABC & Co2	MR
		ISI marked	ISI marked	MR





		Required	Provided	MR
17	Standby power supply			
18	Refuge Area.			
	• Total area	N/A	N/A	N/A
	• Location	N/A	N/A	N/A
19	Fire Control Room			
	• Detector system panel	N/A	N/A	N/A
	• Flow switch panel	N/A	N/A	N/A
	• PA system panel	N/A	N/A	N/A
	• Batter backup	N/A	N/A	N/A
	• Building Floor Plans	N/A	N/A	N/A
20	Special Fire Protection systems for protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested checked and found functional at the time of inspection. The fire protection arrangements & exit as required under the law are independent from other part of building.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rule 2010.

*Singh*  
20.10.2016

Signature of the Inspecting Officer

Name :-Suresh Singh

Designation:ADO(Shah.)

DO(ED)

Submitted for approval please.

Dy CFO (NS2)

*Vingh*  
20/01/16