FORM 'H' FORM FOR ISSUING FIRE SAFETY CERTIFICATE

[Refer sub - rule (1) of rule 35]

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE

No. F6/DFS/as/cinema/2016/62/139

Dated: 20/01/16

FIRE SAFETY CERTIFICATE

Certified that the M2K Entertainment Pvt Ltd,plot no 4.Road no. 44, community center, Pitampura, New Delhi comprised B1+B2 +Ground + 03 Upper Floors was issued FSC vide Letter No. F6/DFS/MS/2012/2630 dated 20/07/2012. The premises was re inspected by the officers concerned of this department on 22-12-2015 in the presence of Mr. Parbhaker,(Manager) and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rule, 2010 and that the premises is fit for occupancy class "Mercantile & Assembly Building" Group F & Group D with effect from Mercantile 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on . 20. . o. 1. 1. L. . . . at New Delhi by.

(Santokh Singh) Chief Fire Officer, Ph: - 011-23414250

Copy to:

Sh Parbhaker(Manager), M2K Entertainment Pvt Ltd,plot no 4.Road no. 44, community center, Pitampura, New Delhi

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 6. Basement shall be used as per building bye laws.
- 7. The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.
- 8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 9. All the doors, Exits and internal roads must be kept free from any obstruction.

INSPECTION REPORT

Name & address of the building: M2K Entertainment Pvt Ltd,plot no
 Road no. 44, community center, Pitampura, New Delhi

2. Type of Occupancy

; Class- F (Mercantile)

3. Type of Case

: Renewal

4. Details of previous NOC

: F6/DFS/MS/2012/2630 dated 20/07/2012

5. Fire Safety directives Letter No.: Letter No. F6/DFS/MS/BP/1611 Date 21-07-2003

6. Date of inspection

: 22-12-2015

7. Name of the Inspecting Officer: DO/W & ADO (WP)

8. Name and designation of Officer

from the building side

: Mr. Parbhaker, (Manager)

9. Year of Construction

: 2004-5

10. Applicant's letter No.

: Nil Dated Nil

| S | Minin | num standards on fire | BBL | Provided at | Remarks |
|-----|------------------|---------------------------|-----------------|--------------|--|
| No | | | Water Comment | | STATE OF THE PROPERTY OF THE P |
| INO | 33 | ntion and fire safety U/R | Requirements | site | MR/NMR |
| 1. | 25,005 | ss of building | <u> </u> | | |
| 1. | 710003 | Road width | 09mtrs | 24mtr. | MR |
| | | Gate width | 5 mtr | Provided | MR |
| | | Width of internal road | 6 m | Provided(old | MR |
| | | width of internal road | OIII | case) | IVIK |
| 2. | Numb | er, width, Type & Arrang | ements of exits | cuse) | |
| | a. | | | | |
| | • | Upper floors | 2. | 4 provided | MR (As ber be |
| | • | Basements | 2+1 Ramb | Provided | MR |
| | b. | Width of staircases | | | Fig. Sugar-sup |
| | • | Upper floors | 2x1.5mtrs | Old case | MR |
| | • | Basements | 2x1.5mtrs | Old case | MR |
| | c. | Protection of exits | | | |
| | • | Fire check door | Required | Provided | MR |
| | • | Pressurization | NA | NA | NA |
| | d. | No of continuous | 02 | Provided | MR |
| | | staircase to terrace | | | |
| | li con | Width Of Corridor | Old case | Old case | MR Being |
| | f. | Door Size | | | old case |
| | | | Old case | Old case | MR Being |
| | | | | | old case |
| 3. | Compartmentation | | | | |
| | • | Fire check door | Required | Provided | MR |
| | • | Sealing of electrical | Required | Provided | MR |
| | | shafts | | | |
| | • | Fire Rating of shaft | Required | Provided | MR |
| | | door | D | | |
| | • | Water Curtain | Required | Provided | NR |
| | • | Fire Dampers | Required | Provided | NR |

| 4. | Smoke managements System | | 7 | *************************************** | | | |
|----------|--|---------------|-----------|---|--|--|--|
| (AR) = V | Basements | Required | Provided | NR | | | |
| | Upper floors | Required | Provided | MR | | | |
| 5. | Fire Extinguishers | 1104 | 1101100 | | | | |
| ٥. | Total numbers | 22 | Provided | MR | | | |
| | | ABC,CO2 type | Provided | MR | | | |
| | • Types | ISI marked | Provided | MR | | | |
| _ | IS marking | 151 marked | Provided | IVIK | | | |
| 6. | First – Aid Hose Reels | | | | | | |
| | • Total numbers on each | 1 3 | Provided | MR | | | |
| | floor | | | | | | |
| | Length of hose reel | | | | | | |
| | hose | 30 m | Provided | MR | | | |
| | Nozzle diameter | | | | | | |
| | | 5 mm | Provided | MR | | | |
| 7. | Automatic fire detection and a | | | | | | |
| | Type of detectors | Required | Provided | MR | | | |
| | Location of Main | Ground floor | Provided | MR | | | |
| | Panel | | | | | | |
| | Location of Repeater | Each floor | Provided | MR | | | |
| | Panel | | | | | | |
| | Alternate source of | Required | Provided | MR | | | |
| | power | Required | Provided | MR | | | |
| | Hooters' Location | Required | Provided | MR | | | |
| 8. | MOEFA | Required | Provided | MR | | | |
| 9. | Public Address System | Required | Provided | MR | | | |
| 10. | Automatic Sprinkler System | Required | Trovided | IVIIX | | | |
| 10. | Basements | Required | Provided | NR | | | |
| | 2017 C. S. 400 C. S. C. C. C. C. S. S. S. C. | | Provided | | | | |
| | Upper Floor | Required | | MR | | | |
| | Sprinkler above false | Required | Provided | MR | | | |
| | ceiling | | 1 | <u> </u> | | | |
| 11. | Internal Hydrants | | | · · · · · · · · · · · · · · · · · · · | | | |
| | Size of riser/down- | 150 mm | Provided | MR | | | |
| | comer | | | | | | |
| | No. of hydrants per | 3 | Provided | MR | | | |
| / | floor | - 4 | | | | | |
| 7 | Hose Box | 3 | Provided | MR | | | |
| 12. | Yard Hydrants | | | | | | |
| | Total no. of hydrants | Required | Provided | MR | | | |
| | Hose Box | Required | Provided | MR | | | |
| 13. | Pumping Arrangements | -1 | | | | | |
| | Ground Level | | | | | | |
| | Discharge of main pun | np 2850LPM | Provided | MR | | | |
| | > Head of main pump | 60 mtr | Provided | MR | | | |
| | Number of main pump | | Provided | MR | | | |
| | > Jockey pump out put | 180 lpm | Provided | MR | | | |
| | > Jockey pump head | 60 m | Provided | MR | | | |
| | Standby Pump out put | | Provided | MR | | | |
| | Standby Pump Head | 60 mtr | Provided | MR | | | |
| | > Auto Staring/Manual | Required | Provided | | | | |
| | stopping | Required | riovided | MR | | | |
| | ➤ Pump House Access | Daguinad | Drovida 1 | MD | | | |
| | Terrace level | Required | Provided | MR | | | |
| | Discharge of pump | NT A | NIA | 1271 | | | |
| | Head of the pump | NA | NA | NA | | | |
| | | NA | NA | NA | | | |
| | > Power supply | NA | NA | NA | | | |

| | Auto starting of pump | NA | NA | NA | | | |
|-----|--|----------------|----------|----|--|--|--|
| 14. | Captive water Storage for fire f | ighting | | | | | |
| | Under ground tank capacity | 1,00,00 litres | Provided | MR | | | |
| | > Draw of connection | Required | Provided | MR | | | |
| | > Fire service inlet | Required | Provided | MR | | | |
| | > Access to tank | Required | Provided | MR | | | |
| | Overhead Tank capacity | 20, 000 litres | Provided | MR | | | |
| 15 | Exit Signage | Required | Provided | MR | | | |
| 16. | Provision of Lifts Lift is of capsule type | | | | | | |
| | Pressurization of Lift | Required | Provided | MR | | | |
| | Shaft | Required | Provided | MR | | | |
| | Pressurization of lift lobby | Required | Provided | MR | | | |
| | Car | Required | Provided | MR | | | |
| | Fireman's GroundingSwitchLift Signage | Required | Provided | MR | | | |
| 17. | Standby power supply | Required | Provided | MR | | | |
| 18. | Refuge Area | Troquires | | | | | |
| 10. | > Total area | NA | NA | NA | | | |
| | > Location | NA | NA | NA | | | |
| 19. | Fire control room | | | | | | |
| | Detector system panel | Required | Provided | MR | | | |
| | > Flow Switch Panel | Required | Provided | MR | | | |
| | > PA System Panel | Required | Provided | MR | | | |
| | Battery backup | Required | Provided | MR | | | |
| | Building Floor Plans | Required | Provided | MR | | | |
| 20. | Special Fire Protection Systems for Protection of special Risks, if any; | NA | NA | NA | | | |

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view of the deemed compliance of minimum standards on fire prevention and fire safety as required under the rules the NOC issued vide letter no. F6/DFS/MS/2012/2630 dated 20/07/2012 renewal under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

Note;- Terrace pump of 900lpm was seen in earlier inspection has been removed although it has been mentioned in directive issued vide letter dated 21/07/2003.

Signature of the Inspecting Officer

Signature of the Inspecting Officer

Name Sh Suril Choud

Designation

Designation 10/w

Eff bestel 16.
Whil above terrace Part 2