

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/MS/DFS/SZ/EH/2016/ 233

Dated: 10/02/16

FIRE SAFETY CERTIFICATE

Certified that Shree Bhagatram's restaurant located at shop no.3, 4 & 5, ground floor, Vasant Square Mall Vasant Kunj, New Delhi-110070 comprised of 02 basements, lower and upper ground floor + three upper floors. The restaurant is running at ground floor with 50 seat covers owned/occupied by Mr. Gautam Khanna. The premises was inspected by the officer concerned of this department in the presence of Mr. J.P.Singla, Manager on 09/01/2016 and found that the said restaurant have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises fit for occupancy class Group - D, Assembly Building (Restaurant) with effect from 10/02/16 for a period of **three years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010.

Issued 10/02/16 at New Delhi by.


(Dr. G. C. Misra)
Chief Fire Officer
Tel: 011-23414333

g.c.
9.2.16

Copy to:

- (1) The Dy. Health Officer,
SDMC, South Zone,
Aurobindo Marg, Green Park
New Delhi
- (2) M/s Shree Bhagatram's
Shop No.3, 4 & 5, Ground Floor, Vasant Square Mall
Vasant Kunj, New Delhi-110070

Following fire safety directives must be adhered to:-

1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
3. The trained fire fighting staff should be available round the clock.
4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
5. The basement shall be used as per the provisions of NBC
6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any
7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building:- Shree Bhagatram's, Shop No.3, 4 & 5, Ground Floor, Vasant Square Mall, Vasant Kunj, New Delhi-110070.
 2. Type of occupancy:- Assembly, Group – D, Restaurant
 3. Type of case:-New
 4. Details of previous NOC:-Nil.
 5. Fire safety directives No.- Nil
 6. Date of inspection:-31/07/2014
 7. Name of the inspecting officer:- D.B.Mukherjee, A.D.O.(BCP)
 8. Name & designation of officer From the building side:- Mr. J.P.Singla, Manager
 9. Year of construction:-
 10. Applicant's letter no:- DHO/SZ/HD/14/D-/503 dated: 02/06/2014
- Building is comprised of 02 basements, lower and upper ground floor + three upper floors. Restaurant is running at Ground Floor only.

Sl. No.	Minimum Standards on fire Prevention and fire safety U/R 33	BBL/NBC Requirement	Provided at Site	Remarks MR/NMR
1.	Access to Building			
	1) Road width	09 mtrs.	Provided	MR
	2) Gate width	05 mtrs.	Provided	MR
	3) Width of internal road	06 mtrs.	Provided	MR
2.	Number, Width Type & Arrangement of Exits			
	A. Number of staircases	Provided and maintained by Mall		
	1. Upper floors	N/A	N/A	N/A
	2. Basements	N/A	N/A	N/A
	B. Width of staircase			
	1. Upper floors	N/A	N/A	N/A
	2. Basements	N/A	N/A	N/A
	C. Protection of exits			
	1. Fire check door	Required	Provided by mall	MR
	2. Pressurization	Required	Provided by mall	MR
	D. No. of continuous staircase to terrace	Required	Provided by mall	MR
	E. Width of corridor	Required	Provided by mall	MR
	F. Door size	02 mtrs.	Provided 03 nos. of exit doors having width of 2 mtrs., 2 mtrs. and 01 mtrs.	MR
3.	Compartmentation			
	1) Fire check door	Required	Provided by Mall	MR
	2) Sealing of electrical shafts	Required	Provided by Mall	MR
	3) Fire rating of shaft door	Required	Provided by mall	MR
	4) Water curtain	Required	Provided by mall	MR
	5) Fire Dampers	Required	Provided by mall	MR
4.	Smoke Management System			
	1) Basements	30 a/c per hour	Provided by Mall	MR
	2) Upper floors	12 a/c per hour	Provided by Mall	MR
5.	Fire Extinguishers			
	Provided and maintained by Mall			
	1) Total numbers	ISI Marked	05Nos.	MR
	2) Types		ABC, Co2	MR
	3) ISI marking		Yes	MR

6.	First-Aid Hose Reel	Provided and maintained by Mall		
	1) Total number of each floor	01	Provided	MR
	2) Length of hose reel hose	30 m	Provided	MR
	3) Nozzle diameter	5 mm	Provided	MR
7.	Automatic Fire Detection & Alarming System	Provided and maintained by Mall		
	1) Type of detectors	Smoke & heat	Provided	MR
	2) Location of main panel	Lower Ground Floor	Provided	MR
	3) Location of repeater panel	Required	Provided	MR
	4) Alternate source of power	Required	Provided	MR
	5) Hooter's Location	Required	Provided	MR
8.	MOEFA	Provided and maintained by Mall		
9.	Public Address System	Provided and maintained by Mall		
10.	Automatic Sprinkler System	Provided and maintained by Mall		
	1) Basement	Required	Provided	MR
	2) Upper floors	Required	Provided	MR
	3) Sprinkler above false ceiling	Required	Provided	MR
11.	Internal Hydrants	Provided and maintained by Mall		
	1) Size of riser/down-comer	Required	Provided	MR
	2) Number of hydrants per floor	Required	Provided	MR
	3) Hose box	Required	Provided	MR
12.	Yard Hydrants	Provided and maintained by Mall		
	1) Total number of hydrants	Required	Provided	MR
	2) Hose box	Required	Provided	MR
13.	Pumping Arrangement	Provided and maintained by Mall		
	1) Ground level			
	a) Discharge of main pump	4500lpm	Provided	MR
	b) Head of main pump	60m	Provided	MR
	c) Number of main pump	02	Provided	MR
	d) Jockey pump out put	180lpm 02 nos.	Provided	MR
	e) Jockey pump head	60m	Provided	MR
	f) Stand by pump output	4500lpm	Provided	MR
	g) Stand by pump head	60m	Provided	MR
	h) Auto starting/Manual stopping	Required	Provided	MR
	2) Terrace level			
	a) Discharge of pump	N/A	N/A	N/A
	b) Head of pump	N/A	N/A	N/A
	c) Power supply	N/A	N/A	N/A
	d) Auto starting of pump	N/A	N/A	N/A
14.	Captive Water Storage for Fire Fighting	Provided and maintained by Mall		
	1) Under ground tank capacity	2,50000 ltrs.	Provided	MR
	a) Draw-off connection	Required	Provided	MR
	b) Fire service inlet	Required	Provided	MR
	c) Access to tank	Required	Provided	MR
	d) Over head tank capacity	30000 ltrs.	Provided	MR
15.	Exit Signage.	Provided and maintained by Mall		
16.	Provision of Lifts.	Provided and maintained by Mall		
	a) Pressurization of lift shaft	Required	Provided	MR
	b) Pressurization of lift lobby	Required	Provided	MR
	c) Communication in lift car	Required	Provided	MR
	d) Fireman's switch	Required	Provided	MR
	e) Lift signage	Required	Provided	MR

17.	Stand by Power Supply	Provided and maintained by Mall		
18.	Refuge Area			
	Total area	N/A	N/A	N/A
	location	N/A	N/A	N/A
19.	Fire Control Room	Provided and maintained by Mall		
	a) Detector system panel	Required	Provided	MR
	b) Flow switch panel	Required	Provided	MR
	c) PA system panel	Required	Provided	MR
	d) Battery backup	Required	Provided	MR
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risk, if any: Provided	MR		

The fire protection system provided in the mall and restaurant were checked and found functional at the time of inspection. The mall has been issued NOC/FSC vide letter no.F6/DFS/MS/Mall/2015/SZ/611 dt.:27/04/2015.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rules 35 of the Delhi Fire Service Rules 2010.

Accordingly DFA is put up for sign. please.



D.B. Mukherjee
14/1/2016

Signature of the inspecting officer

Name :- D.B. Mukherjee.

Designation :- Asstt. Divisional Officer(BCP)

20/1/2016
(South)

[Signature]
19/1/16

By CRG. S2
[Signature]
19/1/16