## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001.

E-mail:- <u>cfohq.dlfire@nic.in</u>
No. F.6/DFS/MS/EH/2016/SZ

Fax: - 011-23412593

Dated:

24/02/16

## **FIRE SAFETY CERTIFICATE**

Certified that the building of M/s Bemisaal Reloaded (a unit of Bemisal Food Co.), B-26,27, GF & FF, B-Block Community Centre, Janak Puri, New Delhi-110058, is comprised of basement, upper ground floor plus two upper floors. The restaurant is running at ground floor plus one upper floor only. The above restaurant was issued NOC by this department vide Letter No. F6/MS/DFS/2005/EH/1471 dated 12.07.2005 owned/occupied by M/s Bemisal Reloaded (a unit of Bemisal Food Co.). The Restaurant building was re-inspected by the officers concerned of this department on 10.02.2016 in the presence of Sh. Alok Narang (Partner) and found that the management have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the restaurant building (at ground floor plus one upper floor only) is fit for occupancy class Group D "Assembly Building" w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed overleaf.

(DR. G.C. MISRA)
CHIEF FIRE OFFICER
DELHI FIRE SERVICE

6) C Sam

Copy to:-

 The Manager, Bemisal Reloaded (a unit of Bemisal Food Co.), B-26,27, GF & FF, B-Block Community Centre, Janak Puri, New Delhi-110058.

 The Deputy Health Officer, West Zone (SDMC), Public Health Department, Vishal Enclave, New Delhi. (Letter No. D-230/HD/WZ dated 25.01.2016) Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 6. Basement shall be used as per the building bye laws.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

Building is comprised of basement, upper ground plus two upper floors but Restaurant is running at ground plus one upper floor only (Bemisal Reloaded (a unit of Bemisal Food Co.), B-26,27, GF & FF, B-Block Community Centre, Janak Puri, New Delhi-110058)

**INSPECTION REPORT** 

## 1. Name & address of the building: Bemisal Reloaded (a unit of Bemisal Food Company), B-26,27, GF & FF, B-Block, Community Centre, Janak Puri, New Delhi-110058 2. Type of Occupancy Group D (Assembly Building) 3. Type of Case 4. Details of Previous NOC F6/MS/DFS/2005/EH/1471 dated 12.07.2005. 5. Fire Safety directives letter No : Nil. 6. Date of inspection 10.02.2016 7. Name of Inspecting Officer A.D.O. Sandeep Duggal 8. Name and designation of officers From the building side Sh. Alok Narang (Partner) 9. Year of Construction Before 2003 : D-230/HD/WZ dated 25.01.2016 10. Applicant's letter No. Minimum Standards on fire prevention and fire NBC/ BBL S. Provided at Remarks MR/NMR No. safety U/R 33 Requirement site 1. Access to building Road width M/R Accessible 12 mtrs Gate width Width of internal road 2. Number, Width, Type & Arrangement of Exits (Restaurant is running at ground plus one upper floor) Number of staircases Upper Floors 02 No.'s 02 No.'s M/R Basements N/A N/A N/A b. Width of staircases M/R 190 & 120 Cms 150 cms Upper Floor N/A 190 & 120 Cms N/A Basements Protection of exits N/A N/A N/A Fire check door Pressurization N/A N/A N/A d. No. of continuous staircases to N/A One N/A terrace N/A Opening in hall N/A e. Width of Corridor f. Door Size 165, 200 & 93 M/R cms on GF & 190, 188 & 104 cms on FF 3. Compartmentation N/A N/A N/A Fire check door Sealing of electrical shafts N/A N/A N/A Fire Rating of shaft door N/A N/A N/A Water Curtain N/A N/A N/A Fire Dampers N/A N/A N/A (Restaurant is running at ground plus one upper floor) Smoke Management System 4. N/A Exhaust fan N/A Basements with ducts are provided

Building is comprised of basement, upper ground plus two upper floors but Restaurant is running at ground plus one upper floor only (Bemisal Reloaded (a unit of Bemisal Food Co.), B-26,27, GF & FF, B-Block Community Centre, Janak Puri, New Delhi-1 10058)

	Linnar floors	Community Centre, Janak Pi		58)		
	Upper floors	_	Natural Ventilation	M/R		
5.	Fire Extinguishers	7 5 7 5 7 5 7 5 7 5 7 5 7 5 7 5 7 5 7 5				
	Total numbers	06 no's	Provided	M/R		
	Types	ABC/CO <sub>2</sub>	Provided			
	IS marking	ISI marked	ISI marked	M/R		
6.	First-Aid Hose Reels		M/R			
	Total numbers on ground floor	unning at ground plus				
	Length of hose reel hose	One/Floor	Provided	M/R		
	Nozzle diameter	30 mtrs	Provided	M/R		
	TOTAL GIATRICE	5 mm	Provided	M/R		
7.	Automatic fire detection and alarming sys	5				
	Type of detectors	N/A	Smoke detector	N/A		
	Location of Main Panel	N/A	Provided			
	Location of Repeater Panel	N/A	At GFloor	N/A		
	Alternate source of power	N/A	N/A	N/A		
	Hooters' Location	N/A	DG Set 125 KVA	N/A		
3.	MOEFA		At exit	N/A		
٥.	MOEFA	Required	Provided	M/R		
).	Public Address System	Required	Provided	M/R		
LO.	Automatic Sprinkler System					
	Basement	· N/A	Provided	N/A		
	Ground Floor & First Floor	N/A	Provided	N/A		
	Sprinkler above false ceiling	N/A	N/A	N/A		
1.	Internal Hydrants					
	Size of riser/down-comer	Required	100 MM	M/R		
	Number of hydrants	Required	One	M/R		
_	Hose Box	Required	One	M/R		
.2.	Yard Hydrants					
	Total number of hydrants	N/A	N/A	N/A		
2	Hose Box	N/A	N/A	N/A		
3.	Pumping Arrangements					
	Ground Level					
	Discharge of main Pump	N/A	N/A	N/A		
	Head of Main pump	N/A	N/A	N/A		
	Number of main pumps	N/A	N/A	N/A		
	Jockey Pump out put	N/A				
	Jockey pump head		N/A	N/A		
	Standby Pump out put	N/A	N/A	N/A		
	Standby Pump Head	N/A	N/A	N/A		
	Auto Starting/Manual Stopping	N/A	N/A	N/A		
	The state of the s	N/A	N/A	N/A		



2)4

Building is comprised of basement, upper ground plus two upper floors but Restaurant is running at ground plus one upper floor only (Bemisal Reloaded (a unit of Bemisal Food Co.), B-26,27, GF & FF, B-Block Community Centre, Janak Puri, New Delhi-110058)

	B-20,27, GF & FF, B-Block Collinaint	)					
		N/A	N/A	N/A			
	Pump House Access						
	Terrace level	450 LPM & 180	900 LPM	M/R			
	Discharge of pump	LPM	provided				
	Head of the pump	30 mtrs	Provided	M/R			
	Power Supply	Required	Provided	M/R			
	Auto Starting of pump	N/A	N/A	N/A			
	3						
14.	Captive Water Storage for fire fighting						
	Underground tank capacity	N/A	N/A	N/A			
	Draw-off connection	N/A	N/A	N/A			
	Fire service inlet	N/A	N/A	N/A			
	Access to tank	N/A	N/A	N/A			
	Overhead Tank capacity	10,000 ltrs	15000 ltrs.	M/R			
		Required	Provided	M/R			
15.	Exit Signage.						
16.	Provision of Lifts.			(No Lift)			
	Pressurization of Lift Shaft	N/A	N/A	N/A			
	Pressurization of Lift lobby	N/A	N/A	N/A			
	Communication In lift Car	N/A	N/A	N/A			
	Fireman's Grounding Switch	N/A	N/A	N/A			
	Lift Signage	N/A	N/A	N/A			
		Required	Provided	M/R			
17.	Standby power supply	ricqui ou		•			
35							
18.	Refuge Area.  Total Area	N/A	N/A	N/A			
	Location	N/A	N/A	N/A			
19.	Fire Control Room						
	Detector System Panel	N/A	N/A	N/A			
	Flow Switch Panel	N/A	N/A	N/A			
	PA System Panel	N/A	N/A	N/A			
	Battery backup Building Floor Plans	N/A	N/A	N/A			
		N/A	N/A	N/A			
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A			





Building is comprised of basement, upper ground plus two upper floors but Restaurant is running at ground plus one upper floor only (Bemisal Reloaded (a unit of Bemisal Food Co.), B-26,27, GF & FF, B-Block Community Centre, Janak Puri, New Delhi-110058)

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the Fire Safety Certificate issued vide letter number F6/MS/DFS/2005/EH/1471 dated 12.07.2005 renewal under rule 37 of the Delhi Fire Service Rules 2010 is recommended.

Note:- Restaurant name has been changed from Bemisaal restaurant to Bemisaal Reloaded

Signature of Inspecting Officer

Name:- S.K. Tomar

Designation:- Divisional Officer

Signature of Inspecting Officer

Name: Sandeep Duggal

Designation:- Asstt. Divisional Officer

Dy.C.F.O.( South Zone)

