GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

E-mail:- cfohq.dlfire@nic.in

Fax:- 011-23412593

No. F.6/DFS/MS/GH/2016/ \$2 332

Dated: 01 | 03 /16

FIRE SAFETY CERTIFICATE

Certified that the **Hotel Picasso Prive** located at A-14, Naraina Vihar, New Delhi-110028 is comprised of Basement, Stilt, Ground floor plus three upper floors, using basement as storage, stilt floor as parking, ground floor used as parking, reception & office etc., first & second floor each having front side 04 guest rooms and back side as owner's residence respectively, third floor having 13 guest rooms (Total 21 guest rooms), a pantry with staff room in temporary shed on terrace owned/occupied by Sh. Kulmohan Singh & Sh. Gurjeet Singh. The guest house building was re-inspected by the officers concerned of this department on 16.02.2016 in the presence of Sh. Gurjeet Singh (Owner) and found that the owner have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class residential w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed overleaf.

(DR. G.C. MISRA) CHIEF FIRE OFFICER DELHI FIRE SERVICE Phy- 011-23414333

Copy to:-

- 1. The Joint Commissioner of Police (Lic.)
 1st floor, P.S., Defence Colony, New Delhi.
 (Ref. No.2444-48/Joint C.P./Lic.(H), Dated 13.11.2015)
- 2. Sh. Kulmohan Singh & Sh. Gurjeet Singh (Owner), Hotel Picasso Prive, A-14, Naraina Vihar, New Delhi-110028. (Ref.No. Nil dated 01.02.2016)

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The basement shall be used strictly as per the provisions of the building bye laws.
- 7. The owner/ occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

		NSPECT	ION REPORT		
	1. Name & address of the bu	ilding: F	total Picasso P.	HIVE A-14 NAM	aina Vihan N.
	2. Type of Occupancy	:	Residential (quest House	and Imar, No
	3. Type of Case		New Case/Renew		
	4. Details of Previous NOC		Letter No.		Date
	5. Fire Safety directives lette	rNo :	0.000	Transported to the second seco	
	6. Date of inspection	:	16.0	2.2016	
	7. Name of Inspecting Office	r :		nax \$ A.D.O	P. C. Nahina
	8. Name and designation of			nus prince	1 3 · Isaniga
	From the building side		Sh. Gurjeet Si	ngh & Sh. Jasi	neet Singh
	9. Year of Construction		2014-15		
	10. Applicant's letter No.		Nil dated or	02.2016	
S.	Minimum Standards on fire		NBC/BBL	Provided at	Remarks
No.	prevention and fire safety U/R	33	Requirement		MR/NMR
1.	Access to building		Tregatierierie	3100	THE THIRD
	Road width		Accessible	12 mts	MR
	Gate width		11 00 000.5	02 mts	MR
	C 11 10 10 10 10 10 10 10 10 10 10 10 10		1	Ud mts	LIK
7	• Width of internal road				
2.	Number, Width, Type & Arran	gement	of Exits		
	a. Number of staircases				
	• Upper Floors		Two	Two	MR, OIS. Case L
	Basements		Two	Two	MR
	b. Width of staircases				
	 Upper Floor 		150cms	152 cms, 152 cms	MR
	 Basements 		150cms	153 cms, 110 cms	
	c. Protection of exits				The second section of the second section of the second sec
	 Fire check door 		bo	-	-
	pressurization				The state of the s
	d. Not of continuous staircase	s to			Annual Control of the
	terrace			One	And the party an
	e. Width of Corridor			145cms	
	f. Door Size			80 cms + 20 S cms	And the same and t
				OCCIND ROUS CIND	
3.	Compartmentation				
	Fire check door		•-7	Provided	MR
	Sealing of electrical shafts	afts		Sealed	MR
	 Fire Rating of shaft doc 	or	a strategic calculations in a strategic calculation in the strategic calculation and the strategic calculations and	JUITER	/*//\
	 Water Curtain 		***************************************		
	• Fire Dampers	1	-		
1		The Control of the Co			
4.	Smoke Management System				
	* Basements		30 a/c per	Exhaust fans are Provided	MR
	 Upper floors 		hour	Natural Ventilation	
				MALLISA VENDIANE	mR MR



n s	* A!	16	× ×		
		12 a/c per hour			
5.	Fire Extinguishers			Ţ r	- 15
	 Total numbers 	Three at each Floor	Provided	0 0	
	Types	ABC, Coz, WCoz	- do -	MR	
	IS marking	ISI marked	1SI Marked	MR	
6.	First-Aid Hose Reels		13) Marked	MR	-
	 Total numbers on each floor 	One	Provided	MR	
	Length of hose reel hose	30 m	- do -	MR	
	 Nozzle diameter 	5 mm	- de-	MR	
7.	Automatic fire detection and alarming	system			
	 Type of detectors 				
1	 Location of Main Panel 	_			
	 Location of Repeater Panel 				
	 Alternate source of power 	_			
	 Hooters' Location 				
8.	MOEFA	Required	Provided	MR	-
9.	Public Address System	- do -	- do -		
10.	Automatic Sprinkler System	1	1 - 200 -	L MR	
	 Basement 	Required	Provided	MR	
	 Upper Floor 	Refused	Provided	MR	
	 Sprinkler above false ceiling 		1 DOVIDED		
11.	Internal Hydrants	1:	<u> </u>		
1	 Size of riser/down-comer 		-		
	 Number of hydrants per floor 	N	-	- 1	
	 Hose Box 				
12.	Yard Hydrants		J.		
	7 Total number of hydrants		And the second s		
: 	* Hose Box		Agencia.		
13.	Pumping Arrangements	12			
	 Ground Level 				
	Discharge of main Pump			-	
	Head of Main pump		·	-	
	Number of main pumps				
	> Jockey Pump out put	Managers			
	Jockey pump head	-			
	Standby Pump out put				-
	> Standby Pump Head		i.		
	Auto Starting/Manual				
	stopping				



NIT A-14, Naraina Vihar, New Delli- 110028.

	NEW DEIM - 110078					
	Pump House Access	•	•			
	 Terrace level 	8				
	Discharge of pump	450 LPM Each	450 LPM Each	MR (02 Pum		
	Head of the pump	30M Each	30 M Each	MR		
	Power Supply	Required	Provided	MR		
	Auto Starting of pump					
14.	Captive Water Storage for fire fighting			f		
	 Underground tank capacity 		Persona	-		
	Draw-off connection	-		-		
	Fire service inlet		Provided	MR		
	Access to tank			_		
	 Overhead Tank capacity 	10000 Ctr	10000 Cfr	MR		
15.	Exit Signage.	10000 CFr Required	Provided	MR		
16.	Provision of Lifts.					
	 Pressurization of Lift Shaft 	•	-	-		
	 Pressurization of Lift lobby 					
	 Communication In lift Car 		P. 11.1	Da 0		
	• * Fireman's Grounding Switch		Provided	MR		
	 Lift Signage 	Required - do -	- do -	MR		
		- do -	-do-	MR		
17.	Standby power supply	Required	D.G. Set of 62.5 KVA	MR		
18.	Refuge Area.					
and the second s	> Total Area	•	_	-		
	> Location			-		
19.	Fire Control Room	9				
allo suf 1	Detector System Panel	•		Name of the last o		
	Flow Switch Panel					
	PA System Panel					
	Batter backup					
	Building Floor Plans					
		×	-	-		
20.	Special Fire Protection System for Protection of special Risks, if any:	-		-		



The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the above substantial compliance of the minimum standards on fire prevention and Fire Safety measures required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial numbers.

Note: - The Guest House Building is comprised of Basement, Stilt, Ground floor plus three Upper Floors. Basement used as storage, Stilt as parking, Ground as reception, Offices parking, first floor as 04 quest rooms in front side, Owner's residence at back side. Second floor 04 quest rooms in Front side, Owner's residence at back side, third floor having 13 quest rooms and a pantry with staff room in temporary shed on terrace. FSC is recommended for 21 quest rooms only.

0x 18/2/18

Signature of Inspecting Officer

Name S. K. Tomar

Designation Divisional Officer

Signature of Inspecting Officer

Name P.S. Dahiya

Designation Applt. Divisional Officer

A CFOCSZO AM

1912/16