GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001

No. F6 DFS | MS | School | 2016 | NO2 / 341

Dated: 03/03/16

FIRE SAFETY CERTIFICATE

Certified that the Amity International School at Mayur Vihar Phase-1,Delhi-91,comprised of basement,ground plus four upper floors owned/occupied by Amity International School have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officers concerned of this department on 05.02.2016 in the presence of Sh.Dharmpal Singh (Manager-HR)and found that the building is fit for occupancy class 'B''Educational Building' with effect from period of three years in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010, printed overleaf.

(Dr.G.C.Misra) Chief Fire Officer Ph.011-23414333

9c lls

To.

The Principal Amity International School Mayur Vihar Phase-1,Delhi-91

Copy to:-

The Dy.Director of Education D-Block, Anand Vihar, Delhi.

CONDITIONS:

1. All the means of escape shall be kept free of all type of obstruction all the time.

2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of

3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall

4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.

5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction if any.

6. Basement shall be used as per BBL. 7. "The owner /occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form'J'[sub rule(1) of rule 37] along with a copy of this certificate, six months

8. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on

www.dfs.delhigovt.nic.in.

1. Name & address of the building: Amity International School, Mayur Vihar Phase -1, Delhi -91.

2. Building is comprised of : Basement,ground +4, upper floor

3. Type of Occupancy : Educational

4. Type of Case : Additional/Alternation

5. Details of Previous FSC :F.6/DFS/MS/School/2015/NDZ/12 dated

02.01.15 (For G+3 upper floors)

6. Fire Safety direction letter No :F6/DFS/MS/BP/2014/129 dated 12.05.14

7. Date of Inspection : 05.02.16

8. Name of the Inspecting officers: ADO R.K.Yadav & DO Virendra Singh

9. Name and designation of Officer:

from the building side : Sh.Dharm pal Singh (Manager-HR).

10. Year of Construction :2005 & 2015

11. Applicant's letter No : AIS/MV/APP/2016. Dated 20.01.2016.

NO.	Minimum Standards on fire	NBC Part IV	Provided at	Remark			
	prevention and fire safety U/R33	Requirement	Site	S			
1	Access to building						
ν.	Road width	06 Mtrs.	15 Mtrs.	MR			
	Gate width	4.5 Mtrs.	4.5 Mtrs.	MR			
	 Width of internal road 	N/A	N/A	N/A			
2	Number, Width, Type and Arrangement of Exits						
	a. Number of Staircases						
	 Upper Floor 	03 Nos	03 Nos.	MR			
	 Basement 	02 Nos	02 Nos.	MR			
	B. Width of Staircases						
	 Upper Floor 	1.5 M	.1.5 M	MR			
	 Basement 	1.5 M	1.5 M	MR			
	c. Protection of exits	N/A	N/A	N/A			
	 Fire check door 	N/A	N/A	N/A			
	 Pressurization 	N/A	N/A	N/A			
	e. No. of continuous staircases to terrace	2 nos.	2 Nos.	MR			
	g. Width of Corridor	1.5 M	2.0 M	MR			
	h. Door Size	1.0 Mtrs	1.0 Mtrs	MR			
3	Compartmentation.						
	Fire check door	Required	Provided	MR			
	 Sealing of electrical shafts 	Required	Sealed	MR			
	 Fire rating of shaft door 	N/A	N/A	N/A			
	 Water curtain 	N/A	N/A	N/A			
	 Fire Dampers 	N/A	N/A	N/A			
4	Smoke Management System.						
	Basement	N/A	N/A	N/A			
	Upper floor	N/A	N/A	N/A			
5.	Fire Extinguisher						
	Total numbers	25 Nos.	28 Nos.	MR			
	• Types	ABC & Co2	ABC & Co2	MR			
	IS marking	ISI marked	ISI marked	MR			

re	Total numbers of each floor	2 nos.	2 nos.	MR			
	Length of hose reel hose	30 M	30 M	MR			
	Nozzle diameter	5 mm	5 mm	MR			
7	Automatic fire detection and alarming system.						
	Tune of detectors	N/A	N/A	N/A			
	Type of detectors	N/A	N/A	N/A			
	Location of main panel	N/A	N/A	N/A			
	Location of repeater panel Alternate source of power	N/A	N/A	N/A			
-	Hooter's location	N/A	N/A	N/A			
0	MOEFA	Required	Provided	MR			
8 9	Public address System.	Required	Provided	MR			
10	Automatic Sprinkler System.	rtequired	1101100				
10	Basement	Required	Provided	MR			
		N/A	N/A	N/A			
	upper floor	N/A	N/A	N/A			
4.4	sprinkler above false ceiling	IN//A	14// (1777			
11	Internal Hydrants	100 MM	100 MM	MR			
	size of riser/down-comer	2 Nos.	2 Nos.	MR			
	Number of hydrants per floor	2 Nos.	2 Nos.	MR			
	Hose Box	Z NOS.	2 1105.	IVIIX			
12	Yard Hydrants.		N1/0	NI/A			
	Total number of hydrants	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
13	Pumping Arrangements.	N/A	N/A	N/A			
	Ground Level	N/A	N/A	N/A			
	Discharge of main Pump	N/A	N/A	N/A			
	Head of Main Pump	N/A	N/A	N/A			
	Number of main pumps	N/A	N/A	N/A			
	Jockey pump out put	N/A	N/A	N/A			
	Jockey pump head	N/A	N/A	N/A			
	Standby pump out put	N/A	N/A	N/A			
	Standby pump Head	N/A	N/A	N/A			
	Auto Starting /Manual stopping	N/A	N/A	N/A			
	Pump House Access	N/A	N/A	N/A			
	Terrace Level						
	Discharge of pump	900 LPM	900 LPM	MR			
	Head of the Pump	40 M	40 M	MR			
	Power supply	Required	Provided	MR			
	Auto Starting of pump	Required	Provided	MR			
14	Captive Water Storage for Fire Fighting.	N/A	N/A	N/A			
, ,	Underground tank capacity	N/A	1,00,000 ltrs.	MR			
	Draw-off connection	N/A	N/A	N/A			
	Fire service inlet	N/A	N/A	N/A			
	Access to tank	N/A	N/A	N/A			
15	Overhead Tank capacity	25,000 Ltrs.	25,000 Ltrs.	MR			
16	Exit Signage.	Required	Provided	MR			
17	Provision of Lifts.	-					
17	Pressurization of Lift Shaft	N/A	N/A	N/A			
	Pressurization of Lift lobby	N/A	N/A	N/A			
	Communication in lift car	N/A	N/A	N/A			
	Firemen's grounding switch	N/A	N/A	N/A			
	Firemen's drollnding SWIICH	1.4/7.7	1 1// 1				

	Ot Here a war a upply	N/A	N/A	N/A
18	Standby power supply	N/A	N/A	N/A
	Refuge Area.		N/A	N/A
	 Total area 	N/A	5 (100)	
	Location	N/A	N/A	N/A
19	Fire Control Room	N/A	N/A	N/A
19	D. I. I	N/A	N/A	N/A
		N/A	N/A	N/A
	 Flow switch panel 	20 00000	Provided	MR
	 PA system panel 	Required	Provided	IVIIX
	Battery backup	Required	Provided	MR
	- "" El DI	N/A	N/A	N/A
			N/A	N/A
20	Special Fire Protection systems for	N/A	IN/A	18// 3
	protection of special Risks, if any:			
1				

The fire protection systems provided in the building were tested/ checked functional at the time of inspection. This department had already issued FSC vide letter no. F.6/DFS/MS/School/2015/NDZ/12 dtd.02/01/15.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rule 2010.

Signature of the Inspecting Officer

Name:-R.K.Yadav Designation:-ADO (LN)

DO(ED) Submitted for approval please.