GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001.

E-mail:- cfohq.dlfire@nic.in

Fax:- 011-23412593

No.F.6/DFS/MS/GH/2016/ 52/364

Dated: 08/03/14

FIRE SAFETY CERTIFICATE

Certified that the **Hotel Singh Continental** located at 8A/6, WEA, Karol Bagh, New Delhi-110005 is comprised of Basement, ground floor plus four upper floors, using basement as hall/storage, ground floor as reception & 02 guest rooms, first, second & third floor each having 07 guest rooms respectively, fourth floor having one room for storage (Total 23 guest rooms) was issued NOC by this department vide letter No.F.6/DFS/MS/GH/2012/4376 dated 26.11.2012 owned/occupied by Sh. Kanwal Jeet Singh. The guest house building was re inspected by the officers concerned of this department on 25.02.2016 in the presence of Sh. Rajesh Singh (Manager) and found that the owner have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class residential w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed overleaf.

(DR. G.C. MISRA) CHIEF FIRE OFFICER DELHI FIRE SERVICE Ph:- 011-23414333

Copy to:-

- The Joint Commissioner of Police (Lic.)
 1st floor, P.S., Defence Colony, New Delhi.
 (Ref. No. 1921/Joint C.P./Lic.(H), Dated 29.09.2015)
- Sh. Kanwal Jeet Singh (Owner)
 Hotel Singh Continental, 8A/6,
 WEA, Karol Bagh, New Delhi 110005.
 (Ref. No. Nil dated 20.01.2016 received on 17.02.2016)

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The basement shall be used strictly as per the provisions of the building bye laws.
- 7. The owner/ occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

| | INSPEC | TION REPORT | | : 1 | | |
|--|--|--|--|--|--|--|
| | Name & address of the building : | Hotel Singh Co | Intinental SAL | WEA KONIA | | |
| | , | Residential (| Guest House) | M.D-05 | | |
| | 3. Type of Case : | New Case/Rener | wal | | | |
| | 4. Details of Previous NOC : | Letter No. F. GINES MS GHI2012 437 Pate 26.11.2012 | | | | |
| | a solicity an ecenves retter NO . | - | | | | |
| | 6. Date of inspection : | 2.5. | 32.2016 | | | |
| | 7. Name of Inspecting Officer : | D.O S.K. TO | max \$ A.D.C | P.S. Dahina | | |
| 8) | 8. Name and designation of officers | | | | | |
| | From the building side : | Sh. Rajes | h Singh (Mana | iger) | | |
| | 9. Year of Construction | Before 200 | 1 0 | Ø · | | |
| S. | 10. Applicant's letter No. | Nil dated 20. | | | | |
| No. | Minimum Standards on fire | NBC/BBL | Provided at | Remarks | | |
| 1. | prevention and fire safety U/R 33 | Requirement | site | MR/NMR | | |
| | Access to building | | - | | | |
| | Road width | Accessible | 09 mtr | MR | | |
| | • Gate width | - | 165 cms | MR | | |
| | Width of internal road | | e-man. | | | |
| 2. | Number, Width, Type & Arrangement | of Exits | The second secon | | | |
| | a. Number of staircases | | | | | |
| | • Upper Floors | One | One | me alda | | |
| | Basements | Two | Two | MR, Old Case | | |
| | b. Width of staircases | 7.00 | 7.00 | | | |
| | Upper Floor | - | 121cms to 139cm | NO OLLO | | |
| | Basements | | | MR, Old Cas | | |
| | c. Protection of exits | The second secon | 116 cma, 121 cms | - 200 - | | |
| | Fire check door | Required | Provided | And O | | |
| | • pressurization | Negarea | 1 sovided | MR | | |
| | d. No. of continuous staircases to | | | | | |
| | terrace | | One | CONTROL NAME OF THE PARTY OF TH | | |
| | e. Width of Corridor | | | - | | |
| | f. Door Size | | 165cms | | | |
| | | - | 82 cms x 20 Scms | - | | |
| 3. | Compartmentation | | | | | |
| | Fire check door | | | A STATE OF THE PROPERTY OF THE | | |
| | Sealing of electrical shafts Fire Rating of shaft door | | 0 | Angeles and the second of the | | |
| | | | Sealed | | | |
| | Water Curtain | | | • | | |
| | • Fire Dampers | | • | | | |
| 4. | Smoke Management System | | | b | | |
| | The state of the s | | The same of the sa | | | |
| | ogociii@ii63 | 30 a/c per | Exhaust Fons | MR | | |
| Name of the latest to the late | Upper floors | hour | are Provided | | | |
| | | | Yafarai Ventilatio | H MR | | |

| | N 2 | 28 | | |
|------------------|--|--------------------------------|------------|--------------|
| | | 12 a/c per hour | - | |
| 5. | Fire Extinguishers | | | |
| | Total numbers | Two at each floor Cog, WCoz | Provided | MR |
| | • Types | ISI marked | -dg- | MR |
| 6. | IS marking First-Aid Hose Reels | ISI Market | 1SI Marked | MR |
| <u>U</u> ; | | 0. | 0 | |
| | | <u>Ohe</u> 30 m | Provided | MR |
| | Length of hose reel hoseNozzle diameter | 5 mm | - do - | MR |
| 7 | | | 15-do- | MR |
| 7. | Automatic fire detection and alarming | system | T | |
| | • Type of detectors | | | + |
| | Location of Main Panel Location of Barratan Barratan | - | - | + |
| | Location of Repeater Panel | 1 | | |
| | Alternate source of power | - | . — | + i · |
| and and other to | Hooters' Location | - | | |
| 8. | MOEFA | Required | Provided | MR |
| 9. | Public Address System | -do- | - do- | MR |
| 10. | Automätic Sprinkler System | | | |
| | Basement | Required | Provided | MR |
| | Upper Floor | - | | |
| | Sprinkler above false ceiling | | | |
| 11. | Internal Hydrants | | | 1: |
| | Size of riser/down-comer | | | + |
| | Number of hydrants per floor | _ | | |
| | Hose Box | | (113 | |
| 12. | Yard Hydrants | | J. | |
| | Total number of hydrants | | | |
| - | * Hose Box | | | |
| 13. | Pumping Arrangements | × | | ļ.· |
| | Ground Level | | | |
| | Discharge of main Pump | • | | |
| | > Head of Main pump | - | | |
| İ | > Number of main pumps | | | / |
| | > Jockey Pump out put | | | Name - |
| | Jockey pump headStandby Pump out put | | | |
| | Standby Pump Head | | - | _ |
| | Standby Fullip ReadAuto Starting/Manual | | - L | - |
| | stopping | | | |
| | 310441118 | | | |

M

8A/6, WEA, Karol Bagh, New Delli - 110005.

| | Pump House Access | - | - | | | |
|-----|--|--------------------|----------------------|----------------|--|--|
| | Terrace level | | | H ₂ | | |
| | Discharge of pump | _ | 450 LPM | MR, Old Co. | | |
| | Head of the pump | *** | | - da | | |
| | Power Supply | Required | 30 M Provided | -do- | | |
| | Auto Starting of pump | | | | | |
| 14. | Captive Water Storage for fire fighting | | | | | |
| | Underground tank capacity | | - | * * | | |
| | Draw-off connection | s.inner | - | _ | | |
| | Fire service inlet | | _ | _ | | |
| | Access to tankOverhead Tank capacity | | - | - | | |
| | | | 6000 Ltr | MR, Old Co | | |
| 15. | Exit Signage. | Required | Provided | MR | | |
| 16. | Provision of Lifts. | · Y | | - · | | |
| | Pressurization of Lift Shaft | | - | | | |
| | Pressurization of Lift lobby | - | | - ; | | |
| | Communication In lift Car Fireman's Grounding Switch Lift Signage | | Provided | MR | | |
| | | Raniel | - do - | | | |
| | | reguerrea | | MR | | |
| | | -do- | -do- | MR | | |
| 17. | Standby power supply | Required Required | D.G. Set of 82.5 KVA | MR | | |
| 18. | Refuge Area. | | | 0 3 0 | | |
| | Total Area | | | - | | |
| | > Location | | | | | |
| | | | | : | | |
| 19. | Fire Control Room | | | | | |
| | Detector System Panel Flow Switch Panel PA System Panel Batter backup Building Floor Plans | - | _ | 8 | | |
| | | - | - | | | |
| | | | - | | | |
| | | | | | | |
| | | | | _ | | |
| 20. | Special Fire Protection System for Protection of special Risks, if any: | | _ | | | |

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter no. $\frac{f \cdot 6/\Delta FS/MS}{GH} \frac{GH}{30/3} \frac{4376}{4376}$ dated $\frac{26 \cdot H \cdot 20/2}{20/3}$ renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

Note: The owner of the Guest House is rectified all the shortcomings which are raised by this department vide letter No. F. 6/DFS/MS/GH/2015/2386 dated 18.11.2015. Renewal of FSC is recommended please.

Signature of Inspecting Officer

Name S. K. Tomar

Designation Divisional Officer

Signature of Inspecting Officer

Name P.S. Dahiye

Designation Appth. Divisional Officer