GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE **NEW DELHI-110 001.**

E-mail:- cfohq.dlfire@nic.in

Fax:- 011-23412593

No. F.6/DFS/MS/GH/2016/ 32 1438

Dated: 18/3/16

FIRE SAFETY CERTIFICATE

Certified that the Hotel Silver Arc located at 17A/6, WEA, Karol Bagh, New Delhi-110005 is comprised of Basement, ground floor plus four upper floors, using basement as hall/storage and shops, ground floor as reception, store and shops, first, second & third floor each having 07 guest rooms and one store room respectively (Total 21 guest rooms), a staff pantry, hall and store on fourth floor was issued NOC by letter No.F.6/DFS/MS/GH/2013/162 dated vide department owned/occupied by Sh. Inderjeet Singh. The guest house building was re-inspected by the officers concerned of this department on 08.03.2016 in the presence of Sh. Karan (Manager) and found that the owner have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class residential w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to dompliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed overleaf.

Issued on 18/3/2016 at New Delhi.

(DR. G.C. MISRA) CHIEF FIRE OFFICER **DELHI FIRE SERVICE**

Ph:- 011-23414333

Copy to:-

1. Sh. Inderjeet Singh (Owner), Hotel Silver Arc, 17A/6, WEA, Karol Bagh, New Delhi-110005. Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The basement shall be used strictly as per the provisions of the building bye laws.
- 7. The owner/ occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

Basement, Ground Floor plus Four upper Floors

	INSPEC	TION REPORT			
	1. Name & address of the building:	Hotel Silver A	re. 17Ala WE	A Karal Book	
	2. Type of Occupancy	Residential (C	Droest House)	11, 764.01 204911	
		: New Case/Renewal			
	1 5		SFS/MS/GH/2013/16	9 Date 09,04.	
	5. Fire Safety directives letter No	:	ar spring surger spre	Dutc of of	
	6. Date of inspection	. 08	3.63.2016		
	7. Name of Inspecting Officer	: N.O. C.K. To	mar & A.D.0	Condeel Negar	
	8. Name and designation of officer	5		Sunders Bugge	
	From the building side	Sh. Kar	an (Manager)		
	9. Year of Construction	: Betore 200			
	10. Applicant's letter No.		NIL CFORM J		
5.	Minimum Standards on fire	NBC/BBL	Provided at	Remarks	
۷o.	prevention and fire safety U/R 33	Requirement	1	MR/NMR	
1.	Access to building	. 1	3100	·	
	Road width	Accessible	08 mts	MR	
	Gate width	a,	110 cms		
	Width of internal road		110 CHIS		
2.	Number, Width, Type & Arrangemen	t of Evito			
	a. Number of staircases	LOIENTS		-	
	* Upper Floors	1	1	*,	
	Basements	One	One	MR, Old Co	
	b. Width of staircases	100	700	MR	
	• Upper Floor			arrange and the second designation of the second se	
	Basements	5	12Scms	MR, Old Cas	
	c. Protection of exits		175cms, 180cms	MR	
	• Fire check door				
			*		
	• pressurization			.,	
	d. No. of continuous staircases to terrace				
	1.1001.1	-	One	: : :	
	e. Width of Corridor f. Door Size	~	245cms, 130cms		
	3126		87 cms x 204 cms		
3.	Compartmentation		- Or construct terms		
	Fire check door		•		
	 Sealing of electrical shafts 	-	Sealed	E	
	 Fire Rating of shaft door 		veried		
	 Water Curtain 				
	 Fire Dampers 				
4.	Smoke Management System				
	* Basements	20 7	Exhaust Fons	1	
	Upper floors	30 a/c per hour	are Provided	MR	
_	opper noors	Hour	Natural Ventilation	MR	

		2/10		
		12 a/c per hour		
5.	Fire Extinguishers		35	
	Total numbers	Two at each floor	Provided	MR
١.	Types	Co, WCo, ABC	- do-	MR
	IS marking	ISI marked	1s1 Marked	MR
6.	First-Aid Hose Reels		LIST MARCH	
	 Total numbers on each floor 	One	Provided	MR
	Length of hose reel hose	30 m	-do-	Me
	 Nozzle diameter 	5 mm	-do:	MR
7.	Automatic fire detection and alarming			
	 Type of detectors 	-		
	 Location of Main Panel 	-		
	 Location of Repeater Panel 			
	 Alternate source of power 			
	Hooters' Location			
8.	MOEFA	Required	Provided	h o
9,	Public Address System	-do-	1 sovided	MAR
10.	Automatic Sprinkler System	7	αο -	I MK
	 Basement 	Required	Provided	MR
	 Upper Floor 	regioner	· I sovided	MIN
	 Sprinkler above false ceiling 			
11.	Internal Hydrants	1		
	Size of riser/down-comer			
	 Number of hydrants per floor 	•		-
	* Hose Box			
12.	Yard Hydrants		1.	
	 Total number of hydrants 			
	* Hose Box		-	
13.	Pumping Arrangements			
	* Ground Level			
	Discharge of main Pump	-		
	Head of Main pump			
	Number of main pumps			
	> Jockey Pump out put			
	Jockey pump head	-		
	Standby Pump out put	Omeran I		
	Standby Pump Head			
	Auto Starting/Manual			
	stopping			

17A/6, WEA, Karol Bagh, New Delhi-110005.

. 1	
11/10	
NI	

100							
	> Pump House Access	-		-			
	• Terrace level						
	Discharge of pumpHead of the pump	*****	456 LPM	MR, Old Co	216		
	> Power Supply			MR			
	> Auto Starting of pump	Required	20 M Provided	MR			
	or pump						
14.	Captive Water Storage for fire fighting						
	 Underground tank capacity 	*					
	Draw-off connection			-			
	Fire service inlet	~	S				
	Access to tank	-					
	 Overhead Tank capacity 		6000 Ctr	MR, Old C	316		
15.	Exit Signage.	Required	Provided	MR	100		
16.	Provision of Lifts.	· ·		. a			
	 Pressurization of Lift Shaft 		•	-			
	 Pressurization of Lift lobby 		-				
	• Communication In lift Car		Provided	MR			
	• Fireman's Grounding Switch	Required	-do-	MR			
	 Lift Signage 	Required - do -	-do-	, MR			
17.	Standby power supply	Required	Provided D.G. Set of 88 KVA	MR			
10	D-fu-						
18.	Refuge Area. > Total Area	T					
	> Location		5-				
	25531511	_					
19.	Fire Control Room			-			
	 Detector System Panel 	_		- :			
	 Flow Switch Panel 						
	PA System Panel			4			
	Batter backup		_				
	 Building Floor Plans 						
***************************************			-	-			
20.	Special Fire Protection System for						
	Protection of special Risks, if any:		_				
				**			
At an overland and other states							

2/12

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter no. 6.6 | Second | Secon

Signature of Inspecting Officer

Name S. K. Tomar

Designation Divisional Officer

Sauden John

Signature of Inspecting Officer

Name Sandeep Auggal

Designation ASSH. Divisional Officer