### GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI- 110001

NO. F6/DFS/MS/ Motel/2016/SZ/ 432

DATED: 17/03/16

#### FIRE SAFETY CERTIFICATE

Dr. G.C. Misra Chief Fire Officer

# Copy To:-

- 1. The Addl. Commissioner of Police, Lice), First floor, PS Defence Colony, New Delhi.
- 2. Mr. Harbans Kaur, M/s Lilywhite Motel at Kh. No.772,773,and 774, Chattarpur main road, New Delhi.

# Conditions for the validity of fire safety certificate

- 1. All the fire safety and means of escape facilities shall be maintained in good working conditions at all time. Any lapse rendering fire safety or means of evacuation facilities rendering non-functional shall be the responsibility of the management.
- 2. Building Sanctioning authority may verify any deviation with regard to the construction/occupancy in the building. In case of any deviation, the fire safety certificate stands null and void.
- 3. The staffs shall be trained for operating fire fighting system and mock evacuation drills be conducted at regular intervals and record be maintained.
- 4. The basement shall be used strictly as per the provisions of Building Bye laws.
- 5. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules-2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form "J" [ sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>

1	Name & add		New Delhi	7.112,110,and 111, 011		
2	Type of Occ	cupancy	Residential building "A" ( Mo	otel)		
3	Building cor		B+ G+1st floor ( Total 19 gue	est rooms)		
4	Type of cas		Renewal			
5			F6/DFS/MS/Motel/2013/72 d	lated 14.03.2013		
6			F6/DFS/MS/BP/2005/1658 Dated 09.08.2005			
7	Date of insp		10.03.2016			
8			DO Dharampal Bhardwaj, Al	DO D.B. Muykherjee		
9		designation of officers	Mr. Harbans Kaur			
	from the bu					
10	Year of con		2007			
	Applicant's		Nil. Dated 23.02.2016			
11 S. NO.	Minimum 9	Standards on fire	NBC Requirement	Provided at site	Remarks	
3. 140.		and fire safety U/R			MR / NMR	
	33					
1	Access to		6 Mtr	Provided	MR	
	2) Gate wid		5 Mtr	Provided	MR	
2		internal road	N/A	N/A	N/A	
				114/71		
2		vidth Type & arrangem of staircases	left of exits			
		TOTAL SECURITION	Five	Five Provided	MR	
	1. Upper flee 2. baseme		Six	Six Provided	MR	
		f staircase	OIX .			
	1. Upper fl		1.25 Mtr	1.25 Mtr each Provided	MR	
	2. baseme		1.25 Mtr	1.25 Mtr each Provided	MR	
		ion of exits	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2			
	1. Fire che		Required	Provided	MR	
	2. Pressur		N/A	N/A	N/A	
	d. No. of	continuous staircase	Required	Five Provided	MR	
	to te	rrace	Α			
	e. Width o	f corridor	1.5 Mtr	Provided	MR	
	f. Door siz		Required	1 Mtr Provided	MR	
3	Comparti	nentation.	у.			
	1. Fire che		Required	Provided	MR	
	2. Sealing	of electrical shafts	Required	Provided	MR	
	3. Fire Ra	ting of shaft door	N/A	N/A	N/A	
	4. water c	urtain	N/A	N/A	N/A	
	5. Fire da		N/A	N/A	N/A	
4	Smoke M	anagement system.	30 a/c per hour 12			
			30 a/c per hour 12 a/c per hour	Exhust Fans provided	MR	
	basemen			Natural Ventilation	MR	
	upper floo			Traction of the second		
5		nguishers		20 Nos. Provided	MR	
	total num	bers		ABC, CO2, Water	MR	
	Types		 ISI	Provided	MR	
	ISI marki		101	in a		
6		Hose Reels.	Five	Provided	MR	
		bers on each floor	30 Mtr	Provided	MR	
		f Hose reel hose	5mm	Provided	MR	
	Nozzle D	nameter	John T.	Majorita de la companya della companya della companya de la companya de la companya della compan		

#### **INSPECTION REPORTS**

7	Automatic fire detection and ala	arming eyetom			
/		Comico Dravida d	MD		
	Type of detectors  location of Main Panel	Required	Somke Provided	MR	
	A COME SAME SAME TO A STATE OF THE SAME SAME SAME SAME SAME SAME SAME SAM	Required	Ground Provided	MR	
	location of Repeater panel	N/A Required	N/A  Rottory Pools in Provided	N/A	
	Alternate source of power		Battery Backup Provided	MR	
_	hooter's location	Required	Different place Provided	MR	
8	MOEFA	Required	Provided	MR	
9	Public Address System.	Required	Provided	MR	
10	Automatic Sprinkler System.				
	basement	Required	Provided	MR	
	upper floors	Required	Provided	MR	
	sprinkler above false ceiling	N/A	N/A	N/A	
11	Internal Hydrants				
	Size of riser/down-corner	150MM	Provided	MR	
	Number of Hydrants per floor	Required	Five Provided	MR	
	hose Box	Required	Flve Provided	MR	
12	Yard Hydrants.				
	total number of hydrants	Five	Provided	MR	
	house box	Five	Provided	MR	
13	Pumping arrangements	-			
	1. Ground level	3	1 14 14 14 14 14 14 14 14 14 14 14 14 14		
	a. Discharge of main Pump	N/A	N/A	N/A	
	b.Head of main pump	N/A	N/A	N/A	
	c.Number of main pumps	N/A	N/A	N/A	
	d.jockey pump out put	N/A	N/A	N/A	
	e.jockey pump head	N/A	N/A	N/A	
	f. Standby Pump output	N/A	N/A	N/A	
	g.Stanby Pump head	N/A	N/A	N/A	
	h.Auto Starting/Manual stopping	N/A	N/A	N/A	
	pump house access	N/A	N/A	N/A	
	2.Terrace level				
	a. Discharge of pump	1620 & 180 LPM	Provided	MR	
	b. head of the pump	40 Mtr	Provided	MR	
	c. Power supply	Required	Provided	MR	
	d. Auto starting of pump  Captive water storage for fire	Required	Provided	MR	
4.0	The state of the s				
14	fighting  1 Underground tank conscity	50 000 l +r	Provided	MR	
	Underground tank capacity     Draw off capacities	50,000 Ltr	Provided	MR	
	a. Draw-off connection	Required	Provided	MR	
	b. fire service inlet	Required		MR	
	c.Access to tank	Required	Provided		
	Over head tank Capacity	20,000 Ltr	Provided	MR	
15 16	Exit Signage.	Required	Provided No. 1 if Provided	MR	
	Provision of lifts.	No Lift Provided		NI/A	
	a. Pressurization of lift shaft	N/A	N/A	N/A	
	b. pressurization of lift lobby	N/A	N/A	N/A	
	c. communication in lift car	N/A	N/A	N/A	
	d. Fireman's grounding switch	N/A	N/A	N/A	
	e. Lift signage	N/A	N/A	N/A	

**INSPECTION REPORTS** 

17	Standby power supply	Required	Provided	MR
18	Refuge Area.	·	Not Required	
	total area location			
19	Fire control room			*
	a. detector system Panel	Required	Provided	MR
	b. Flow switch Panel	N/A	N/A	N/A
	c. PA system Panel	Required	Provided	MR
	d. Batter backup	Required	Provided	MR
	e. Building floor plans	N/A	N/A	N/A
20	Special Fire Protection system for protection of special risks, if any:		Co2 Fire Extinguishers Provided	MR

The fire protection systems provided in the building were checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules of NOC issued vide letter no. F6/DFS/MS/Motel/2013/72 dated 14.03.2013 renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

Accordingly DFA/is put up for your approval and signature please.

Signature of the inspecting officer

Name Dharampal Bhardwaj

Designation : Divisional Officer

Signature of the Inspecting Officer

Name D.B. Mukherjee

**Designation ADO (BCP)** 

DCFO (SZ)