GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS; DELHI FIRE SERVICE, NEW DELHI-110001.

No.F6/DFS/MS/Hospital/2016/SZ /559

Dated: 8/4/16

FIRE SAFETY CERTIFICATE

Certified that the Rockland Hospital/ Nursing Home (A unit of Rockland Hospitals Ltd.) Plot No.HAF-B, Phase-1, Sector-12, Dwarka, New Delhi comprised of two basements, Ground plus five upper floors was granted NOC by this department vide letter no. F6/DFS/MS/Hospital/2011/3533 dated 15.11.2011. The building was re-inspected by the officers concerned of this department on 05.04.2016 in presence of Sh. Ashwani R.P (Vice President) & Sh. Sushil Kumar (Admn.) and found that the premises have deemed complied with fire prevention requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the Building/premises is fit for occupancy class Group C "Institutional building" Sub-Division C-1 with effect from Specific Service, 2010, printed overleaf.

(Aful Garg)
Dy. Chief Fire Officer
(011-26189168)

Copy to:

1. Authorised Signatory, Rockland Hospital, HAF Pocket-B, Sector-12, Phase-1, Dwarka, New Delhi-110075.

CONDITIONS

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
- 5. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
- 6. All comments / directions of licensing Department shall always be permitted and followed.
- 7. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J', (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.

	INSPE	CTION REPORT			
	Name & address of the building	ROCKLAND Hospital, HAF Pocket-B, Sector-12, Phase-1, Dwarka, New Delhi.			
2	Type of Occupancy	Institutional C-1 (Hosp	ital)		
3		Renewal			
1		F/6/DFS/MS/Hospital/2011/3533 Dated 15.12.2011			
	Betails of provides 115	F/6/DFS/MS/BP/Hosp			
5	The salety and area letter.	05.04.2016 D O Sanjay Kumar Tomar ADO S.P. Bhardwaj			
6	Date of hispection				
7	Traine of the second	Sh. Ashwani (Vice-President) & Sh. Sushil Kumar (Admn.) 2010-2011			
3	Name and designation of officers from the building side				
9	Year of construction	Nii doted 24.02.004	6		
0	Applicant's letter No.	NII dated 31.03.201	Nil dated 31.03.2016		
		Two Basements, Ground + Five upper Floors			
S. N O.	Minimum Standards on fire prevention and fire safety U/R 33	Requirements As per NBC	Provided at site	Remarks MR/NMR	
1	Access to building				
-	1) Road width	6 Mtrs.	24 Mtrs.	MR 1	
	2) Gate width	6 Mtrs.	6 Mtrs.	MR "	
	3) Width of internal road	5.8 to 6 Mtrs.	5.8 to 6 Mtrs.	MR being old ca	
2	Number, width Type & arrangement of exits				
	a. Number of staircases				
	1. Upper floors	Two Nos.	Two Nos.	MR -	
	2. basements	Two Nos.	Two Nos.	MR	
	b. Width of staircase				
	1. Upper floors	2 Mtrs.	2 Mtrs.	MR	
		140, 202 Cms.	140, 202 Cms.	MR being old ca	
	2. basements	140, 202 01115.	1-10, 202 Offic.		
	c. Protection of exits	Poquired	Provided	MR -	
	1. Fire check door	Required			
	2. Pressurization d. No. of continuous staircase to	Required	Provided	M/R	
	d. No. of continuous staircase to terrace	2 Nos.	2 Nos.	MR 1	
	e. Width of corridor	206, 240 & 300 Cms.			
	f. Door size	2.05 Mtrs.	2.05 Mtrs.	MR	
3					
_	Compartmentation. 1. Fire check door	Required	Provided	MR -	
	2. Sealing of electrical shafts	Required	Provided	MR ·	
	3. Fire Rating of shaft door	2 Hours	2 Hours	MR ^	
	4. water curtain	N/A	N/A	N/A	
	5. Fire dampers	Required	Provided	MR	
4				T	
	hasement	30 AC Change	provided	MR C	

	ISI marking	Required	Provided MR			
6	First-Aid Hose Reels.	,				
	total numbers on each floor	2 Nos.	2 Nos.	MR 1		
	Length of Hose reel hose	30 m	30 m	MR *		
	Nozzle Diameter	5 mm	5 mm	MR ′		
7	Automatic fire detection and alarming system					
	Type of detectors	Heat/Smoke	Provided	MR ′		
	location of Main Panel	Basement	Basement	MR ′		
	location of Repeater panel	N/A	N/A	N/A		
	Alternate source of power	Required	DGSet 380 & 250 KVA	MR -		
	hooter's location	Staircase	Staircase	MR		
8	MOEFA	Required	Provided	MR '		
9	Public Address System.	Required	Provided	MR -		
10	Automatic Sprinkler System.					
	basement	Required	Provided	MR -		
	upper floors	Required	Provided	MR 1		
	sprinkler above false ceiling	Required	Provided	MR /		
11	Internal Hydrants					
	Size of riser/down-corner	150 mm	150 mm	MR ′		
			0.11	MD		
	Number of Hydrants per floor	2 Nos.	2 Nos.	MR ′		
	hose Box	Required	Provided	MR ′		
12	Yard Hydrants.			ME		
	total number of hydrants	4 Nos.	4 Nos.	MR*		
	hose box	Required	Provided	MR ′		
13	T uniping arrangements					
	1. Ground level		00001514	IMD (
	a. Discharge of main Pump	2280 LPM	2280 LPM	MR		
	b.Head of main pump	80 Mtrs.	80 Mtrs.	MR /		
	c.Number of main pumps	Two	Two	MR /		
	d.jockey pump out put	180 LPM	180 LPM	MR /		
	e.jockey pump head	40 Mtrs.	40 Mtrs.	MR /		
	f. Standby Pump output	2280 LPM	2280 LPM	MR /		
	g.Stanby Pump head	80 Mtrs.	80 Mtrs.	MR /		
	h.Auto Starting/Manual stopping	Required	Provided	MR ′		
	I. pump house access	Required	Provided	MR ′		
	2.Terrace level	900 LPM	900 LPM	MR -		
	a. Discharge of pump	30 m	30 m	MR		
	b. head of the pump	Required	Provided	MR *		
	c. Power supply	Required	Provided	MR 1		
	d. Auto starting of pump	Nequiled	11001000	IVIIX		
14	Captive water storage for fire fighting					
	Underground tank capacity	1.5 Lakh Ltrs.	1.5 Lakh Ltrs.	MR -		
	a. Draw-off connection	Required	Provided	MR C		
	b. fire service inlet	Required	Provided	MR		
	c.Access to tank	Required	Provided	MR ′		
	Over head tank Capacity	20000 Ltrs.	20000 Ltrs.	MR ′		
15		Required	Provided	MR ′		
	Provision of lifts.					

Renewel

Su

Rockland Harportal Dwarks.

	b. pressurization of lift lobby	N/A	N/A	N/A
	c. communication in lift car	Required	Provided	MR -
	d. Fireman's grounding switch	Required	Provided	MR 4
	e. Lift signage	Required	Provided	MR .
17	Standby power supply	Required	Provided	MR
18	Refuge Area.			
	total area	N/A	N/A	N/A
	location	N/A	N/A	N/A
	Fire control room			
	a. Detector system Panel	Required	Provided	MR *
	b. Flow switch Panel	N/A	N/A	N/A
19	c. PA system Panel	Required	Provided	MR 1
	d. Battery backup	Required	Provided	MR *
	e. Building floor plans	Required	Provided	MR <
	o. Building the present			
20	Special Fire Protection System for Protection of special Risk if any:		Co2 Provided.	

The fire protection systems provided in the building were checked and found functional at the time of inspection. The shortcomings vide letter no. F6/DFS/MS/Hospital/2015/559 dated 19.03.2015 found rectified.

Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety required under the rules, renewal of Fire Safety Certificate issued vide letter no. F6/DFS/MS/Hospital/2011/3533 dated 15.12.2011, is recommended under Rule 37 of the Delhi Fire Service Rules, 2010.

Accordingly DFA is put up for approval and signature please.

Sanjay Kumar Tomar

Signature of the Inspecting Officer II

Name

S.P. Bhardwaj

Signature of the Inspecting Officer I

Designation Divisional Officer

Designation

ADO (Dwarka)

Name