

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**

No. F6/MS/DFS/SZ/EH/2016/ 52/597

Dated: 07/04/16

FIRE SAFETY CERTIFICATE

Certified that the Taco Bell (a unit of Burman Hospitality Pvt. Ltd.) located at Shop no-6A, Upper Ground Floor, Epicuria Complex, Nehru Place Metro Station, New Delhi-19, comprised of basement, lower ground & upper ground floors owned/occupied by a unit of Burman Hospitality Pvt. Ltd. was inspected by the officer concerned of this department on 16/03/2016 in the presence of Mr. Pandey and observed that the said restaurant have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class **Group-D, Assembly (Restaurant)** with effect from ~~07/04/16~~ for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010.

Issued ~~07/04/16~~ at New Delhi by.

(Dr. G. C. Misra)
Director
Tel: 011-23414333

Dr. G. C. Misra

Copy to:-

- (1) Dy. Health Officer, Central Zone
Jal Vihar, Lajpat Nagar
New Delhi
- (2) Mr. Kumar Saurabh
Taco Bell(a unit of Burman Hospitality Pvt. Ltd.)
Shop no-6A, Upper Ground Floor, Epicuria Complex,
Nehru Place Metro Station, New Delhi-19

Following fire safety directives must be adhered to:-

1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
3. The trained fire fighting staff should be available round the clock.
4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
5. The basement shall be used as per the provisions of NBC
6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form "J" [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building:- Taco Bell (a unit of Burman Hospitality Pvt. Ltd.) located at Shop no-6A, Upper Ground Floor, Epicuria Complex, Nehru Place Metro Station, New Delhi-19
 2. Type of occupancy:- Assembly Building, Group – D, Restaurant
 3. Type of case:- New
 4. Details of previous NOC:- Nil
 5. Fire safety directives No.- Nil
 6. Date of inspection:- 16/03/2016
 7. Name of the inspecting officer:- D.B.Mukherjee, A.D.O.(BCP)
 8. Name & designation of officer From the building side:- Mr.Pandey
 9. Year of construction:- 2012.
 10. Applicant's letter No:-.DHO/CZ/2016/2140 dated 26/02/2016
- Building is comprised of Basement, Lower Ground & Upper Ground Floor.
(Restaurant is running at upper ground floor)

Sl. No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement NBC	Provided at site	Remarks MR/NMR
1.	Access to Building			
	1) Road width	9 mtrs	Provided	MR
	2) Gate width	N/A	N/A	N/A
	3) Width of internal road	06	Provided	MR
2.	Number, Width Type & Arrangement of Exits		Provided and maintained by Mall	
	A. Number of staircases			
	1. Upper floors	N/A	N/A	N/A
	2. Basements	N/A	N/A	N/A
	B. Width of staircase			
	1. Upper floors	N/A	N/A	N/A
	2. Basements	N/A	N/A	N/A
	C. Protection of exits			
	1. Fire check door	N/A	N/A	N/A
	2. Pressurization	N/A	N/A	N/A
	D. No. of continuous staircase to terrace	N/A	N/A	N/A
	E. Width of corridor	1.50 mtrs.	Provided by mall	MR
	F. Door size	02 m	02 Nos. of EXITS-2M,1.5M	MR
3.	Compartmentation		Provided and maintained by Mall	
	1) Fire check door	Required	Provided	MR
	2) Sealing of electrical shafts	Required	Provided	MR
	3) Fire rating of shaft door	Required	Provided	MR
	4) Water curtain	N/A	N/A	N/A
	5) Fire Dampers	N/A	N/A	N/A
4.	Smoke Management System		Provided and maintained by Mall	
	1) Basements	30 a/c per hour	N/A	N/A
	2) Upper floors	12 a/c per hour	N/A	N/A
5.	Fire Extinguishers			
	1) Total numbers	ISI Marked	06 Nos.	MR
	2) Types		ABC, Co2 ,Foam	MR
	3) ISI marking		Yes	MR
6.	First-Aid Hose Reel		Provided and maintained by Mall	
	1) Total number of each floor	Required 04 no.	Provided by Mall	MR
	2) Length of hose reel hose	Required	Provided by Mall	MR
	3) Nozzle diameter	Required	Provided by Mall	MR

7.	Automatic Fire Detection & Alarming System Provided and maintained by Mall			
	1) Type of detectors	Required	Provided by Mall	MR
	2) Location of main panel	Required	Provided by Mall	MR
	3) Location of repeater panel	Required	Provided by Mall	MR
	4) Alternate source of power	Required	Provided by Mall	MR
	5) Hooter's Location	Required	Provided by Mall	MR
8.	MOEFA	Required	Provided by Mall	MR
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System			
	1) Basement	Required	Provided by Mall	MR
	2) Upper floors	Required	Provided by Mall	MR
	3) Sprinkler above false ceiling	Required	Provided by Mall	MR
11.	Internal Hydrants Provided and maintained by Mall			
	1) Size of riser/down-comer	Required	Provided by Mall	MR
	2) Number of hydrants per floor	Required	Provided by Mall	MR
	3) Hose box	Required	Provided by Mall	MR
12.	Yard Hydrants			
	1) Total number of hydrants	Required	Provided by Mall	MR
	2) Hose box	Required	Provided by Mall	MR
13.	Pumping Arrangement Provided and maintained by Mall			
	1) Ground level			
	a) Discharge of main pump	2280 lpm	Provided by Mall	MR
	b) Head of main pump	70m	Provided by Mall	MR
	c) Number of main pump	02	Provided by Mall	MR
	d) Jockey pump out put	280 & 180 lpm	Provided by Mall	MR
	e) Jockey pump head	70m	Provided by Mall	MR
	f) Stand by pump output	2850 lpm	Provided by Mall	MR
	g) Stand by pump head	70m	Provided by Mall	MR
	h) Auto starting/Manual stopping	Required	Provided by Mall	MR
	2) Terrace level			
	a) Discharge of pump	N/A	N/A	N/A
	b) Head of pump	N/A	N/A	N/A
	c) Power supply	N/A	N/A	N/A
	d) Auto starting of pump	N/A	N/A	N/A
14.	Captive Water Storage for Fire Fighting Provided and maintained by Mall			
	1) Under ground tank capacity	100KL	Provided by Mall	MR
	a) Draw-off connection	Required	Provided by Mall	MR
	b) Fire service inlet	Required	Provided by Mall	MR
	c) Access to tank	Required	Provided by Mall	MR
	d) Over head tank capacity	Required	Provided by Mall	MR
15.	Exit Signage.	Required	Provided by Mall	MR
16.	Provision of Lifts.			
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply Provided and maintained by Mall			
18.	Refuge Area			
	Total area	N/A	N/A	N/A
	location	N/A	N/A	N/A

n/3

19.	Fire Control Room	Provided and maintained by Mall		
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risk, if any:			N/A

The fire protection system provided in the restaurant were checked and found functional at the time of inspection.
The mall has issued FSC by this department vide letter no.F6/DFS/MS/2013/321 dt.:16/05/2013
In view of the substantial compliance of the minimum standards on fire prevention and fire safety measures as required under rules 35 of the Delhi Fire Service Rules 2010 it is recommended to grant fire safety certificate.
Accordingly DFA is prepared and put up for perusal, approval and signature pl.

D.B. Mukherjee
13/3/16

Signature of the inspecting officer
Name :- D.B. Mukherjee.
Designation :- Assistant Divisional Officer