GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001

Email – gargatul@hotmail.com

(Ph. 26189168),

No. F6/DFS/ ons/ Horpitul/2016/52/602

Dated: 19/04/16

## FIRE SAFETY CERTIFICATE

Dy. Chief Fire Officer Delhi Fire Service

Copy to:-

1. Dr. Anil Agarwal, Dy. Head (Admin), Institute of Liver & Biliary Sciences, Plot No. D-1, Vasant Kunj, New Delhi – 110070.

## Conditions for the validity of fire safety certificate:-

- a) All the fire safety and means of escape facilities shall be maintained in good working conditions at all time. Any lapse rendering fire safety or means of evacuation facilities rendering non-functional shall be the responsibility of the management.
- b) Building Sanctioning authority may verify any deviation with regard to the construction/occupancy in the building. In case of any deviation, the fire safety certificate stands null and void.
- c) The staffs shall be trained for operating fire fighting system and mock evacuation drills be conducted at regular intervals and record be maintained.
- d) The basement shall be used strictly as per the provisions of Building Bye Laws.
- e) The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules-2010. The form is available on www.dfs.delhigovt.nic.in.
- f) The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form "J" (Sub rule (1) of rule 37) along with a copy of this certificate, six months prior to its expiry. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>.

			INSPECTION REP	ORTS			
*	Name & address of the building		Vivarium Block, Patient Area , Lower & Upper basement, (Part of phase-II)				
	O Duildin O		Institute of Liver & Biliary Sciences, Plot No. D-1, Vasant Kunj, New Delhi-				
2	Building Comprised of		B+G+5 upper floor				
3	Type of Occupancy		Institutional				
4	Type of case		New				
	5 Details of previous NOC		No				
7	Fire safety directives letter No		F6/DFS/MS/BP/Hospital/2011/723 dated 21.04.2015				
8	Date of inspection		11.4.16				
		inspecting Officers	DY.CFO Atul Garg, DO Dharampal Bhardwaj & ADO DB Mukherjee				
9		signation of officers	Sh. Amit Gautam & official of DMRC				
10	from the build		2015				
10	Year of construction Applicant's letter No.		2015				
11	, ipplicant one	110.	F.2.48/ONM/ILBS/2013/F&S/6933/1166-78 Dated 30.03.2016				
S. NO.		andards on fire nd fire safety U/R	NBC Requirement	Provided at site	Remarks MR / NMR		
1	Access to bu						
	1) Road width	The same of the sa	9 Mtr	Provided	MR		
	2) Gate width		6 Mtr	Provided	MR		
	3) Width of in	ternal road	6 Mtr	Provided	MR		
2	Number, wid	th Type & arrangem					
	a. Number of						
	1. Upper floor	S	8 Nos.	Provided	MR		
	2. basements		13 Nos+ 2 Ramps	Provided	MR		
	b. Width of s	taircase		1 1011404			
	1. Upper floors		2 Mtr & 1.5 Mtr	2 m - 6 nos. each & 1.5m- 2 no. Provided	MR		
			2 Mtr & 1.5 Mtr	2 m- 6 nos. each & 1.59- 4 nos each . 1.5-1no, 1.42- 1 no, 1.18-1 no. mtrs+ 2	MR		
	2. basements		3	nos. Ramps Provided			
	c. Protection			: = 1			
	1. Fire check of		Required	Provided	MR		
	2. Pressurizati	on ntinuous staircase	Required	Provided	MR		
	to terrace			2 Nos.Provided	MR		
	e. Width of cor	ridor	1.5 m 1200 <u>+</u> 50 for pateint	Provided	MR		
			room & 1 mtr rest of the				
	f. Door size		building	Provided	  MR		
3	Compartment	ation.			IVIE		
	1. Fire check d		Required	Provided	MR		
	2. Sealing of el		Required	Provided	MR		
	3. Fire Rating	· · · · · · · · · · · · · · · · · · ·	Required	Provided	MR		
	4. water curtair		N/A	N/A	N/A		
	5. Fire damper		Required	Provided	MR		
4		ement system.					
	basement		30 a/c per hour 12 a/c per hour	Provided	MR		
	upper floors			Provided	MR		
5 Fire Extinguish		hers					
	total numbers			280 Nos. Provided	MR		
	Types		r		MR		
	ISI marking			Provided	MR		

		INSPECTION REPO	ORTS		
6	First-Aid Hose Reels.	-1			
	total numbers on each floor	2 Nos	Provided	MR	
	Length of Hose reel hose	30 Mtr	Provided	MR	
	Nozzle Diameter	5mm	Provided	MR	
7	Automatic fire detection and a	larming system			
	Type of detectors	Required	Provided	MR	
	location of Main Panel	Upper basement	Provided	MR	
	location of Repeater panel	Ground floor	Provided	MR	
	Alternate source of power	Required	Battery Backup Provided	MR	
	hooter's location	Required	Staircase Provided	MR	
8	MOEFA	Required	Provided	MR	
9	Public Address System.	Required	Provided	MR	
10	Automatic Sprinkler System.				
	basement	Required	Provivded	MR	
	upper floors	Required	Provided	MR	
500 SEC	sprinkler above false ceiling	Required	Provided	MR	
11	Internal Hydrants		And the Charles		
	Size of riser/down-corner	150 MM	Provided	MR	
	Number of Hydrants per floor	2 nos- Vivarium block & Basements- 18 Nos.	Provided	MR	
	hose Box	2 nos- Vivarium block & Basements- 18 Nos.	Provided	MR	
12	Yard Hydrants.		177 4 7		
	total number of hydrants	27 Nos	Provided	MR	
	house box	27 Nos.	Provided	MR	
13	Pumping arrangements	Com	mon Pump House with old blo	ck	
	1. Ground level			в	
	a. Discharge of main Pump	2850 LPM	Provided	MR	
	b.Head of main pump	95 Mtr	Provided	MR	
	c.Number of main pumps	Two	Provided	MR	
	d.jockey pump out put	180 LPM (2 Nos.)	Provided	MR	
	e.jockey pump head	95 Mtr	Provided	MR	
	f. Standby Pump output	2850 LPM	Provided	MR	
	g.Stanby Pump head	95 Mtr	Provided	MR	
	h.Auto Starting/Manual stopping	Required	Provided	MR	
	pump house access	Provided	Provided	MR	
	2.Terrace level				
	a. Discharge of pump	900 LPM	Provided	MR	
	b. head of the pump	40 Mtr	Provided	MR	
	c. Power supply	Provided	Provided	MR	
	d. Auto starting of pump	Provided	Provided	MR	
4	Captive water storage for fire fighting	Common tank with old block			
	1. Underground tank capacity	2.50,000 Ltr	Provided	MR	
	a. Draw-off connection		Provided	MR	
	b. fire service inlet		Provided	MR	
	c.Access to tank		Provided	MR	
			TOTIGOU	INIL	

-

## **INSPECTION REPORTS**

	15	Exit Signage.		Required	Provided	
	16	Provision of li	fto	rioquirea	JFTOVIded	MR
11-	10					
		a. Pressurizatio		Required	Provided	MR
		b. pressurizatio	,	Required	Provided	MR
		c. communicati	and the second second	Required	Provided	MR
		d. Fireman's gr	ounding switch	Required	Provided	MR
		e. Lift signage		Required	Provided	MR
	17	Standby powe	r supply	Required	Provided	MR
	18	Refuge Area.				1411 (
		total area		N/A	N/A	N/A
L		location		N/A	N/A	N/A
L	19	Fire control ro	om			IN/PC
		a. Detector syst	em Panel	Required	Provided	MR
		b. Flow switch F	anel	Required	Provided	MR
		c. PA system Pa	anel	Required	D 11 1	MR
		d. Batter backup	)	Required		MR
		e. Building floor		Required		MR
	20	Special Fire Pro	otection systems	Automatic suppression		MR
		for protection of	of special risks, if	system		
		any:				
_						
	1					

The fire protection systems provided in the building were checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rule it is recommended to grant of Fire Safety Certificate under rules 35 of the Delhi Fire Service Rules 2010

Accordingly DFA is put up for your approval and signature please.

Signature of the inspecting officer Atul Garg

Designation : DCFO (SZ)

Name

Signature of the inspecting officer Name Dharampal Bhardwai

Designation: Divisional Officer

Signature of the Inspecting Officer

Name

D.B. Mukherjee

Designation

ADO (BCP)