GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI- 110001

No. F6/DF8/018/Benguet/2016/M02/615 Dated: 21/04/16

FIRE SAFETY CERTIFICATE

Certified that the Pearl Grand Banquet Hall running at First & Second floor of building at Plot No.C, DDA Community Centre, Vivek Vihar, Delhi, owned/occupied by M/s Pearl Hospitality & Events Pvt.Ltd., comprised of two basement, ground plus nine upper floors was granted fire safety certificate vide letter no.F6/DFS/MS/2013/NDZ/475 dated 25/06/2013. The building was inspected by the officers concerned of this department on 12.04.2016 in the presence of Sh. Sunil (Manager) and found that the building have deemed complied with the fire prevention and fire safety requirements in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 and that the building is fit for occupancy Group "Assembly Building/Banquet" with effect from Andrew Group are very subject to conditions printed overleaf.

Issued on 21.14.14.6...... at New Delhi by

(Rajesh Panwar) Dy.Chief Fire Officer Ph. 011-23412025

To,

Pearl Grand Banquet Hall
M/s Pearl Hospitality & Events Pvt.Ltd.,
Plot No.C, DDA Community Centre, Vivek Vihar, Delhi,
Copy to:-

The Dy. Health Officer, East Delhi Municipal Corporation ,Health Department, Shahdara (South) Zone, Karkardooma, Shahdara, Delhi The sea

CONDITIONS:

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
- 5. This Fire Safety certificate can not be treated in any case for regularizations of unauthorized if any.
- 6. "The owner /occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form'J'[sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry"
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

1. Name & address of the building : Pearl Grand Banquet Han at 1 Community Centre, Vivek Vihar, Delhi. : Assembly 2. Type of Occupancy : Renewal 3. Type of Case : F.6/DFS/MS/2013/ NDZ/475 dated 25.06.13 4. Details of Previous NOC : F.6/DFS/MS/2012/77 Dated: 04.07.12. 5. Fire Safety directives No : 12.04.16 6. Date of Inspection 7. Name of the Inspecting Officer: DO Virendra Singh & ADO Suresh Singh 8. Name of the designation of Officer : Sh.Sunil (Manager) From the building side : 2009 9. Year of Construction : 01.04.16 10.Applicant's letter No Remark Provided at Site Minimum Standards on fire prevention and NBC Requirement fire safety U/R33 MR/NM Access to building MR 30 Mtrs. 12 Mtrs Road width MR 6 Mtrs. Gate width 4.5 Mtrs. MR 6 Mtrs. Width of internal road 6 Mtrs. Number, Width, Type and Arrangement of Exits 2 a. Number of Staircases MR 2 Nos. 2 Nos. Upper Floor N/A N/A N/A Basement B. Width of Staircases MR 1.5 M & 1.25 M 1.5 M Upper Floor N/A N/A N/A Basement c. Protection of exits MR Provided Required Fire check door MR Provided Required Pressurization MR 2 nos. e. No. of continuous staircases to terrace 2 nos. N/A N/A g. Width of Corridor N/A MR 1.5 M & 2 M 2.0 Mtrs. h. Door Size Compartmentation. MR 3 Provided Required Fire check door MR Sealed Required Sealing of electrical shafts N/A N/A N/A Fire rating of shaft door N/A N/A N/A Water curtain N/A N/A N/A Fire Dampers Smoke Management System. N/A 4 N/A N/A Basement N/A N/A N/A Upper floor Fire Extinguisher MR 5. 06 Nos. 04 Nos. Total numbers MR ABC & Co2 ABC & Co2 types MR ISI marked ISI marked IS marking • First-aid-Hose Reels. MR 6. 2 nos. Total numbers of each floor 2 nos. MR 30 m 30 m Length of hose reel hose MR 5 mm 5 mm Nozzle diameter Automatic fire detection and alarming system. MR 7. Provided Heat & smoke Type of detectors MR Provided N/A Location of main panel N/A N/A N/A Location of repeater panel MR Provided Battery & DG Alternate source of power Set MR Different Different Hooters's location Location Location

| N | 10 |
|---|----|
| - | |

| 8 | MOEFA | Required | Dunida | |
|-----|--|--|----------------|-------|
| 9 | Public address System. | Required | Provided | MR |
| 10 | Automatic Sprinkler System. | Required | provided | MR |
| | • basement | N/A | NI/A | D1/4 |
| | | | N/A | N/A |
| | apper 11001 | Required | provided | MR |
| 11 | sprinkler above false ceiling | Required | provided | MR |
| 11 | Internal Hydrants | | | |
| | size of riser/down-comer | 150 mm | 150 mm | MR |
| | Number of hydrants per floor | 2 nos. | 2 nos. | MR |
| 4.0 | Hose Box | 2 nos. | 2 nos. | MR |
| 12 | Yard Hydrants. | | | |
| | Total number of hydrants | N/A | 04 Nos. | MR |
| | Hose Box | N/A | 04 Nos. | MR |
| 13 | Pumping Arrangements. | | | |
| | Ground Level | N/A | Provided | MR |
| | Discharge of main Pump | N/A | 2280 LPM | MR |
| | Head of Main Pump | N/A | 88 mtrs | MR |
| | Number of main pumps | N/A | 2 nos. | MR |
| | Jockey pump out put | N/A | 450 LPM | MR |
| | Jockey pump head | N/A | 88 mtrs. | MR |
| | Standby pump out put | N/A | 2280 LPM | MR |
| × | Standby pump Head | N/A | 88 Mtrs. | MR |
| | Auto Starting / Manual stopping | N/A | Auto | MR |
| | Pump House Access | N/A | Provided | MR |
| | Terrace Level | | | ,,,,, |
| | Discharge of pump | 450 LPM | Provided | MR |
| | Head of the Pump | 88 M | Provided | MR |
| | Power supply | Required | Provided | MR |
| | Auto Starting of pump | Required | Provided | MR |
| 14 | Captive Water Storage for Fire Fighting. | | | |
| | Underground tank capacity | N/A | 2,00,000 Ltrs. | MR |
| | Draw-off connection | N/A | Provided | MR |
| | Fire service inlet | N/A | Provided | MR |
| | Access to tank | N/A | Provided | MR |
| | Overhead Tank capacity | 20,000 Ltrs. | 20,000 Ltrs. | MR |
| 15 | Exit Signage. | Required | Provided | MR |
| 16 | Provision of Lifts. | | Trovided | IVII |
| | Pressurization of Lift Shaft | Required | Provided | MR |
| | Pressurization of Lift lobby | Required | Provided | MR |
| | Communication in lift car | Required | Provided | MR |
| | Firemen's grounding switch | Required | Provided | MR |
| | Lift Signage | Required | Provided | MR |
| 17 | Standby power supply | Required | Provided | MR |
| 18 | Refuge Area. | 1 / 2 7 7 7 | | 14115 |
| | Total area | N/A | N/A | N/A |
| - | | and the second s | 1 / | |

| 19 | Fire Control Room | | | |
|----|--|-----|----------|-----|
| | Detector system panel | N/A | Provided | MR |
| | Flow switch panel | N/A | Provided | MR |
| | PA system panel | N/A | Provided | MR |
| | Batter backup | N/A | Provided | MR |
| | Building Floor Plans | N/A | Provided | MR |
| 20 | Special Fire Protection systems for protection of special Risks, if any: | N/A | N/A | N/A |

The fire protection systems provided in the building were tested checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules. The fire safety certificate issued vide letter no. :F.6/DFS/MS/2003/NDZ/475 Dated 25.06.13 renewal under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

> Ssuy 13.4, 16 Signature of the Inspecting Officer

Name:-Suresh Singh

Designation :- ADO(Shah.)

Dy CPO (NIDZ)

Dy CPO (NIDZ)

13/41