GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001

No. F6/OFS/MS/school/2016/H02/636 Dated: 26/04/16

FIRE SAFETY CERTIFICATE

Certified that the Fahan International School at Between Block B-2 & B-3, Yamuna Vihar, Delhi-110053, comprised of ground plus first floor only, owned/occupied by Fahan International School was issued FSC vide letter No-F6/DFS/MS/School/2012/2933 dated-09/08/2012. The school building was re-inspected by the officer concerned of this department on 17/03/2016 in the presence of Mr. S.H.M. Naqui, Manager of the school and found that the school building have deemed complied with the fire prevention and fire safety requirements in accordance with Circular Letter No-F16/Estate/CC/FireSafety/2011/3298 to 3398 dt-01/03/11 issued by Director of Education and found that the school building is fit for occupancy class "B" 'Educational Building' for ground plus first floor with effect from 2.6. 19.16... for a period of **three** years, subject to conditions, printed overleaf.

(Rajesh Panwar) Dy. Chief Fire Officer Ph.011-23412025

ole

To,

The Principal/Manager, Fahan International School, Between Block B-2 & B-3, Yamuna Vihar, Delhi-110053

Copy:-

The Dy. Director of Education, B–Block, Yamuna Vihar, North-East, Delhi-110053

CONDITIONS

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.
- 5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction /unauthorized use of land if any.
- The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.
- 7. The owner / occupier shall apply for renewal of this Fire Safety Certificate of the Director in Form 'J' [sub rule (1) of rule (37)] along with a copy of this Certificate, Six Months prior to its expiry.

1. Name & address of the building

: Fahan International School,

Between Block B-2 & B-3, Yamuna Vihar, (Behind Mohan Nursing Home) Delhi-110053

2. Building is comprised of

: Small basement plus Ground plus first floor (school is running on ground plus first floor)

3. Type of Occupancy

: Educational

4. Type of Case

: Renewal

5. Details of Previous NOC letter

: F6/DFS/MS/School/2012/2933 dated-09/08/2012

6. Fire Safety direction letter No

: F16/Estate/CC/FireSafety/2011/3298to3398 dt-01/03/11

of

7. Date of Inspection

: 17/03/2016

8. Name of the Inspecting officers

: ADO Vijay Bahadur

9. Name and designation of Officer

from the building side

: Mr. S.H.M Naqui (Manager)

10. Year of Construction

: 2005 & 2007

11. Applicant's letter No

: Letter No.-Nil, Dated-11/03/2016

Sr. No.	Minimum Standards on Fire	Circular	Provided at Site	Remarks				
01	Prevention and Fire Safety U/R33 Requirement MR/NMR Access to Building							
	Road width	06 mtr.	06 mtr.	MR				
	Gate width	N/A	N/A	N/A				
	Width of internal road	N/A	N/A	N/A				
02	Number, Width, Type and Arrangement of Exits							
	a. Number of Staircases							
	Upper floor	01 no.	02 nos.	MR				
	Basement	N/A	N/A	N/A				
	b. Width of Staircases							
	Upper floor	1.50 mtr.	1.50 mtr. & 0.54 mtr.	MR				
	Basement	1.50 mtr.	01 mtr. (old accepted)	MR				
	c. Protection of Exits							
	 Fire check door 	N/A	N/A	N/A				
	 Pressurization 	N/A	N/A	N/A				
	d. No. of Continuous Staircases to Terrace	01 no.	01 no.	MR				
	e. Width of Corridor	1.50 mtr.	1.67 mtr.	MR				
	f. Door Size	01 mtr.	01 mtr.	MR				
03	Compartmentation.							
	Fire check door	N/A	N/A	N/A				
	 Sealing of electrical shafts 	N/A	N/A	N/A				
	Fire rating of shaft door	N/A	N/A	N/A				
	Water curtain	N/A	N/A	N/A				
	 Fire dampers 	N/A	N/A	N/A				
04	Smoke Management System.							
	Basement	N/A	N/A	N/A				
	 Upper floor 	N/A	N/A	N/A				
05.	Fire Extinguishers							
	Total numbers	06 nos.	07 nos.	MR				
	• types	ABC /CO ₂	ABC /CO ₂	MR				
	IS marking	ISI marked	ISI marked	MR				

06	First-Aid-Hose Reels.						
	Total numbers on each floor	N/A	Provided	MR			
	 Length of hose reel hose 	N/A	Provided	MR			
with the same of t	 Nozzle diameter 	N/A	Provided	MR			
07	Automatic Fire Detection and Alarming System.						
	Type of detectors	N/A	N/A	N/A			
	 Location of main panel 	N/A	N/A	N/A			
	 Location of repeater panel 	N/A	N/A	N/A			
	Alternate source of power	N/A	N/A	N/A			
	Hooter's location	N/A	N/A	N/A			
08	MOEFA	N/A	N/A	N/A			
09	Public Address System.	N/A	N/A	N/A			
10	Automatic Sprinkler System.						
	Basement	N/A	N/A	N/A			
	 upper floor 	N/A	N/A	N/A			
	sprinkler above false ceiling	N/A	N/A	N/A			
11	Internal Hydrants						
	size of riser/down-comer	N/A	N/A	N/A			
	 Number of hydrants per floor 	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
12	Yard Hydrants.						
	Total number of hydrants	N/A	N/A	N/A			
4.0	Hose box	N/A	N/A	N/A			
13	Pumping Arrangements.						
	> Ground Level			***************************************			
	Discharge of main pump	N/A	N/A	N/A			
	Head of main pump	. N/A	N/A	N/A			
	Number of main pumps	N/A	N/A	N/A			
	Jockey pump out put	N/A	N/A	N/A			
	Jockey pump head	N/A	N/A	N/A			
	Standby pump out put	N/A	N/A	N/A			
	Standby pump head	N/A	N/A	N/A			
	Auto starting/manual stopping	N/A	N/A	N/A			
	Pump house access Terrace Level	N/A	N/A	N/A			
	Discharge of pump	N/A	225 Lpm	MD			
	Head of the pump	N/A	225 Lpm 40 M	MR			
	Power supply	N/A	Provided	MR			
	Auto starting of pump	N/A	N/A	MR MR			
14	Captive Water Storage for Fire Fighting.	1.07.5	10/4	1411			
	Underground tank capacity	N/A	N/A	N/A			
	Draw-off connection	N/A	N/A	N/A			
	Fire service inlet	N/A	N/A	N/A			
	Access to tank	N/A	N/A	N/A			
	Overhead tank capacity	N/A	2500 Ltr.	MR			
15	Exit Signage.	N/A	N/A	N/A			

16	Provision of Lifts.						
	Pressurization of lift shaft	N/A	N/A	N/A			
	E lift labbut	N/A	N/A	N/A			
	O manufaction in lift cor	N/A	N/A	N/A			
	- 1	N/A	N/A	N/A			
		N/A	N/A	N/A			
17	Lift signage Standby power supply	N/A	N/A	N/A			
18	Refuge Area.						
	Total area	N/A	N/A	N/A			
	Location	N/A	N/A	N/A			
19	Fire Control Room						
	Detector system panel	N/A	N/A	N/A			
	m Mala annual	N/A	N/A	N/A			
	DA salasa manal	N/A	N/A	N/A			
	m Harris Ismaliana	N/A	N/A	N/A			
	Battery backupBuilding floor plans	N/A	N/A	N/A			
20	Special Fire Protection Systems for Protection of Special Risks, if Any:	N/A	N/A	N/A			

The fire protection systems provided in the building were tested/checked at the time of letter No. issued FSC earlier vide The school inspection. building was F6/DFS/MS/School/2012/2933 dated-09/08/2012

Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety required under the circular-F16/Estate/CC/FireSafety/2011/3298to3398 dt-01/03/11, it is recommended to renew Fire Safety Certificate.

Signature of the Inspecting Officer Name- Vijay Bahadur

Designation- A.D.O (T.Pur)

Dyckolonited for approval please.

Dyckolonist

18 41/1