GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

E-mail:- director.dlfire@nic.in No.F.6/DFS/MS/School/2016/SZ / 7 0 (Fax: - 011-23412593
Dated: 5/6

FIRE SAFETY CERTIFICATE

Certified that the building of **Adarsh Public School**, WZ-2, Dayal Sar Road, New Delhi-110059, is comprised of Stilt, ground plus three upper floors, but School is running at ground plus one upper floor only as per school chairman. The school is owned/occupied by the school management was inspected by the officer concerned of this department on 21.4.2016 in the presence of Ms Gagan Preet (In-charge) and found that the school management have complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the school building/ premises (**Ground plus one upper floor only**) is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed as under.

DIRECTOR DELHI FIRE SERVICE

Copy to:-

 The Chairman, Adarsh Public School, WZ-2, Dayal Sar Road, New Delhi-110059.

2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 6. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

NI

Building is comprised of stilt, ground plus three upper floors. But applicant has applied for school running at ground plus one upper floor only.

(Adarsh Public School, WZ-2, Dayal Sar Road, New Delhi-110059)

INSPECTION REPORT

1. Name & address of the building: Adarsh Public School, WZ-2, Dayal Sar Road, New Delhi-110059.

2. Type of Occupancy : Educational

3. Type of Case : New
4. Details of Previous NOC : N/A
5. Fire Safety directives letter No : N/A
6. Date of inspection : 21.4.2016

7. Name of Inspecting Officer : A.D.O. Sandeep Duggal

8. Name and designation of officers

From the building side : Ms Gagan Preet (In-charge)

9. Year of Construction : 2014

S. No.	Applicant's letter No. : Nil dated Nil Minimum Standards on fire prevention and fire safety U/R 33	Dir. Of Edu. Circular dt. 01.03.2011	Provided at site	Remarks MR/NMR		
1.	Access to building					
	Road widthGate widthWidth of internal road	Accessible —	09 mtrs 2.95 mtrs (02 no.'s)	M/R ~ 		
2.	Number, Width, Type & Arrangement of Exits					
	a. Number of staircases					
	Upper Floors	01 No.	01 No.	M/R		
	Basements	N/A	N/A	No basement		
	b. Width of staircases					
	Upper Floor	150 cms	150 cms	M/R		
	Basements	N/A	N/A	No basement		
	c. Protection of exits	N/A	N/A	N/A		
	Fire check door	N/A	N/A	N/A		
	Pressurization	1 1/1 2				
	d. No. of continuous staircases to	N/A	N/A	N/A		
	terrace	150 cms	230 cms	M/R -		
	e. Width of Corridor.					
	f. Door Size	100 cms	103 cms (Double Door)	M/R		
3.	Compartmentation					
	Fire check door	N/A	N/A	N/A		
	Sealing of electrical shafts	N/A	N/A	N/A		
	Fire Rating of shaft door	N/A	N/A	N/A		
	Water Curtain	N/A	N/A	N/A		
	• Fire Dampers	N/A	N/A	N/A		
4.	Smoke Management System					
	Basements	N/A	N/A	No basement		



2/2

Building is comprised of stilt, ground plus three upper floors. But applicant has applied for school running at ground plus one upper floor only.

(Adarsh Public School, WZ-2, Dayal Sar Road, New Delhi-110059)

	Upper floors	N/A	Natural Natural	M/R =			
	• Opper Hoors	IV/A	Ventilation	IVI/ K =			
5.	Fire Extinguishers						
	 Total numbers 	10 no's	Provided	M/R			
	 Types 	ABC/CO ₂ type	Provided	M/R			
	IS marking	ISI marked	ISI marked	M/R			
6.	First-Aid Hose Reels	1					
	 Total numbers on each floor 	N/A	Provided	N/A			
	 Length of hose reel hose 	N/A	30 m	N/A			
	Nozzle diameter	N/A	5 mm	N/A			
7.	Automatic fire detection and alarming system						
	Type of detectors	N/A	N/A	N/A			
	 Location of Main Panel 	N/A	N/A	N/A			
	 Location of Repeater Panel 	N/A	N/A	N/A			
	 Alternate source of power 	N/A	N/A	N/A			
	 Hooters' Location 	N/A	N/A	N/A			
3.	MOEFA	N/A	N/A	N/A			
).	Public Address System	N/A	N/A	N/A			
10.	Automatic Sprinkler System						
•	Basement	N/A	N/A	N/A			
	Ground Floor	N/A	N/A	N/A			
	Sprinkler above false ceiling	N/A	N/A	N/A			
11.	Internal Hydrants						
	Size of riser/down-comer	N/A	N/A	N/A			
	Number of hydrants per floor	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
12.	Yard Hydrants						
	Total number of hydrants	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
13.	Pumping Arrangements						
	Ground Level						
	Discharge of main Pump	N/A	N/A	N/A			
	Head of Main pump	N/A	N/A	N/A			
7	Number of main pumps	N/A	N/A	N/A			
	Jockey Pump out put	N/A	N/A	N/A			
	Jockey pump head		,				
	Standby Pump out put	N/A	N/A	N/A			
	Standby Pump Head	N/A	N/A	N/A			
	Auto Starting/Manual Stopping	N/A	N/A	N/A			
		. N/A	N/A	N/A			



Building is comprised of stilt, ground plus three upper floors. But applicant has applied for school running at ground plus one upper floor only.

(Adarsh Public School, WZ-2, Dayal Sar Road, New Delhi-110059)

	(Adarsh Public School, WZ-2,			/
	Pump House Access	N/A	N/A	N/A
	Terrace level			
	Discharge of pump	N/A	450 LPM	N/A
	> Head of the pump	N/A	40 mtrs	N/A
	Power Supply	N/A	Provided	N/A
	➤ Auto Starting of pump	N/A	N/A	N/A
14.	Captive Water Storage for fire fighting			4
	Underground tank capacity	N/A	N/A	N/A
ν.	Draw-off connection	N/A	N/A	N/A
	➤ Fire service inlet	N/A	N/A	N/A
	Access to tank	N/A	N/A	N/A
	Overhead Tank capacity	N/A	10,000 ltrs	
	6	N/A	N/A	N/A N/A
15.	Exit Signage.	11/71	IN/A	IN/A
16.	Provision of Lifts.			(No Lift)
	Pressurization of Lift Shaft	N/A	N/A	N/A
	Pressurization of Lift lobby	N/A	N/A	N/A
	Communication In lift Car	N/A	N/A	N/A
	Fireman's Grounding Switch	N/A	N/A	N/A
	Lift Signage	N/A	N/A	N/A
17.	Standby power supply	N/A	N/A	N/A
18.	Refuge Area.			
10.	> Total Area	N/A	N/A	N/A
	> Location			
		N/A	N/A	N/A
19.	Fire Control Room			
	Detector System Panel	N/A	N/A	N/A
	Flow Switch Panel	N/A	N/A	N/A
	PA System Panel	N/A	N/A	N/A
	Battery backup	N/A	N/A	
	Building Floor Plans			N/A
		N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A

2/4

Building is comprised of stilt, ground plus three upper floors. But applicant has applied for school running at ground plus one upper floor only.

(Adarsh Public School, WZ-2, Dayal Sar Road, New Delhi-1 10059)

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Keeping in view of the above substantial compliance of the minimum standards of fire prevention and fire safety measures as required in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education it is recommended to grant Fire Safety Certificate.

Note:- As per the letter submitted by the chairman (placed at C-2), the details of building is :- Stilt (used for parking), ground plus one upper floor (for school), second & third floor (for personal use).

Signature of Inspecting Officer

Name:- Sandeep Duggal

Designation:- Asstt. Divisional Officer

Signature of Inspecting Officer

Name

Designation

Divisional Officer (South West)

DIRECTORIOP

la lignature please.