GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS : DELHI FIRE SERVICE : NEW DLEHI - 110 001

No. F.6/DFS/MS/GH/2016/ HD2/753

Dated:

1/05/16

FIRE SAFETY CERTIFICATE

Certified that the Hotel Sun Shine Palace located at 957/4, Naiwalan, Bank Street, Karol Bagh, New Delhi-110005 comprises of Basement, Ground floor + Five Upper floors, basement is vacant, Ground floor as reception and one office, first, second, third and fourth floor each having four guest rooms respectively (Total 16 guest rooms), fifth floor sealed by the owner was granted NOC by this department vide letter No.F.6/DFS/MS/GH/2013/235 dated 01-05-2013. The premises was reinspected by the officer concerned of this department on 06-05-2016 in the presence of Sh. Pawan Kumar and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub-Division A-1 Guest House for 16 guest rooms with effect from ------------2016 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010.

(Rajesh Panwar)
Dy. Chief Fire Officer
Ph:- 011-23412025

9_

Copy to:-

- 1. The Joint Commissioner of Police (Lic.), First Floor, P.S. Defence Colony, New Delhi-110049 w.r.t. letter No. 919/Joint C.P./Lic.(H) dated New Delhi 19-04-2016
- 2. Sh. Pawan Kumar Chawla (Owner), Hotel Sun Shine Palace, 957/4, Naiwalan, Bank Street, Karol Bagh, New Delhi-110005.

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all time. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

1. Name & address of the building Karol Bagh, New Delhi-110005. 2. Type of Occupancy Residential (G.H.) B+G+5 Floor total guest rooms-16 Fifth floor sealed by the owner 3. Type of Case Renewal 4. Details of Previous NOC F.6/DFS/MS/GH/2013/235 dated 01/05/2013 5. Fire Safety directives letter No N/A 6. Date of inspection 06/05/2016 7. Name of Inspecting Officer Dy. C.F.O Rajesh Panwar 8. Name and designation of officers From the building side Sh. Pawan Kumar 9. Year of Construction Before 2003 10. Applicant's letter No. 919/Joint C.P/Lic.(H) dated 19.04.2016 Minimum Standards on fire prevention S. No. NBC/BBL Provided at site Remarks and fire safety U/R 33 Requirement MR/NMR 1. Access to building Road width Accessible 12 mtr MR NA Gate width NA NA NA NA NA Width of internal road 2. Number, Width, Type & Arrangement of Exits a. Number of staircases Upper Floors One One MR, Old Case Basements One One MR, Old Case b. Width of staircases 125 cms 120 cms MR, Old Case **Upper Floor** 125 cms 130 cms MR, Old Case Basements c. Protection of exits NA NA NA Fire check door NA NA NA Pressurization d. No. of continuous staircases to One MR One terrace 1.0 Mtr 1.33 Mtr Width of Corridor MR f. Door Size 1.0 Mtr. 81 cm X 200 cm MR, Old Case Compartmentation 3. NA NA Fire check door NA Sealing of electrical shafts NA Sealed MR Fire Rating of shaft door NA NA NA Water Curtain NA NA NA Fire Dampers NA NA NA 4. Smoke Management System Basements 30 ACPH Exhaust fans are MR provided Natural MR 12 ACPH Upper floors Ventilation 5. Fire Extinguishers Total numbers 02 at each floor Provided MR Co2, WCO2 Types Provided MR IS marking ISI marked MR ISI marked 6. First-Aid Hose Reels One Total numbers on alternate floor Provided MR, Old Case 30 m Length of hose reel hose Provided MR 5 mm Nozzle diameter Provided MR

INSPEC

Hotel Sun Shine Palace, 957/4, Naiwalan, Bank Street,

7. <i>I</i>	Automatic fire detection and alarming sy					
	Type of detectors	NA	NA	NA		
	 Location of Main Panel 	NA NA	NA	NA		
	 Location of Repeater Panel 	NA	NA	NA		
	 Alternate source of power 	NA	NA	NA		
	the should be action	NA	NA	NA		
3. I	Hooters' Location MOEFA	Required	Provided	MR		
	Public Address System	Required	Provided	MR		
	Automatic Sprinkler System	required	11011404			
	Basement	Required	Provided	MR		
		NA	NA	NA		
	 Ground Floor 	NA	NA	NA		
	 Sprinkler above false ceiling 					
1.]	Internal Hydrants					
	 Size of riser/down-comer 	NA	NA	NA		
	 Number of hydrants per floor 	NA	NA	NA		
	Hose Box	NA	NA	NA		
2.	Yard Hydrants	771	37.1	NT A		
	Total number of hydrants	NA	NA	NA NA		
	• Hose Box	NA	NA	NA		
3.	Pumping Arrangements					
	Ground Level	NIA	NIA	NA		
	Discharge of main Pump	NA	NA			
	Head of Main pumpNumber of main pumps	NA	NA	NA		
	> Jockey Pump out put	NA	NA	NA		
·	Jockey pump head	NA	NA	NA		
	> Standby Pump out put	NA	NA	NA		
	Standby Pump Head	NA	NA	NA		
	Auto Starting/Manual	NA	NA	NA		
	Stopping	NA	NA	NA		
	Pump House Access					
	Terrace level	450 LPM	450 LPM	MR		
	Discharge of pump	30 M	30 M	MR		
	> Head of the pump		Provided	MR		
F.	Power SupplyAuto Starting of pump	Required		Notes appeared		
	Auto Starting or pump	NA	NA	NA		
14.	Captive Water Storage for fire fighting					
	Underground tank capacity	NA	NA	NA		
	Draw-off connection	NA	NA	. NA		
	Fire service inlet	NA	NA	NA		
	Access to tank	NA	NA	NA		
	 Overhead Tank capacity 	5000 Ltr	5000 Ltr	MR, Old Case		
		Required	Provided	MR		
15.	Exit Signage.					
16.	Provision of Lifts.			27.1		
	 Pressurization of Lift Shaft 	NA	NA	NA		
	 Pressurization of Lift lobby 	NA	NA	NA		
	Communication In lift Car	Required	Provided	MR		
	 Fireman's Grounding Switch 	Required	Provided	MR		

- \- \- \- \- \- \- \- \- \- \- \- \- \-	Exportant and the last of the			
4		D 1-1	D	MD
17.	Standby power supply	Required	Provided	MR
18.	Refuge Area.			
	> Total Area	NA	NA	NA
	> Location	NA	NA	NA
19.	Fire Control Room Detector System Panel Flow Switch Panel PA System Panel Batter backup	NA NA NA	NA NA NA	NA NA NA
		NA	NA	NA
	Building Floor Plans	NA	NA	NA
20.	Special Fire Protection System for Protection of special Risks, if any:	NA	NA	NA

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter no. F.6/DFS/MS/GH/2013/235 dated 01.05.2013 renewal under rule 35 of Delhi Fire Service Rules 2010, is recommended please.

Signature of Inspecting Of

Name:- Rajesh Panwar

Designation:- Dy. C.F.O (NDZ)

Signature of Inspecting Officer

Name

Designation

III C

AA

As approved FT letter is put up for signature pole

Lim International Control of the Con

DCFO