GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

E-mail: gargatul@hotmail.com, Tel:- 011-26189168

No. F6/DFS/MS/School/2016/ \$2 | 817

Dated: 19/05/16

FIRE SAFETY CERTIFICATE

Certified that M.C.Primary School, Boys No.1, located at Sector-5, Dr. Ambedkar Nagar, New Delhi- 110062 comprised of ground and one upper floor was granted Fire Safety Certificate by this department vide letter No. F6/DFS/MS/School/2013/107 dated 22/03/2013. The school building was re-inspected by the officer concerned of this department on 11/05/2016 in presence of Mr. Sujan Singh, School Assistant of the school and found that the said School building have deemed complied with the fire prevention and fire safety requirements in accordance with the Directorate of Education circular No. F.6/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01-03-2011 and that the school building is fit for occupancy class "Educational" with effect from the date of issue of this certificate for a period of three years, subject to compliance of the under mentioned conditions.

Issued on -- 19-1-6- at New Delhi by.

Dy. CHIEF FIRE OFFICER

Copy to: -

- 1. The Principal, M.C.Primary School Boys No.1, Sector-5, Dr. Ambedkar Nagar, New Delhi- 110062.
- 2. The Commissioner, SDMC, Civic Centre, Minto road, NewDelhi-110002.

Conditions for the Validity of Fire Safety Certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner/occupier shall submit a declaration every year in form 'K' Provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

: M.C.Primary School Boys No.1, Sector-5, Dr. Ambedkar 1. Name & address of the building

Nagar, New Delhi- 110062

: Educational 1. Type of Occupancy

: Renewal 2. Type of Case

: F6/DFS/MS/School/2013/107 dated 22/03/2013 3. Details of previous NOC

: Directorate of Education circular No. F.16/Estate/CC/Fire 4. Fire Safety directives letter No

Safety/2011/3298 to 3398 dated 01-03-2011.

: 11.05.2016 5. Date of inspection

: M.K.Chattopadhyay, ADO(M.Rd) 6. Name of the Inspecting Officers

7. Name and designation of officers

: Shri Sujan Singh, School Assistant. from the building side

: 2006 9. Year of Construction

: Nil dated 28.03.2016. 10. Applicant's letter No.

M.C.Primary School Boys No.1, Sector-5, Dr. Ambedkar Nagar, New Delhi- 110062 is comprised of ground and one upper floor.

S. No.	M	inimum Standards on fire ention and fire safety U/R 33	Directorate of Education circular	Provided at site	Remarks MR/NMR
1	Access	to building			MR
		Road width	06 mts	Provided Provided	MR
	•	Gate width	4.5 mts N/A	N/A	N/A
		Width of internal road	0.77		
2	Numbe	er, Width, Type & Arrangement o	of Exits		
		ber of staircases) (D
		Upper Floors	02 Nos.	Provided	MR N/A
			N/A	N/A	IN/A
	•	Basements			
	b. Width of staircases		1.5 mts or less &	2.0 mts each provided	MR
	•	Upper Floors	0.75 mt	N/A	N/A
		Basements	N/A	14/21	
	c. Protection of exits				
	C. F100		N/A	N/A	N/A
	•	Fire check door		N/A	N/A
	•	Pressurization	N/A	Provided (01)	MR
	e. No.	of continuous staircases to terrace	01	N/A	N/A
	o Wi	dth of Corridor	N/A	IN/A	
		or Size	1.0 mts	Provided (1.0 mt)	MR
	Compartmentation.				т п
3					
-		Fire check door	N/A	N/A	N/A
	•		NI/A	N/A	N/A
			N/A		
		Fire Rating of shaft door	N/A	N/A	N/A
		Water Curtain	N/A	N/A	N/A
			N. A. C.		STIA

	San A Cycetom		**				
4	Smoke Management System.	30 a/c per hour	N/A	N/A			
	Basements	12 a/c per hour	N/A	N/A			
	Upper floors	1 110015					
5	Fire Extinguishers	09 nos.	Provided	MR			
	 Total numbers 	ABC & CO ₂ type	Provided	MR			
	• Types	ISI marked	Provided	MR			
	IS marking	151 marro	·				
6	First-Aid Hose Reels.		N/A	N/A			
	Total numbers on each floor	30 m	N/A	N/A			
	• Length of hose reel hose	5 mm	N/A	N/A			
	Nozzle diameter		t required				
7	Automatic fire detection and alarming	N/A	N/A	N/A			
	Type of detectors			NI/A			
37	Location of Main Panel	N/A	N/A	N/A			
	 Location of Repeater Panel 	N/A	N/A	N/A			
	Alternate source of power	N/A	N/A	N/A			
	Hooters' Location	N/A	N/A	N/A			
8	MOEFA	N/A	N/A	N/A			
9	Public Address System.	N/A	N/A	N/A			
10	Automatic Sprinkler System	red	I DT/A				
10	Basement	N/A	N/A	N/A			
	Upper Floor	N/A	N/A	N/A			
	Sprinkler above false ceiling	N/A	N/A	N/A			
11	Internal Hydrants Not r						
	Size of riser/down-comer	N/A	N/A	N/A			
	Number of hydrants per floor	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
12	2 Yard Hydrants. Not required						
12	Total number of hydrants	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
13							
	Ground Level			·			
	Discharge of main Pump	N/A	N/A	N/A			
	> Head of Main pump	N/A	N/A	N/A			
	> Number of main pumps	N/A	N/A	N/A			
	> Jockey Pump out put	N/A	N/A	N/A			

	4	M	(A)		N/A	N/A	N/A	
1	1			andby Pump out put	N/A	N/A	N/A	all appear
				andby Pump Head	N/A	N/A	N/A	
			Auto Starting/ Manual stopping			N/A	N/A	1
					N/A	1772		
				ump House Access	N/A	N/A	N/A	A
		•		ace level	No. 10.3	N/A	N/A	A
				Discharge of pump Head of the pump	N/A		N/.	^
		No. Li		Power Supply	N/A	N/A	N/	
				Auto Starting of pump	N/A	N/A		
-	14	Contine Water Storage for firefighting Not required						
-	14	-		lerground tank capacity	N/A	N/A	N/	
				w-off connection	N/A	N/A		/A
				e service inlet	N/A	N/A	V	/A //A
		>		cess to tank	N/A	N/A		
18.		•	Ov	erhead Tank capacity	N/A	N/A	N	I/A
					Required	Prov	rided N	/IR
	15		Signa	The state of the s	Not Appli	cable		
	16	Prov		of Lifts.	N/A	N/A	. 1	N/A
		•		essurization of Lift Shaft	N/A	N/A	1	N/A
		•		essurization of Lift lobby	N/A	N/A	1	N/A
		•		ommunication In lift Car	Maria de la companya del companya de la companya de la companya del companya de la companya de l	N/A	W 420431	N/A
		•	Fi	reman's Grounding Switch	N/A	_	1	
		•	L	ift Signage	N/A	N/A	4	N/A
	1	7 04	11	mowor sunnly	N/A	N/A	A	N/A
	1		efuge A	power supply				
	1	o Re		Total Area	N/A	N/	A	N/A
				Location	N/A	N/	A	N/A
	-	IC IE:		ntrol Room				
		19 Fi	reco	Detector System Panel	N/A	N	/A	N/A
			-7		N/A	N	/A	N/A
			•	Flow Switch Panel	N/A	N	/A	N/A
			•	PA System Panel	N/A		[/A	N/A
			•	Batter backup		N	J/A	N/A
			•	Building Floor Plans	N/A Paguire	0	~	MD
20				Fire Protection Systems for	Required	n e	ear elect. Panel.	
				tion of special Risks, if any:				
The fire protection systems provided in the building were test checked and found functional at the								
		Th	ie fire	protection systems provide			The same of	b

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the NOC issued vide letter No. F6/DFS/MS/School/2013/107 dated 22/03/2013, renewal under the Directorate of Education circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01-03-2011 is recommended.

DFA is put up for approval & signature please

Name (M.K. CHATTOPADHYAY) Assistant Divisional Officer (MRD)

DCFO (D.P.Bhardwaj)

DCFO(SZ)