GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/2016/ 1402 / 80/

Dated : 19/5/16

FIRE SAFETY CERTIFICATE

Certified that the Surya Inn Guest House located at 7875, Arakashan Road, Pahar Gani, New Delhi comprised of Ground + 04 Upper floors, Ground floor (01 guest room + Reception + 01 office), 1st floor to 3rd floor (03 guest rooms + 01 Store room at each floor) and 4th floor (Vacant), total 10 guest rooms was granted FSC by this department vide letter No.F6/DFS/MS/GH/2013/692 dated 18/02/13. The premises was re-inspected by the officer concerned of this department on 10/05/16 in the presence of Mr. Rajive (Manager) and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

(Rajesh Panwar) Dy. Chief Fire Officer Delhi Fire Service Ph. 011-23412025

Copy to:-

- elc me 1. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi
- 2. The Manager, Surya Inn Guest House located at 7875, Arakashan Road, Pahar Ganj, New Delhi

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

INSPECTION REPORT

1. Name & address of the building Surya Inn Guest House located at 7875,

Arakashan Road, Pahar Ganj, New Delhi 2. Type of occupancy:-Residential, Sub Division-A-1

Gr. + 04 Upper floors (total 10 Guest rooms)

3. Type of case:-Renewal

4. Details of previous FSC:-F6/DFS/MS/GH/2013/692 dated 18/02/13 5. Fire safety directives No.-

N/A 6. Date of inspection:-10/05/16

7. Name of the inspecting officer:-Sh. Manoj Kumar Sharma (ADO/CC) 8. Name & designation of officer

From the building side:-Mr. Rajive (Manager)

9. Year of construction:-1990 10. Applicant's letter No:-

Nil dated 29/04/2016.

S.No.	Minimum Standards on fire	D	D :11 1 ::	Old Case			
5.110.	Prevention and fire safety U/R 33	Requirement Existing	Provided at site	Remarks MR/NMR			
1.	Access to Building						
	1) Road width	N/A	06 mtr.	MR			
	2) Gate width	N/A	N/A	N/A			
	3)Width of internal road	N/A	N/A	N/A			
2.	Number, Width Type & Arrangement of Exits						
	A. Number of staircases						
	1. Upper floors	01 Nos.	01 Nos.	MR			
	2. Basements	N/A	N/A	N/A			
	B. Width of staircase		a .				
	1. Upper floors	0.80 mtr.	1.03 to 1.10 mtr.	MR			
	2. Basements	N/A	N/A	N/A			
	C. Protection of exits						
	1. Fire check door	N/A	N/A	N/A			
	2. Pressurization	N/A	N/A	N/A			
	D. No. of continuous staircase to terrace	N/A	N/A	N/A			
	E. Width of corridor	N/A	N/A	N/A			
	F. Door size	01 mtr.	01 mtr.	MR			
3.	Compartmentation						
	1) Fire check door	N/A	N/A	N/A			
	2) Sealing of electrical shafts	N/A	N/A	N/A			
	3) Fire rating of shaft door	N/A	N/A	N/A			
	4) Water curtain	N/A	N/A	N/A			
	5) Fire Dampers	N/A	N/A	N/A			
4.	Smoke Management System						
	1) Basements	N/A	N/A	N/A			
	2) Upper floors	12 a/c per hour	Natural	MR			
5.	Fire Extinguishers						
	1) Total numbers	08 Nos.	08 Nos.	MR			
	2) Types	ABC & CO2	Provided	MR			
	3) ISI marking	Required	Provided	MR			

	First-Aid Hose Reel	NI/A	N/A	N/A	
	1) Total number of eachfloor	N/A N/A	N/A	N/A	
	2) Length of hose reel hose		N/A	N/A	
	2) M la diameter	N/A	The state of the s		
	Automatic Fire Detection &	Alarming	N/A	N/A	
7 •	1) Type of detectors	N/A	N/A N/A	N/A	
	2) Location of main panel	N/A	The second secon	N/A	
	3) Location of repeater panel	N/A	N/A	N/A	
	4) Alternate source of power	N/A	N/A	N/A	
	5) Hooter's Location	N/A	N/A	N/A	
8.	MOEFA	N/A	N/A	MR	
9.	Public Address System	Required	Provided	IVIK	
9.	Intercom	Ĭ.			
4.0	Antomotic Sprinkler System		, , , , , , , , , , , , , , , , , , , ,	NI/A	
10.	1) Basement	N/A	N/A	N/A	
	2) Upper floors	N/A	N/A	N/A	
	3) Sprinkler above false	N/A	N/A	N/A	
	apiling	112 00			
	ceiling Internal Hydrants				
11.	1) Size of riser/down-comer	N/A	N/A	N/A	
	2) Number of hydrants per	N/A	N/A	N/A	
		11122			
	floor	N/A	N/A	N/A	
	3) Hose box				
12.	Yard Hydrants	N/A	N/A	N/A	
	1) Total number of hydrants	N/A	N/A	N/A	
	2) Hose box	14/11			
13.	Pumping Arrangement	N/A	N/A	N/A	
	1) Ground level	N/A N/A	N/A	N/A	
	a) Discharge of main	N/A	13/12		
	pump	NT/A	N/A	N/A	
	b) Head of main pump	N/A	N/A	N/A	
	c) Number of main pu	mp N/A	N/A	N/A	
	d) Jockey pump out pu	at N/A	N/A	N/A	
	e) Jockey pump head	N/A	N/A N/A	N/A	
	f) Stand by pump out	put N/A		N/A	
	g) Stand by pump hea	d N/A	N/A	N/A	
	h) Auto starting/Manu	ial N/A	N/A	14/11	
	stopping				
	2) Terrace level		DT/A	N/A	
	a) Discharge of pump	N/A	N/A	N/A	
	b) Head of pump	N/A		N/A	
	c) Power supply	N/A		N/A	
	d) Auto starting of pu	imp N/A		IN/A	
14.		or Fire Fig	ghting	N/A	
	1) Under ground tank	N/A	N/A	IN/A	
	capacity			27/4	
	a) Draw-off connecti	ion N/A	N/A	N/A	
	b) Fire service inlet	N/A	N/A	N/A	
	1	N/A	N/A	N/A	
	d) Over head tank	N/A	1 1	N/A	

15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection Syste Risk, if any:	NA		

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/2013/692 dated 18/02/13 renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended.

Signature of the Inspecting Officer

Name: - M.K. Sharma Designation: - ADO (CC)

DO(CD)

July 16/5/16